EC-3702

Submitted By: Bharath Kumar K 121EC0571

Activity 1:

ORG 0000H

MOV TMOD,#20H

MOV TH1,#-6

MOV SCON,#50H

SETB TR1

AGAIN: MOV A, #"N"

ACALL TRANS

MOV A,#"I"

ACALL TRANS

MOV A,#"T"

ACALL TRANS

MOV A,#" "

ACALL TRANS


SJMP AGAIN

TRANS: MOV SBUF,A HERE:JNB TI,HERE

CLR TI

RET

END



Activity 2:

ORG 0000H

MOV A,PCON

SETB ACC.7

MOV PCON,A

MOV TMOD,#20H

MOV TH1,#-3

MOV SCON,#50H

SETB TR1

BACK: MOV A, #"b"

ACALL LOOP

MOV A,#"h"

ACALL LOOP

MOV A,#"a"

ACALL LOOP

MOV A,#"r"

ACALL LOOP

MOV A,#"a"

ACALL LOOP

MOV A,#"t"

ACALL LOOP

MOV A,#"h"

ACALL LOOP

MOV A,#" "

ACALL LOOP

SJMP BACK

LOOP: MOV SBUF,A

HERE:JNB TI, HERE

CLR TI

RET

END

UART #1

фX

th bharath bharath bharath bharath bharath bharath bharath bharath bharath bh h bharath bhar bharath bharat bharath harath bharath bharath bharath bharath bharath bharath bharath bharath bharath bharat arath bharath rath bharath bharath bharath bharath bharath bharath bharath bharath bharath bharath

Command

Activity 3:

ORG 0000H

START: MOV R7,#08H

MOV A,#7FH

ROTATE:MOV P1,A

MOV PO,A

MOV P2,A

MOV P3,A

ACALL DELAY

RL A

DJNZ R7,ROTATE

SJMP START

DELAY: MOV R2,#0FFH LOAD: MOV R1,#0FFH HERE: DJNZ R1,HERE

DJNZ R2,LOAD

RET END



