

Filled points: original full qualification. Cross: complete motion failure. Partial / NOT_RUN have no cost coordinates. n = 2 parameter conditions.