

Mechanical Interface Diagram





Robotic arm adapter

This is a arm interface example for RELMAN. The robotic arm adapter needs to reserve cable outlet holes and cooling vents.



Electrical Interface Diagram





10	485B	9	485A
8	CANFD_F	7	CANFD_H
6	TX0-	5	TX0+
4	RX0-	3	RX0+
2	VRXTX	1	GND

Note:The power supply is 12V， Maximum power 240W.