




- 1. Table of Contents (This Page)
  Created on Wed Oct 9 21:01:06 2013
- 2. component
- 3. solder
- 4. outline
- 5. signal1
- 6. plated-drill
- 7. componentmask
- 8. soldermask
- 9. topsilk
- 10. bottomsilk
- 11. toppaste
- 12. topassembly
- 13. bottomassembly
- 14. fab






























There are 8 different drill sizes used in this layout, 186 holes total

				•
Symbol	Diam. (Inc	h) Count	<u>Plated?</u>	
Y	0.012	93	YES	
+	0.028	20	YES	
*	0.035	9	YES	
۰	0.038	52	YES	
	0.060	4	YES	Title: (unknown) - Fabrication Drawing
\$	0.100	2	YES	Author: Michael McMaster
+	0.125	4	YES	Date: Wed 09 Oct 2013 11:01:07 GMT UTC
×	0.157	2	YES	



Board outline is the centerline of this path