

Cosmetic Refurbishment

Manage the cosmetic pipeline for devices that need body refinishing before they can be sold.

Step 1: Access the Cosmetic Dashboard

- Go to Quality -> Cosmetic Dashboard from the left navigation.
- The dashboard shows all devices at each stage of the cosmetic pipeline with device counts per stage.

Step 2: Understand the Cosmetic Pipeline

- The pipeline has 7 stages in order:
 - QC Check -> Cleaning -> Dry Sanding -> Masking -> Painting -> Water Sanding -> Final QC -> Ready to Sale.
- Each device moves through each stage in sequence.
- A yellow badge on each stage header shows how many devices are currently waiting there.

Step 3: Advance a Device Through Stages

- On the Cosmetic Dashboard, find the device at its current stage.
- Click 'Advance' to move it to the next stage in the pipeline.
- Each advance is logged with the operator name and timestamp.
- Continue until the device reaches Final QC, then it moves to Ready to Sale.

Step 4: Skip the Cosmetic Pipeline

- From the QC Check decision form, select 'Skip Cosmetic' instead of sending to the pipeline.
- Alternatively, click 'Go Cleaning' on the QC list to start the pipeline for that device.
- The device jumps directly to Final QC, bypassing all cosmetic stages.
- Use Skip for Grade A devices or where cosmetic work is not economically justified.

Tips & Best Practices

- * The cosmetic pipeline is mainly for Grade C devices or devices with significant body defects.
- * A full pipeline run typically takes 1 to 3 days depending on workload.
- * Plan cosmetic batches by grade to improve throughput.
- * Use the 'Go Cleaning' button on the QC Check list to start the cosmetic pipeline for a device.