
Mounting holes are located at X = 1.27, Y = 1.365 and X = 2.28, Y = 0.215 Center of FFC connector is X = 2.28

FFC CONNECTOR



20 PIN CONNECTOR (anywhere but oriented north-south)