

Note: Sequence for stepper using Steppor library is INI, IN3, IN2, IN4 = DZ, DH, D3, D5

> Stepper #steps in I FeV = 2038 Platen gear ratio: 85:15

GND -> pin 7

tep Sequence: INI OITO 1100 1001 1100