




PCIexpress e Interrupções do sistema PCI slot 2 PCI slot 2 PCI e 2.0 x16 _ 3 slot (white, at x4 link) PCI e 2.0 x16 _ 2 slot (blue, at x16 link) PCI e 2.0 x16 _ 1 slot (blue, at x16 link) PCI e 2.0 x16 _ 1 slot (blue, at x16 link)













5

Interrupções

- Uma interrupção é um sinal de um dispositivo que tipicamente resulta em uma troca de contextos, isto é, o <u>processador</u> para de fazer o que está fazendo para atender o dispositivo que pediu a interrupção.
- Esses eventos são sinalizados para o processador através de pedidos de interrupção (IRQs).

6







Chipset	Code name	Part numbers	South bridge	Release date	Processors	FSB	SMP	Memory types	Max. memory	Parity/ECC	PCI Type	Graphics	TDP
350	Tehama	82850 (MCH)	ICH2	November 2000	Pentium 4	400 MHz	No	PC800/600 RDRAM	2 GB	Yes/Yes	v2.2/33 MHz	AGP 4×	
360	Colusa	82860 (MCH)	ICH2	May 2001	Xeon	400 MHz	Yes	PC800/600 RDRAM	4 GB (w. 2 repeaters)	Yes/Yes	v2.2/33 MHz	AGP 4×	
345	Brookdale	82845 (MCH)	ICH2	January 2002	Celeron, Pentium 4	400 MHz	No	either DDR 200/266 or PC133	2 GB DDR, 3 GB SDR	Yes/Yes	v2.2/33 MHz	AGP 4×	
≣7500	Plumas	E7500 (MCH)	існз-в	Feb 2002	Xeon	400 MHz	Yes	Dual channel DDR 200/266	16 GB	Yes/Yes		PCI-X	
350E	Tehama-E	82850E (MCH)	ICH2	May 2002	Pentium 4	400/533 MHz	No	PC1066/800 RDRAM	2 GB	Yes/Yes	v2.2/33 MHz	AGP 4×	
345E	Brookdale- E	82845E (MCH)	ICH4	May 2002	Celeron, Celeron D, Pentium 4	400/533 MHz	No	DDR 200/266	2 GB	Yes/Yes	v2.2/33 MHz	AGP 4×	5.8 W
345GL	Brookdale- GL	82845GL (GMCH)	ICH4	May 2002	Celeron, Pentium 4	400 MHz	No	DDR 266, PC133	2 GB	No/No	v2.2/33 MHz	Integrated	5.1 W (SDRAI 5.8 W (DDR)
3 4 5G	Brookdale- G	82845G (GMCH)	ICH4	May 2002	Celeron, Celeron D, Pentium 4	400/533 MHz	No	DDR 266,DDR 333(unofficial), PC133	2 GB	No/No	v2.2/33 MHz	AGP 4× & Intel Extreme Graphics	(SDRAN 5.7 W

Relação: quantidade de portas (I/O) e o chipset

LGA 1150 [edit]

Chipsets supporting LGA 1150 CPUs (Haswell).

Chipset	Code Name	sSpec Number	Part numbers	Release Date	Bus Interface	Bus Speed	PCI Express lanes	PCI	SATA	USB	FDI support	TDP
Z87	Lynx Point	SR13A(C1) SR176(C2)		June 2013	DMI 2.0	4 GB/s	8 PCIe 2.0	No	6 Gbit/s, 6 Ports	Rev 3.0, 6 Ports & Rev 2.0, 8 ports	Yes	4.1 W
H87	Lynx Point	SR139(C1) SR175(C2)		June 2013	DMI 2.0	4 GB/s	8 PCIe 2.0	No	6 Gbit/s, 6 Ports	Rev 3.0, 6 Ports & Rev 2.0, 8 ports	Yes	4.1 VV
H81	Lynx Point	SR13B(C1) SR177(C2)		June 2013	DMI 2.0	4 GB/s	6 PCIe 2.0	No	6 Gbit/s, 2 Ports & 3 Gbit/s, 4 Ports	Rev 3.0, 2 Ports & Rev 2.0, 8 ports	Yes	4.1 VV
Q87	Lynx Point	SR137(C1) SR173(C2)		June 2013	DMI 2.0	4 GB/s	8 PCIe 2.0	No	6 Gbit/s, 6 Ports	Rev 3.0, 6 Ports & Rev 2.0, 8 ports	Yes	4.1 VV
Q85	Lynx Point	SR138(C1) SR174(C2)		June 2013	DMI 2.0	4 GB/s	8 PCIe 2.0	No	6 Gbit/s, 4 Ports & 3 Gbit/s, 2 Ports	Rev 3.0, 6 Ports & Rev 2.0, 8 ports	Yes	4.1 VV
B85	Lynx Point	SR13C(C1) SR178(C2)		June 2013	DMI 2.0	4 GB/s	8 PCIe 2.0	No	6 Gbit/s, 4 Ports & 3 Gbit/s, 2 Ports	Rev 3.0, 4 Ports & Rev 2.0, 8 ports	Yes	4.1 W

11

Southbridge 9xx and 3/4 Series chipsets [edit]

Main article: I/O Controller Hub

Chipset	Part Number	Parallel ATA	Serial ATA	RAID Level	USB	TDP
ICH6	82801FB	UDMA 100/66/33	SATA 1.5 Gbit/s, 4 Ports	No	Rev 2.0, 6 Ports	3.8 W
ICH6R	82801FR	UDMA 100/66/33	SATA 1.5 Gbit/s, 4 Ports	RAID0, RAID1, Matrix RAID	Rev 2.0, 6 Ports	3.8 W
ICH6-M	82801FBM	UDMA 100/66/33	SATA 1.5 Gbit/s, 2 Ports	No	Rev 2.0, 4 Ports	3.8 W
ICH7	82801GB	UDMA 100/66/33	SATA 3.0 Gbit/s, 4 Ports	No	Rev 2.0, 8 Ports	3.3 W
ICH7R	82801GR	UDMA 100/66/33	SATA 3.0 Gbit/s, 4 Ports	RAID0, RAID1, RAID5, RAID10, Matrix RAID	Rev 2.0, 8 Ports	3.3 W
ICH7DH	82801GDH	UDMA 100/66/33	SATA 3.0 Gbit/s, 4 Ports	RAID0, RAID1, Matrix RAID	Rev 2.0, 8 Ports	3.3 W
ICH7-M	82801GBM	UDMA 100/66/33	SATA 1.5 Gbit/s, 2 Ports	No	Rev 2.0, 4 Ports	3.3 W
ICH7-M DH	82801GHM	UDMA 100/66/33	SATA 3.0 Gbit/s, 4 Ports	RAID0, RAID1, Matrix RAID	Rev 2.0, 4 Ports	3.3 W
ICH8	82801HB	No	SATA 3.0 Gbit/s, 4 Ports	No	Rev 2.0, 10 Ports	3.7 W
ICH8R	82801HR	No	SATA 3.0 Gbit/s, 6 Ports	RAID0, RAID1, RAID5, RAID10, Matrix RAID	Rev 2.0, 10 Ports	3.7 W
ICH8DH	82801HH	No	SATA 3.0 Gbit/s, 6 Ports	RAID0, RAID1, RAID5, RAID10, Matrix RAID	Rev 2.0, 10 Ports	3.7 W
ICH8D0	82801HO	No	SATA 3.0 Gbit/s, 6 Ports	RAID0, RAID1, RAID5, RAID10, Matrix RAID	Rev 2.0, 10 Ports	3.7 W
ICH8M	82801HM	UDMA 100/66/33	SATA 3.0 Gbit/s, 3 Ports	No	Rev 2.0, 10 Ports	2.4 W
ICH8M-E	82801HEM	UDMA 100/66/33	SATA 3.0 Gbit/s, 3 Ports	RAID0, RAID1, Matrix RAID	Rev 2.0, 10 Ports	2.4 W
ICH9	82801IB	No	SATA 3.0 Gbit/s, 4 Ports	No	Rev 2.0, 12 Ports	4.3 W
ICH9R	82801IR	No	SATA 3.0 Gbit/s, 6 Ports	RAID0, RAID1, RAID5, RAID10, Matrix RAID	Rev 2.0, 12 Ports	4.3 W
ICH9DH	82801IH	No	SATA 3.0 Gbit/s, 6 Ports	RAID0, RAID1, RAID5, RAID10, Matrix RAID	Rev 2.0, 12 Ports	4.3 W
ICH9D0	82801IO	No	SATA 3.0 Gbit/s, 6 Ports	RAID0, RAID1, RAID5, RAID10, Matrix RAID	Rev 2.0, 12 Ports	4.3 W
ICH9M	82801IBM	No	SATA 3.0 Gbit/s, 4 Ports	No	Rev 2.0, 8 Ports	2.5 W
ICH9M-E	82801IEM	No	SATA 3.0 Gbit/s, 4 Ports	RAID0, RAID1, Matrix RAID	Rev 2.0, 8 Ports	2.5 W
ICH10	82801JB	No	SATA 3.0 Gbit/s, 6 Ports	No	Rev 2.0, 12 Ports	4.5 W

 $\textbf{Fonte:} \ \underline{\text{http://www.intel.com/content/www/us/en/chipsets/performance-chipsets/chipsets.html}} \quad 12$

Consumer Chipsets (Z87, H87, H81)

	Z87	H87	H81
Processor Support	Hasell L	GA1150	
Graphics Support	1x16 or 2x8 or 1x8+2x4	1×16 or 2×8	1×16
Intel RST12	Yes	Yes	No
Lake Tiny	Yes	No	No
Intel Smart Response Technology	Yes	Yes	No
Small Business Advantage	No	Yes	No
USB Total (USB 3.0)	14(6)	14(6)	20(2)
Total SATA (SATA 6Gb/s)	6(6)	6(6)	4(2)
PCI-E 2.0*	8	8	6
Mem/DIMMs per Channel	2/2	2/2	2/1
CPU Overclocking	Yes	No	No

#In addition to the 16 DCI-E 2 6 lanes from the CDI

Business Chipsets (Q87, Q85, B85)

	Q87	Q85	B85
Processor Support	ŀ	Haswell LGA11	.50
Intel vPro Technology	Yes	No	No
Intel Small Business Advantage	Yes	Yes	Yes
USB Total (USB 3.0)	14(6)	14(6)	12(4)
Total SATA (SATA 6Gb/s)	6(6)	6(4)	6(4)
PCI-E 2.0*	8	8	8
Identity Protection Technology	Yes	Yes	Yes
iSIPP Eligible	Yes	Yes	No

*In addition to the 16 PCI-E 3.0 lanes from the CPU

conclusão

- Tenha em mente que o chipset é apenas um dos fatores que você deve levar em consideração ao escolher uma placa-mãe. Se há uma característica específica que você precisa, como overclock da CPU, e sabendo o que cada chipset pode oferecer, já dá um ótimo ponto de partida Mas, mesmo a partir dai, você ainda tem que resolver através de um grande número de placas-mãe que usam esse chipset.
- Se você não encontrar uma placa-mãe que se adapta às suas necessidades em termos de portas traseiras ou internas, layout, ou outras funcionalidades, você deve olhar para um chipset "superior" em seu lugar.



14

- •Por exemplo: enquanto a H87 pode 'parecer' como o chipset ideal para a maioria dos casos, observe que as placas-mãe Z87 são quase sempre melhores ajustadas. Desde que o Z87 está no topo dos chipsets, os fabricantes de placa-mãe tendem a incluir portas sobre essas placas-mãe que não estejam no seu equivalente ao H87.
- •Muitas vezes, apenas um par de portas adicionais pode fazer a diferença entre uma placa-mãe que trabalha para um cliente fora de padrão ou a necessidade de usar um cartão PCI-E para obter a funcionalidade adequada. Estes cartões podem dar ao cliente a funcionalidade que ele quer, mas eles geralmente não executam tão bem como as portas 'on board' e adicionar mais pontos de falha que pode levar a instabilidade do sistema.
- Por essa razão, a recomendação é obter o máximo de funcionalidade a partir da própria placa-mãe e só usar cartões PCI-E quando absolutamente necessário.
 - Ver Video sobre o chipset Z87
 - http://www.youtube.com/watch?v=na87NkhSAnU

15

Exercício

 Apresentar uma arquitetura de MB baseada num chipset para configuração de RAID, para arquitetura 'cliente'.

16