



Invoice #: 1584

Fax: 407-788-7488

Invoice Date: 4/9/2025

Qty	Description		Price
			\$840.00
	Inspection of property including zones on nodes -5 HP booster pump by lake and electric control box need to be replaced. Pump no longer works and control box has rusted away and is in inoperable condition. -5 Hp booster pump behind first building at entrance right hand side(1385) is too loud, several residents that live nearby pump are complaining. Recommended to change pump. - We recommended calling well company such as Water Works(stickers for them found on pumps) as they installed those pumps and have necessary tools to replace pumps and high voltage electric control box		
Make all checks payable to Lizpa Landscaping, Inc.			
Thank you for your business!!		TOTAL	\$840.00