



Lizpa Landscaping, Inc.

Bill To: Oakland Village C/O
Sentry Management Inc.

Phone: 407-788-6700 ext 51209

Invoice #: 1776

Address: 2180 W. State Rd. 434
Suite 5000 Longwood, FL
32779

Fax: 407-788-7488

Service Address: Oakland Village
515 Ramsdell Ave
Altamonte Springs, FL
32714

Email: canderson@sentrymgt.com

Invoice Date: 11/20/2025

Qty	Description		Price
	Entrance by Montgomery Rd. We dug under and on sides of retaining wall to try to find a PVC connection that would feed the side not working. We also followed each PVC line lines in both sides trying to find the pipes that connected both sides together but found that when they built the retaining walls they broke the pipes and cancelled them and buried them way down there somewhere. We were there all day hand digging trying to find them which unfortunately we did not find them. The only way to have water on that side would be to have a water meter installed by the city and have a zone run with a battery powered timer or to remove the retaining walls and use a mini excavator to find the sleeve and reconnect to the existing zone.		
	Labor		\$360.00
	Labor for helper		\$280.00
	Area by Montgomery Rd and Tamarack St, exit side. Was investigating why that area did not have any working sprinklers and found that the pipe feeding area has been filled with cement by people who built retention wall. Pipe has cement blockage.		
	Labor		\$90.00
	Make all checks payable to Lizpa Landscaping, Inc.		
	Thank you for your business!!	TOTAL	\$730.00