Metric Tap &			Tap	Drill		Clearance Drill				
Clearance Drill		75% Thread for		50% Thread for						
_		Aluminum, Brass,		Steel, Stainless,		Clos	e Fit	Standa	ard Fit	
Sizes		& Plastics		& Iron						
Screw Size	Thread	Drill Size	Closest	Drill Size	Closest	Drill Size	Closest	Drill Size	Closest	
(mm)	Pitch (mm)	(mm)	American Drill	(mm)	American Drill	(mm)	American Drill	(mm)	American Drill	
M1.5	0.35	1.15	56	1.25	55	1.60	1/16	1.65	52	
M1.6	0.35	1.25	55	1.35	54	1.70	51	1.75	50	
M 1.8	0.35	1.45	53	1.55	1/16	1.90	49	2.00	5/64	
M 2	0.45	1.55	1/16	1.70	51	2.10	45	2.20		
	0.40	1.60	52	1.75	50				44	
M 2.2	0.45	1.75	50	1.90	48	2.30	3/32	2.40	41	
M 2.5	0.45	2.05	46	2.20	44	2.65	37	2.75	7/64	
M 3	0.60	2.40	41	2.60	37	3.15	1/8	3.30	30	
'	0.50	2.50	39	2.70	36					
M 3.5	0.60	2.90	32	3.10	31	3.70	27	3.85	24	
M 4	0.75	3.25	30	3.50	28	4.20	19	4.40	17	
	0.70	3.30	30	3.50	28					
M 4.5	0.75	3.75	25	4.00	22	4.75	13	5.00	9	
M 5	1.00 0.90	4.00 4.10	21 20	4.40 4.40	11/64 17	5.25	5	5.50	7/32	
M 5	0.80	4.10	19	4.40	16					
M 5.5	0.90	4.60	14	4.90	10	5.80	1	6.10	В	
	1.00	5.00	8	5.40	4	6.30	E	6.60	G	
M 6	0.75	5.25	4	5.50	7/32					
	1.00	6.00	В	6.40	E	7.40	L	7.70	N	
M 7	0.75	6.25	D	6.50	F					
M 8	1.25	6.80	Н	7.20	J	8.40	Q	8.80	S	
//\ O	1.00	7.00	J	7.40	L					
M 9	1.25	7.80	N	8.20	Р	9.50	3/8	9.90	25/64	
m >	1.00	8.00	0	8.40	21/64					
M 10	1.50	8.50	R	9.00	Т	10.50	Z	11.00	7/16	
	1.25	8.80	11/32	9.20	23/64					
	1.00	9.00	T	9.40	U	44.60	20/64	42.40		
M 11	1.50	9.50	3/8	10.00	X 27/64	11.60	29/64	12.10	15/32	
M 12	1.75 1.50	10.30 10.50	13/32	10.90 11.00	27/64 7/16	12.60	1/2	13.20	33/64	
	1.25	10.80	27/64	11.20	7/16					
	2.00	12.10	15/32	12.70	1/2					
M 14	1.50	12.50	1/2	13.00	33/64	14.75	37/64	15.50	39/64	
	1.25	12.80	1/2	13.20	33/64					
M 15	1.50	13.50	17/32	14.00	35/64	15.75	5/8	16.50	21/32	
M 16	2.00	14.00	35/64	14.75	37/64					
	1.50	14.50	37/64	15.00	19/32	16.75	21/32	17.50	11/16	
M 17	1.50	15.50	39/64	16.00	5/8	18.00	45/64	18.50	47/64	
M 18	2.50	15.50	39/64	16.50	41/64	19.00	3/4	20.00	25/32	
	2.00	16.00	5/8	16.75	21/32					
	1.50	16.50	21/32	17.00	43/64	00.00	0.5.12.2			
M 19	2.50	16.50	21/32	17.50	11/16	20.00	25/32	21.00	53/64	
,, oc	2.50	17.50	11/16	18.50	23/32	24.00	53/64	22.00	55/64	
M 20	2.00	18.00	45/64	18.50	47/64	21.00				
	1.50	18.50	47/64	19.00	3/4					





the premier source of parts and accessories for mini lathes and mini mills LittleMachineShop.com • (800) 981-9663

Tap &	ap & Clearance Drill Sizes				Tap Drill				Clearance Drill			
Screw Size	Major Diameter	Threads Per Inch	Minor Diameter	Aluminum Plas	hread for 50% Thread for m, Brass, & Steel, Stainless, astics & Iron		Close Fit		Free Fit			
				Drill Size	Dec. Eq.	Drill Size	Dec. Eq.	Drill Size	Dec. Eq.	Drill Size	Dec. Eq.	
0	.0600	80	.0447	3/64	.0469	55	.0520	52	.0635	50	.0700	
1	.0730	64	.0538	53	.0595	1/16	.0625	48	.0760	46	.0810	
		72	.0560	53	.0595	52	.0635					
2	.0860	56	.0641	50	.0700	49	.0730	43	.0890	41	.0960	
3	.0990	64	.0668	50	.0700	48	.0760	37	.1040	35	.1100	
		48 56	.0734	47	.0785	44	.0860					
4	.1120	40	.0771 .0813	45 43	.0820	43 41	.0890	32				
		48	.0864	42	.0935	40	.0980		.1160	30	.1285	
5	.125	40	.0943	38	.1015	7/64	.1094	30				
		44	.0971	37	.1040	35	.1100		.1285	29	.1360	
6	.138	32	.0997	36	.1065	32	.1160	27	.1440	25	.1495	
		40	.1073	33	.1130	31	.1200					
_		32	.1257	29	.1360	27	.1440					
8	.1640	36	.1299	29	.1360	26	.1470	18	.1695	16	.1770	
10		24	.1389	25	.1495	20	.1610	9	.1960	7	.2010	
	.1900	32	.1517	21	.1590	18	.1695					
	.2160	24	.1649	16	.1770	12	.1890	2	.2210	1	.2280	
12		28	.1722	14	.1820	10	.1935					
		32	.1777	13	.1850	9	.1960					
1/4	.2500	20	.1887	7	.2010	7/32	.2188	F	.2570	Н	.2660	
		28	.2062	3	.2130	1	.2280					
		32	.2117	7/32	.2188	1	.2280					
5/16	.3125	18	.2443	F	.2570	J	.2770	Р	.3230	Q	.3320	
		24	.2614	I	.2720	9/32	.2812					
		32	.2742	9/32	.2812	L	.2900					
3/8	.3750	16	.2983	5/16	.3125	Q	.3320	w	.3860	х	.3970	
		24	.3239	Q	.3320	S	.3480					
		32	.3367	11/32	.3438	T	.3580					
7/16	.4375	14	.3499	U	.3680	25/64	.3906	29/64	.4531	15/32	.4687	
		20	.3762	25/64	.3906	13/32	.4062					
		28	.3937	Y	.4040	Z	.4130					
1/2	.5000	13 20	.4056 .4387	27/64 29/64	.4219 .4531	29/64 15/32	.4531	33/64	.5156	17/32	.5312	
		28	.4562	15/32	.4688	15/32	.4688 .4688					
		12	.4603	31/64	.4844	33/64	.5156					
9/16	.5625	18	.4943	33/64	.5156	17/32	.5312	37/64	.5781	19/32	.5938	
		24	.5114	33/64	.5156	17/32	.5312					
		11	.5135	17/32	.5312	9/16	.5625					
5/8	.6250	18	.5568	37/64	.5781	19/32	.5938	41/64	.6406	21/32	.6562	
		24	.5739	37/64	.5781	19/32	.5938	11704				
11/16	.6875	24	.6364	41/64	.6406	21/32	.6562	45/64	.7031	23/32	.6562	
	.7500	10	.6273	21/32	.6562	11/16	.6875	49/64	.7656	25/32	.7812	
3/4		16	.6733	11/16	.6875	45/64	.7031					
		20	.6887	45/64	.7031	23/32	.7188					
13/16	.8125	20	.7512	49/64	.7656	25/32	.7812	53/64	.8281	27/32	.8438	
7/8	.8750	9	.7387	49/64	.7656	51/64	.7969	57/64	.8906	29/32	.9062	
		14	.7874	13/16	.8125	53/64	.8281					
		20	.8137	53/64	.8281	27/32	.8438					
15/16	.9375	20	.8762	57/64	.8906	29/32	.9062	61/64	.9531	31/32	.9688	
1	1.000	8	.8466	7/8	.8750	59/64	.9219	1-1/64	1.0156	1-1/32	1.0313	
		12	.8978	15/16	.9375	61/64	.9531					
		20	.9387	61/64	.9531	31/32	.9688					