BVS Village Amenity List as on 31 Jan 2024

Title	Description	Owner	Sta tus	LastUpdated
Tree/shrub by roundabout	The tree/shrub opposite Summerpool House on the A281 by the	TBD	BVS to determine	14/02/2024
leaning	roundabout is leaning.		ownership	
Parish Council Notice Board	The Parish Council Notice Board on the High Street badly	BPC	TBD	14/021/2024
badly damaged	damaged.			
1977 Silver Jubilee Sign	The 1977 Silver Jubilee sign that was in the grassed area in front of Blunden Court has deteriorated badly and needs restoration.	BPC	Restoration underway by Guildford signs	22/01/2024
Steps from Snowdenham Lane to Mill Pond	The steps at the top of Snowdenham Lane that lead down to the Mill Pond and Mill Lane have become dangerous.	Surrey County Council	Issue reported to SCC Rights of Way and Access Management System	22/01/2024
Village Hall downpipe 'blocked'	The downpipe by the Village Hall entrance is 'blocked' causing flooding in the entrace when raining and damagong the wall.	BPC	TBD	14/01/2024
Flagpole in the Library car park leaning.	One of the flagpoles in the Library car park is leaning	BPC	BVS/BPC investigating	14/01/2024
Village Notice Board on High Street leaning	Village Notice Board on High Street to left of library car park is leaning	BPC	TBD	14/01/2024
Railway sleepers in library car park	Some of the railway sleepers in library car park used to mark the 'end' of the parking slots have deteriorated badly.	TBD	tbd	14/01/2024
Footpath sign moissing	The sign for the footpath from the A281 opposite the Bed Centre leading to Ricado Court is missing.	TBD	BVS to investigate owner	14/01/2024
Fumes on Bramley High Street	For over a year there has been a smell of petrol in the High Street., and contamination of the stream. The problem is affecting some businesses. It has now been confirmed that the Petrol station is responsible and the the EA are investigating with a view to prosecution.	Waverley BC, Environment Agency	Waverley BC and EA Investigation ongoing	05/01/2024
Barrier between car park	One of the posts of the barrier separating the car park from the	TBD	TBD	04/01/2024
and library footpath broken	footpath between the A281 and the Library has broken.			
Water 'hydrant' sign in Library Car Park	The water 'hydrant' sign in Library Car Park has fallen over.	TBD	TBD	01/01/2024
Broken Fingerpost	The fingerpost on Snowdenham Lane at the Iron Lane junction is broken.	TBD	BVS to determine owner	19/06/2023

Improve area around	Resident has asked if the area around the Station could be	BVS	Issue reported to	04/05/2023
Station	improved by removal of debris and some planting		BVS	, , , , , , ,
Bargate Stone Wall	We have been asked if it is possible to prevent Bargate stone	BVS	Issue reported to	04/05/2023
conservation	walls in the conservation area being removed for parking		BVS	
Flag Poles in front of library	The Flag Poles in grassed area in front of the Library Car Park	BPC	Flagpoles now	29/04/2023
	need cleaning and/or maintenance.		restrung in time for	
	Rope on one pole has now snapped.		Coronation	
Statue in Roberson's	Statue in need of maintenance. It has been repainted, but	BPC	BVS to check status	02/04/2023
Garden	needs some restoration.		with BPC.	
Rhens Place Wall	The wall by the Wine Press in Rhens Place has collapsed.	Residents of Old	BVS to check	02/04/2023
		Rectory Close	current status	
Chestnut Way Notice Board	The Parish Council notice board at the end of Chestnut Way	BPC	BVS to check with	02/04/2023
	disappeared a year or two ago.		BPC	
Village Hall Turning Circle	The turning Circle by the Village Hall has deteriorated badly and	BPC	Reported to BPC	26/03/2023
	needs resurfacing.			
Shield on Village Hall	The shield at the entrance to the Village Hall is badly weathered	BPC	BPC are aware	01/03/2023
entrance	and needs repainting.			
Station Shelter Damage	Vandals have damaged the Railway Station Shelter	BPC	Damage repaired	01/03/2023
Bench in Rhens Place	Bench slats are badly weathered.	Rhens Twinning	Bench has been	12/08/2022
		Association	refurbished	
Alley between Hall and	The alley has several areas where tree roots have raised and	TBD	BVS to determine	01/08/2022
Windrush Close	broken the surface making it unsafe, especially at night when it		owner	
	is unlit.			
Benches in Roberson's	The slats of both benches in the Roberson's Garden have been	TBD	BVS to determine	01/08/2022
Garden	badly weathered and need sanding and re-oiling/painting.		owner	
Planting in the Pound	Issue reported at BVS Committee meeting.	TBD	To be investigated	30/07/2022
Village Map by the Station	Issue reported at BVS Committee meeting.	TBD	To be investigated	30/07/2022
Village Map in Front of	The Village Map on the grass in front of the Library Car Park is	BPC	BVS to check status	30/07/2022
Library	looking shabby.		with BPC	
	Perspex needs cleaning and/or replacing and the wooden frame			
	needs attention			
Snowdenham Lane -	Over recent years a number of people have taken to parking	Surrey Count	To be determined	29/07/2022
J. J. J. G. H. Lanc	otal reserve fears a manner of people mate taken to parking	Janey Count	.o se determined	25,5,72022
Dangerous Parking		Council		
Dangerous Parking	their cars on the bend on Snowdenham Lane which severely restricts visibility and is potentially dangerous.	Council		