




Recommended orientation – Fingers without Pads





Note: This orientation is for the clean joint, but makes the top side bumpy





Note: For Avoiding supports inside the actuator space








Note: Actuator link orientation is for structural strength and to not get support inside for the smooth connection

Recommended orientation – Fingers with Pads


Only change is the last finger part






The TPE pad



Recommended orientation – Palm





Note: There is additional part that needs to be separated with slicer, in Creality slicer it is Split to Objects



Recommended orientation – Thumb without Pads



Note: There will be some defect on the bottom side cause of the supports, I never printed this version I only used the version with pads



Recommended orientation – Thumb with Pads

