1	7	3	4	5	6
1	2		4	3	°
A					A
					_
В					В
c					ار
<b> </b>					ا
			USB and power connectio	ns not show.	
			and power connection	when	
			by Brant Saidal		
			M-4 1 0 11		
			by Brent Seidel  Modest Consulting  Sheet: / File: Arduino—Sensors.sch		
			Sheet: /		_
D			File: Arduino-Sensors.sch		Ιp
			Title: RS-485 Network (	Components	
			TICE. R3-405 NELWORK	Components	
			Size: A4 Date: KiCad E.D.A. kicad 4.0.3-		Rev:
			KiCad E.D.A. kicad 4.0.3-	stable	ld: 1/4
1	2	3	4	5	1 6





