```
0010 REM THIS PROGRAM PRINTS THE CUSTOMIZATTION PARAMETERS CALLED "MRCUSTPR"
0020 DIM I$(30)16,B$(64)64
0030 DATA LOAD DC OPEN T "MRPARAMS"
0040 DATA LOAD DC #0,B$,A1$,J$(),H$(),I$(),H()
0050 DATA SAVE DC CLOSE #0
0060 IF H(1)=1 THEN I$(1)="D"
   : ELSE I$(1)="W"
0070 FOR J=2 TO 23
0080 IF H(J)=0 THEN I$(J)="N"
   : ELSE I$(J)="Y"
0090 NEXT J
0100 IF H(27)=0 THEN I$(24)="N"
   : ELSE I$(24)="Y"
0110 CONVERT H$(13) TO A
0120 CONVERT H$(14) TO B
0130 B$(1)="FACTORY NAME ON REPORT"
0140 B$(2)="GREGORIAN DATE CROP STARTED"
0150 B$(3)="LOST TIME CATEGORY NO. 1"
0160 B$(4)="LOST TIME CATEGORY NO. 2"
0170 B$(5)="LOST TIME CATEGORY NO. 3"
0180 B$(6)="LOST TIME CATEGORY NO. 4"
0190 B$(7)="LOST TIME CATEGORY NO. 5"
0200 B$(8)="LOST TIME CATEGORY NO. 6"
0210 B$(9)="LOST TIME CATEGORY NO. 7"
0220 B$(10)="LOST TIME CATEGORY NO. 8"
0230 B$(11)="LOST TIME CATEGORY NO. 9"
0240 B$(12)="LOST TIME CATEGORY NO. 10"
0250 PRINT HEX(0A)
0260 B$(13)="MATERIALS AND SUPPLIES CATEGORY NO. 1"
0270 B$(14)="MATERIALS AND SUPPLIES CATEGORY NO. 2"
0280 B$(15)="MATERIALS AND SUPPLIES CATEGORY NO. 3"
0290 B$(16)="MATERIALS AND SUPPLIES CATEGORY NO. 4"
0300 B$(17)="MATERIALS AND SUPPLIES CATEGORY NO. 5"
0310 B$(18)="MATERIALS AND SUPPLIES CATEGORY NO. 6"
0320 B$(19)="MATERIALS AND SUPPLIES CATEGORY NO. 7"
0330 B$(20)="MATERIALS AND SUPPLIES CATEGORY NO. 8"
0340 B$(21)="MATERIALS AND SUPPLIES CATEGORY NO. 9"
0350 B$(22)="MATERIALS AND SUPPLIES CATEGORY NO. 10"
0360 B$(23)="MATERIALS AND SUPPLIES CATEGORY NO. 11"
0370 B$(24)="MATERIALS AND SUPPLIES CATEGORY NO. 12"
0380 B$(25)="TOTAL ROLL SURFACE OF ALL MILL ROLLS"
0390 B$(26)="BRIX DESIRED FOR REPORTING FINAL MOLASSES M&E/TON CANE"
0400 B$(27)="WILL ANALYSES BE AVERAGED BY CROP DAY (D) OR CANE WEIGHTING (W)"
0410 B$(28)="WILL CRUSHER JUICE GLUCOSE BE REPORTED (Y OR N)"
0420 B$(29)="WILL CRUSHER JUICE pH BE REPORTED (Y OR N)"
0430 B$(30)="WILL MIXED JUICE GLUCOSE BE REPORTED (Y OR N)"
0440 B$(31)="WILL MIXED JUICE pH BE REPORTED (Y OR N)"
0450 B$(32)="WILL CLARIFIED JUICE GLUCOSE BE REPORTED (Y OR N)"
0460 B$(33)="WILL CLARIFIED JUICE pH BE REPORTED (Y OR N)"
0470 B$(34)="WILL SYRUP GLUCOSE BE REPORTED (Y OR N)"
0480 B$(35)="WILL SYRUP pH BE REPORTED (Y OR N)"
0490 B$(36)="WILL SUGAR MADE STARCH BE REPORTED (Y OR N)"
0500 B$(37)="WILL SUGAR MADE DEXTRAN BE REPORTED (Y OR N)"
0510 B$(38)="WILL FINAL MOLASSES MADE GLUCOSE BE REPORTED (Y OR N)"
0520 B$(39)="WILL FINAL MOLASSES MADE ASH BE REPORTED (Y OR N)"
0530 B$(40)="WILL FINAL MOLASSES MADE CLERGET BE REPORTED (Y OR N)"
0540 B$(41)="WILL FINAL MOLASSES SHIPPED GLUCOSE BE REPORTED (Y OR N)"
0550 B$(42)="WILL FINAL MOLASSES SHIPPED ASH BE REPORTED (Y OR N)"
0560 B$(43)="WILL FINAL MOLASSES SHIPPED CLERGET BE REPORTED (Y OR N)"
0570 B$(44)="WILL FILTRATE JUICE BRIX AND POL BE REPORTED (Y OR N)"
0580 B$(45)="WILL TOP-OFF A STRIKES BRIX AND POL BE REPORTED (Y OR N)"
```

```
0590 B$(46)="WILL EITHER B MAGMA OR C CYCLONES BE REPORTED (Y OR N)"
0600 B$(47)="WILL FILTER CAKE MOISTURES BE REPORTED (Y OR N)"
0610 B$(48)="WILL B MAGMA (Y) OR C CYCLONE (N) ANALYSES BE REPORTED"
0620 B$(49)="DOES REPORT PRINTER HAVE EXPANDED PRINT CAPABILITY (Y OR N)"
0630 B$(50)="WILL METERED IMBIBITION WATER BE REPORTED (Y OR N)"
0640 B$(51)="JULIAN DATE CROP STARTED"
0650 %############################################################    ####################
0660 %############################################################    ##########################################################
######
0670 SELECT PRINT 215(132)
0672 IF H(36)=0 THEN 680
0674 SELECT PRINT 204(132)
0680 PRINT TAB(35);"CUSTOM PARAMETERS"
0690 PRINT HEX(0A0A)
0700 PRINTUSING 660,B$(1),B$
0710 PRINTUSING 650,B$(2),A1$
0720 PRINT HEX(0A0A)
0730 PRINT "LOST TIME CATEGORIES"
0740 PRINT "--------------------"
0750 PRINT HEX(0A)
0760 FOR J=1 TO 10
0770 PRINTUSING 650,B$(J+2),J$(J)
0780 NEXT J
0790 PRINT HEX(0A0A)
0800 PRINT "MATERIALS AND SUPPLIES CATEGORIES"
0810 PRINT "---------------------------------"
0820 PRINT HEX(0A)
0830 FOR J=1 TO 12
0840 PRINTUSING 650,B$(J+12),H$(J)
0850 NEXT J
0860 PRINT HEX(0A0A)
0870 FOR J=1 TO 2
0880 PRINTUSING 650,B$(J+24),H$(J+12)
0890 NEXT J
0900 PRINT HEX(0C)
0910 PRINT "SUPPRESSION OF DATA INPUT FOR ITEMS NOT REPORTED"
0920 PRINT "------------------------------------------------"
0930 PRINT HEX(0A)
0940 FOR J=1 TO 24
0950 PRINTUSING 650,B$(J+26),I$(J)
0960 NEXT J
0961 PRINT HEX(0A0A)
0962 PRINT "PRINTER AND DATA DISK SELECTIONS"
0963 PRINT "--------------------------------"
0964 PRINT HEX(0A)
0968 PRINT "PRINTER SELECTED (0 = SYSTEM, 1 = TERMINAL) IS NO. ";H(36)
0969 PRINT "DATA DISK SELECTED (0=SAME AS PROGRAM,1=310,2=D11,3=D12,4=D13,5=D14,6=D20,7=D21,8=D22,9=D23,10=D24,11=D25) IS NO. ";H(37
)
0970 PRINT HEX(0C)
0980 LOAD T "MRSTART" 10
```