```
0010  REM THIS PROGRAM READS IN THE DAILY REPORT DATA REQUIRED (CALLED "MRDATACO")
0020 DIM X(258)
0030 REM LOADING IN DATA FOR PREVIOUS DAY
0040 CONVERT H(26)-1 TO A$,(###)
0050 DATA LOAD DC OPEN T#H(37),A$
0060 DATA LOAD DC #H(37),A1$,X(),B1$()
0070 DATA SAVE DC CLOSE #H(37)
0080 FOR J=1 TO 258
0090 A(J,3)=X(J)
0100 NEXT J
0110 B1$(1),B1$(2),B1$(3),B1$(4),B1$(5),B1$(6)=" "
0120 REM LOADING IN DATA FOR DAY TO BE CORRECTED
0130 CONVERT H(26) TO A$,(###)
0140 DATA LOAD DC OPEN T#H(37),A$
0150 DATA LOAD DC #H(37),A1$,X(),B1$()
0160 DATA SAVE DC CLOSE #H(37)
0170 FOR J=1 TO 258
0180 A(J,1)=X(J)
0190 NEXT J
0200 PRINT HEX(03)
0210 SELECT PRINT 005(80)
0220 PRINT "DATA CORRECTION ROUTINE"
0230 PRINT "FOR CROP DAY ";A(1,1)
0240 PRINT "REPORT FOR DAY ";A1$
0250 PRINT HEX(0A0A)
0260 PRINT "  2   LBS TRS PURCHASED ";A(2,1)
0270  INPUT "  2   LBS TRS PURCHASED",A(2,1)
0280 PRINT HEX(0A)
0290  PRINT J$(1)
0300 PRINT "  3   HOURS LOST ";A(3,1)
0310  INPUT "  3   HOURS LOST",A(3,1)
0320 PRINT HEX(0A)
0330  PRINT J$(2)
0340 PRINT "  4   HOURS LOST ";A(4,1)
0350  INPUT "  4   HOURS LOST",A(4,1)
0360 PRINT HEX(0A)
0370  PRINT J$(3)
0380 PRINT "  5   HOURS LOST ";A(5,1)
0390  INPUT "  5   HOURS LOST",A(5,1)
0400 PRINT HEX(0A)
0410  PRINT J$(4)
0420 PRINT "  6   HOURS LOST ";A(6,1)
0430  INPUT "  6   HOURS LOST",A(6,1)
0440 PRINT HEX(0A)
0450  PRINT J$(5)
0460 PRINT "  7   HOURS LOST ";A(7,1)
0470  INPUT "  7   HOURS LOST",A(7,1)
0480 PRINT HEX(0A)
0490  PRINT J$(6)
0500 PRINT "  8   HOURS LOST ";A(8,1)
0510  INPUT "  8   HOURS LOST",A(8,1)
0520 PRINT HEX(0A)
0530  PRINT J$(7)
0540 PRINT "  9   HOURS LOST ";A(9,1)
0550  INPUT "  9   HOURS LOST",A(9,1)
0560 PRINT HEX(0A)
0570  PRINT J$(8)
0580 PRINT " 10   HOURS LOST ";A(10,1)
0590  INPUT " 10   HOURS LOST",A(10,1)
0600 PRINT HEX(0A)
0610  PRINT J$(9)
```

```
0620 PRINT " 11   HOURS LOST ";A(11,1)
0630  INPUT " 11   HOURS LOST",A(11,1)
0640 PRINT HEX(0A)
0650  PRINT J$(10)
0660 PRINT " 12   HOURS LOST ";A(12,1)
0670  INPUT " 12   HOURS LOST",A(12,1)
0680 PRINT HEX(0A)
0690 PRINT " 13   TOTAL HOURS AVAILABLE FOR GRINDING TODAY ";A(13,1)
0700  INPUT " 13   TOTAL HOURS AVAILABLE FOR GRINDING TODAY",A(13,1)
0710 PRINT HEX(0A)
0720  PRINT H$(1)
0730 PRINT " 14   QUANTITY USED ";A(14,1)
0740  INPUT " 14   QUANTITY USED",A(14,1)
0750 PRINT HEX(0A)
0760  PRINT H$(2)
0770 PRINT " 15   QUANTITY USED ";A(15,1)
0780  INPUT " 15   QUANTITY USED",A(15,1)
0790 PRINT HEX(0A)
0800  PRINT H$(3)
0810 PRINT " 16   QUANTITY USED ";A(16,1)
0820  INPUT " 16   QUANTITY USED",A(16,1)
0830 PRINT HEX(0A)
0840  PRINT H$(4)
0850 PRINT " 17   QUANTITY USED ";A(17,1)
0860  INPUT " 17   QUANTITY USED",A(17,1)
0870 PRINT HEX(0A)
0880  PRINT H$(5)
0890 PRINT " 18   QUANTITY USED ";A(18,1)
0900  INPUT " 18   QUANTITY USED",A(18,1)
0910 PRINT HEX(0A)
0920  PRINT H$(6)
0930 PRINT " 19   QUANTITY USED ";A(19,1)
0940  INPUT " 19   QUANTITY USED",A(19,1)
0950 PRINT HEX(0A)
0960  PRINT H$(7)
0970 PRINT " 20   QUANTITY USED ";A(20,1)
0980  INPUT " 20   QUANTITY USED",A(20,1)
0990 PRINT HEX(0A)
1000  PRINT H$(8)
1010 PRINT " 21   QUANTITY USED ";A(21,1)
1020  INPUT " 21   QUANTITY USED",A(21,1)
1030 PRINT HEX(0A)
1040  PRINT H$(9)
1050 PRINT " 22   QUANTITY USED ";A(22,1)
1060  INPUT " 22   QUANTITY USED",A(22,1)
1070 PRINT HEX(0A)
1080  PRINT H$(10)
1090 PRINT " 23   QUANTITY USED ";A(23,1)
1100  INPUT " 23   QUANTITY USED",A(23,1)
1110 PRINT HEX(0A)
1120  PRINT H$(11)
1130 PRINT " 24   QUANTITY USED ";A(24,1)
1140  INPUT " 24   QUANTITY USED",A(24,1)
1150 PRINT HEX(0A)
1160  PRINT H$(12)
1170 PRINT " 25   QUANTITY USED ";A(25,1)
1180  INPUT " 25   QUANTITY USED",A(25,1)
1190 PRINT HEX(0A)
1200 PRINT " 26   CRUSHER JUICE BRIX ";A(26,1)
1210  INPUT " 26   CRUSHER JUICE BRIX",A(26,1)
1220 PRINT HEX(0A)
```

```
1230 PRINT " 27   CRUSHER JUICE POL ";A(27,1)
1240  INPUT " 27   CRUSHER JUICE POL",A(27,1)
1250 PRINT HEX(0A)
1260  IF H(2)=0 THEN 1300
1270 PRINT " 28   CRUSHER JUICE GLUCOSE ";A(28,1)
1280  INPUT " 28   CRUSHER JUICE GLUCOSE",A(28,1)
1290 PRINT HEX(0A)
1300  IF H(3)=0 THEN 1340
1310 PRINT " 29   CRUSHER JUICE pH ";A(29,1)
1320  INPUT " 29   CRUSHER JUICE pH",A(29,1)
1330 PRINT HEX(0A)
1340 PRINT " 30   MIXED JUICE BRIX ";A(30,1)
1350  INPUT " 30   MIXED JUICE BRIX",A(30,1)
1360 PRINT HEX(0A)
1370 PRINT " 31   MIXED JUICE POL ";A(31,1)
1380  INPUT " 31   MIXED JUICE POL",A(31,1)
1390 PRINT HEX(0A)
1400  IF H(4)=0 THEN 1440
1410 PRINT " 32   MIXED JUICE GLUCOSE ";A(32,1)
1420  INPUT " 32   MIXED JUICE GLUCOSE",A(32,1)
1430 PRINT HEX(0A)
1440  IF H(5)=0 THEN 1480
1450 PRINT " 33   MIXED JUICE pH ";A(33,1)
1460  INPUT " 33   MIXED JUICE pH",A(33,1)
1470 PRINT HEX(0A)
1480 PRINT " 34   LAST ROLL JUICE BRIX ";A(34,1)
1490  INPUT " 34   LAST ROLL JUICE BRIX",A(34,1)
1500 PRINT HEX(0A)
1510 PRINT " 35   LAST ROLL JUICE POL ";A(35,1)
1520  INPUT " 35   LAST ROLL JUICE POL",A(35,1)
1530 PRINT HEX(0A)
1540 PRINT " 36   CLARIFIED JUICE BRIX ";A(36,1)
1550  INPUT " 36   CLARIFIED JUICE BRIX",A(36,1)
1560 PRINT HEX(0A)
1570 PRINT " 37   CLARIFIED JUICE POL ";A(37,1)
1580  INPUT " 37   CLARIFIED JUICE POL",A(37,1)
1590 PRINT HEX(0A)
1600  IF H(6)=0 THEN 1640
1610 PRINT " 38   CLARIFIED JUICE GLUCOSE ";A(38,1)
1620  INPUT " 38   CLARIFIED JUICE GLUCOSE",A(38,1)
1630 PRINT HEX(0A)
1640  IF H(7)=0 THEN 1680
1650 PRINT " 39   CLARIFIED JUICE pH ";A(39,1)
1660  INPUT " 39   CLARIFIED JUICE pH",A(39,1)
1670 PRINT HEX(0A)
1680  IF H(18)=0 THEN 1750
1690 PRINT " 40   FILTRATE JUICE BRIX ";A(40,1)
1700  INPUT " 40   FILTRATE JUICE BRIX",A(40,1)
1710 PRINT HEX(0A)
1720 PRINT " 41   FILTRATE JUICE POL ";A(41,1)
1730  INPUT " 41   FILTRATE JUICE POL",A(41,1)
1740 PRINT HEX(0A)
1750 PRINT " 42   SYRUP BRIX ";A(42,1)
1760  INPUT " 42   SYRUP BRIX",A(42,1)
1770 PRINT HEX(0A)
1780 PRINT " 43   SYRUP POL ";A(43,1)
1790  INPUT " 43   SYRUP POL",A(43,1)
1800 PRINT HEX(0A)
1810  IF H(8)=0 THEN 1850
1820 PRINT " 44   SYRUP GLUCOSE ";A(44,1)
1830  INPUT " 44   SYRUP GLUCOSE",A(44,1)
```

```
1840 PRINT HEX(0A)
1850  IF H(9)=0 THEN 1890
1860 PRINT " 45   SYRUP pH ";A(45,1)
1870  INPUT " 45   SYRUP pH",A(45,1)
1880 PRINT HEX(0A)
1890 PRINT " 46   A MASSECUITE BRIX ";A(46,1)
1900  INPUT " 46   A MASSECUITE BRIX",A(46,1)
1910 PRINT HEX(0A)
1920 PRINT " 47   A MASSECUITE POL ";A(47,1)
1930  INPUT " 47   A MASSECUITE POL",A(47,1)
1940 PRINT HEX(0A)
1950  IF H(19)=0 THEN 2020
1960 PRINT " 48   TOP-OFF A MASSECUITE BRIX ";A(48,1)
1970  INPUT " 48   TOP-OFF A MASSECUITE BRIX",A(48,1)
1980 PRINT HEX(0A)
1990 PRINT " 49   TOP-OFF A MASSECUITE POL ";A(49,1)
2000  INPUT " 49   TOP-OFF A MASSECUITE POL",A(49,1)
2010 PRINT HEX(0A)
2020 PRINT " 50   B MASSECUITE BRIX ";A(50,1)
2030  INPUT " 50   B MASSECUITE BRIX",A(50,1)
2040 PRINT HEX(0A)
2050 PRINT " 51   B MASSECUITE POL ";A(51,1)
2060  INPUT " 51   B MASSECUITE POL",A(51,1)
2070 PRINT HEX(0A)
2080 PRINT " 52   C MASSECUITE BRIX ";A(52,1)
2090  INPUT " 52   C MASSECUITE BRIX",A(52,1)
2100 PRINT HEX(0A)
2110 PRINT " 53   C MASSECUITE POL ";A(53,1)
2120  INPUT " 53   C MASSECUITE POL",A(53,1)
2130 PRINT HEX(0A)
2140 PRINT " 54   A MOLASSES BRIX ";A(54,1)
2150  INPUT " 54   A MOLASSES BRIX",A(54,1)
2160 PRINT HEX(0A)
2170 PRINT " 55   A MOLASSES POL ";A(55,1)
2180  INPUT " 55   A MOLASSES POL",A(55,1)
2190 PRINT HEX(0A)
2200  IF H(19)=0 THEN 2270
2210 PRINT " 56   TOP-OFF A MOLASSES BRIX ";A(56,1)
2220  INPUT " 56   TOP-OFF A MOLASSES BRIX",A(56,1)
2230 PRINT HEX(0A)
2240 PRINT " 57   TOP-OFF A MOLASSES POL ";A(57,1)
2250  INPUT " 57   TOP-OFF A MOLASSES POL",A(57,1)
2260 PRINT HEX(0A)
2270 PRINT " 58   B MOLASSES BRIX ";A(58,1)
2280  INPUT " 58   B MOLASSES BRIX",A(58,1)
2290 PRINT HEX(0A)
2300 PRINT " 59   B MOLASSES POL ";A(59,1)
2310  INPUT " 59   B MOLASSES POL",A(59,1)
2320 PRINT HEX(0A)
2330 PRINT " 60   GRAIN BRIX ";A(60,1)
2340  INPUT " 60   GRAIN BRIX",A(60,1)
2350 PRINT HEX(0A)
2360 PRINT " 61   GRAIN POL ";A(61,1)
2370  INPUT " 61   GRAIN POL",A(61,1)
2380 PRINT HEX(0A)
2390 PRINT " 62   C MAGMA BRIX ";A(62,1)
2400  INPUT " 62   C MAGMA BRIX",A(62,1)
2410 PRINT HEX(0A)
2420 PRINT " 63   C MAGMA POL ";A(63,1)
2430  INPUT " 63   C MAGMA POL",A(63,1)
2440 PRINT HEX(0A)
```

```
2450  IF H(20)=0 THEN 2600
2460  IF H(22)=0 THEN 2540
2470 PRINT " 64   B MAGMA BRIX ";A(64,1)
2480  INPUT " 64   B MAGMA BRIX",A(64,1)
2490 PRINT HEX(0A)
2500 PRINT " 65   B MAGMA POL ";A(65,1)
2510  INPUT " 65   B MAGMA POL",A(65,1)
2520 PRINT HEX(0A)
2530  GOTO 2600
2540 PRINT " 64   C CYCLONE BRIX ";A(64,1)
2550  INPUT " 64   C CYCLONE BRIX",A(64,1)
2560 PRINT HEX(0A)
2570 PRINT " 65   C CYCLONE POL ";A(65,1)
2580  INPUT " 65   C CYCLONE POL",A(65,1)
2590 PRINT HEX(0A)
2600 PRINT " 66   CU. FT. OF A MASSECUITE MADE ";A(66,1)
2610  INPUT " 66   CU. FT. OF A MASSECUITE MADE",A(66,1)
2620 PRINT HEX(0A)
2630  IF H(19)=0 THEN 2670
2640 PRINT " 67   CU. FT. OF TOP-OFF A MASSECUITE MADE ";A(67,1)
2650  INPUT " 67   CU. FT. OF TOP-OFF A MASSECUITE MADE",A(67,1)
2660 PRINT HEX(0A)
2670 PRINT " 68   CU. FT. OF B MASSECUITE MADE ";A(68,1)
2680  INPUT " 68   CU. FT. OF B MASSECUITE MADE",A(68,1)
2690 PRINT HEX(0A)
2700 PRINT " 69   CU. FT. OF C MASSECUITE MADE ";A(69,1)
2710  INPUT " 69   CU. FT. OF C MASSECUITE MADE",A(69,1)
2720 PRINT HEX(0A)
2730 PRINT " 70   MOISTURE % SUGAR MADE ";A(70,1)
2740  INPUT " 70   MOISTURE % SUGAR MADE",A(70,1)
2750 PRINT HEX(0A)
2760 PRINT " 71   POL OF SUGAR MADE ";A(71,1)
2770  INPUT " 71   POL OF SUGAR MADE",A(71,1)
2780 PRINT HEX(0A)
2790  IF H(10)=0 THEN 2830
2800 PRINT " 72   STARCH % SUGAR MADE ";A(72,1)
2810  INPUT " 72   STARCH % SUGAR MADE",A(72,1)
2820 PRINT HEX(0A)
2830  IF H(11)=0 THEN 2870
2840 PRINT " 73   DEXTRAN SUGAR MADE ";A(73,1)
2850  INPUT " 73   DEXTRAN SUGAR MADE",A(73,1)
2860 PRINT HEX(0A)
2870 PRINT " 74   FINAL MOLASSES MADE BRIX ";A(74,1)
2880  INPUT " 74   FINAL MOLASSES MADE BRIX",A(74,1)
2890 PRINT HEX(0A)
2900 PRINT " 75   FINAL MOLASSES MADE POL ";A(75,1)
2910  INPUT " 75   FINAL MOLASSES MADE POL",A(75,1)
2920 PRINT HEX(0A)
2930  IF H(12)=0 THEN 2970
2940 PRINT " 76   FINAL MOLASSES MADE % GLUCOSE ";A(76,1)
2950  INPUT " 76   FINAL MOLASSES MADE % GLUCOSE",A(76,1)
2960 PRINT HEX(0A)
2970  IF H(13)=0 THEN 3010
2980 PRINT " 77   FINAL MOLASSES MADE % ASH ";A(77,1)
2990  INPUT " 77   FINAL MOLASSES MADE % ASH",A(77,1)
3000 PRINT HEX(0A)
3010  IF H(14)=0 THEN 3050
3020 PRINT " 78   FINAL MOLASSES MADE CLERGET ";A(78,1)
3030  INPUT " 78   FINAL MOLASSES MADE CLERGET",A(78,1)
3040 PRINT HEX(0A)
3050 PRINT " 79   FINAL MOLASSES SHIPPED BRIX ";A(79,1)
```

```
3060  INPUT " 79   FINAL MOLASSES SHIPPED BRIX",A(79,1)
3070 PRINT HEX(0A)
3080 PRINT " 80   FINAL MOLASSES SHIPPED POL ";A(80,1)
3090  INPUT " 80   FINAL MOLASSES SHIPPED POL",A(80,1)
3100 PRINT HEX(0A)
3110  IF H(15)=0 THEN 3150
3120 PRINT " 81   FINAL MOLASSES SHIPPED % GLUCOSE ";A(81,1)
3130  INPUT " 81   FINAL MOLASSES SHIPPED % GLUCOSE",A(81,1)
3140 PRINT HEX(0A)
3150  IF H(16)=0 THEN 3190
3160 PRINT " 82   FINAL MOLASSES SHIPPED % ASH ";A(82,1)
3170  INPUT " 82   FINAL MOLASSES SHIPPED % ASH",A(82,1)
3180 PRINT HEX(0A)
3190  IF H(17)=0 THEN 3230
3200 PRINT " 83   FINAL MOLASSES SHIPPED CLERGET ";A(83,1)
3210  INPUT " 83   FINAL MOLASSES SHIPPED CLERGET",A(83,1)
3220 PRINT HEX(0A)
3230 PRINT " 84   POL % FILTER CAKE ";A(84,1)
3240  INPUT " 84   POL % FILTER CAKE",A(84,1)
3250 PRINT HEX(0A)
3260  IF H(21)=0 THEN 3300
3270 PRINT " 85   MOISTURE % FILTER CAKE ";A(85,1)
3280  INPUT " 85   MOISTURE % FILTER CAKE",A(85,1)
3290 PRINT HEX(0A)
3300 PRINT " 86   POL % BAGASSE ";A(86,1)
3310  INPUT " 86   POL % BAGASSE",A(86,1)
3320 PRINT HEX(0A)
3330 PRINT " 87   MOISTURE % BAGASSE ";A(87,1)
3340  INPUT " 87   MOISTURE % BAGASSE",A(87,1)
3350 PRINT HEX(0A)
3360 PRINT " 88   TONS CANE PURCHASED ";A(88,1)
3370  INPUT " 88   TONS CANE PURCHASED",A(88,1)
3380 PRINT HEX(0A)
3385 GOTO 3450
3390 PRINT " 89   NET TONS CANE PURCHASED ";A(89,1)
3400  INPUT " 89   NET TONS CANE PURCHASED",A(89,1)
3410 PRINT HEX(0A)
3420 PRINT " 90   STANDARD TONS CANE PURCHASED ";A(90,1)
3430  INPUT " 90   STANDARD TONS CANE PURCHASED",A(90,1)
3440 PRINT HEX(0A)
3450 PRINT " 91   TONS CANE GROUND ";A(91,1)
3460  INPUT " 91   TONS CANE GROUND",A(91,1)
3470 PRINT HEX(0A)
3480 PRINT " 92   TONS MIXED JUICE ";A(92,1)
3490  INPUT " 92   TONS MIXED JUICE",A(92,1)
3500 PRINT HEX(0A)
3510 PRINT " 93   TONS IMBIBITION WATER ";A(93,1)
3520  INPUT " 93   TONS IMBIBITION WATER",A(93,1)
3530 PRINT HEX(0A)
3540 PRINT " 94   TONS FILTER CAKE MADE ";A(94,1)
3550  INPUT " 94   TONS FILTER CAKE MADE",A(94,1)
3560 PRINT HEX(0A)
3570 PRINT " 95   LBS SUGAR MADE ";A(95,1)
3580  INPUT " 95   LBS SUGAR MADE",A(95,1)
3590 PRINT HEX(0A)
3600 PRINT " 96   GALLONS FINAL MOLASSES MADE ";A(96,1)
3610  INPUT " 96   GALLONS FINAL MOLASSES MADE",A(96,1)
3620 PRINT HEX(0A)
3630 PRINT " 97   LBS SUGAR SHIPPED ";A(97,1)
3640  INPUT " 97   LBS SUGAR SHIPPED",A(97,1)
3650 PRINT HEX(0A)
```

```
3660 PRINT " 98   GALLONS FINAL MOLASSES SHIPPED ";A(98,1)
3670  INPUT " 98   GALLONS FINAL MOLASSES SHIPPED",A(98,1)
3680 PRINT HEX(0A)
3690 PRINT " 99   CORE LAB CANE, % POL ";A(99,1)
3700  INPUT " 99   CORE LAB CANE, % POL",A(99,1)
3710 PRINT HEX(0A)
3720 PRINT "100   CORE LAB CANE, % BRIX ";A(100,1)
3730  INPUT "100   CORE LAB CANE, % BRIX",A(100,1)
3740 PRINT HEX(0A)
3750 PRINT "101   CORE LAB CANE, % FIBER ";A(101,1)
3760  INPUT "101   CORE LAB CANE, % FIBER",A(101,1)
3770 PRINT HEX(0A)
3780 PRINT "102   RAINFALL, INCHES ";A(102,1)
3790  INPUT "102   RAINFALL, INCHES",A(102,1)
3800 PRINT HEX(0A)
3810 PRINT "103   MAXIMUM TEMPERATURE, DEG. F ";A(103,1)
3820  INPUT "103   MAXIMUM TEMPERATURE, DEG. F",A(103,1)
3830 PRINT HEX(0A)
3840 PRINT "104   MINIMUM TEMPERATURE, DEG. F ";A(104,1)
3850  INPUT "104   MINIMUM TEMPERATURE, DEG. F",A(104,1)
3860 PRINT HEX(0A)
3870 PRINT "105   LBS SUGAR BRIX IN PROCESS ";A(105,1)
3880  INPUT "105   LBS SUGAR BRIX IN PROCESS",A(105,1)
3890 PRINT HEX(0A)
3900 PRINT "106   LBS SUGAR POL IN PROCESS ";A(106,1)
3910  INPUT "106   LBS SUGAR POL IN PROCESS",A(106,1)
3920 PRINT HEX(0A)
3930 PRINT "107   LBS FINAL MOLASSES BRIX IN PROCESS ";A(107,1)
3940  INPUT "107   LBS FINAL MOLASSES BRIX IN PROCESS",A(107,1)
3950 PRINT HEX(0A)
3960 PRINT "108   LBS FINAL MOLASSES POL IN PROCESS ";A(108,1)
3970  INPUT "108   LBS FINAL MOLASSES POL IN PROCESS",A(108,1)
3980 PRINT HEX(0A)
3990 IF H(27)=0 THEN 4030
4000 PRINT "246    TONS OF METERED IMBIBITON WATER ";A(246,1)
4010 INPUT "246    TONS OF METERED IMBIBITON WATER",A(246,1)
4011 PRINT "251    LBS SUGAR IN WAREHOUSE # 1 ";A(251,1)
4012 INPUT "251    LBS SUGAR IN WAREHOUSE # 1",A(251,1)
4013 PRINT "252    LBS SUGAR IN WAREHOUSE # 2 ";A(252,1)
4014 INPUT "252    LBS SUGAR IN WAREHOUSE # 2",A(252,1)
4015 PRINT "253    LBS SUGAR IN WAREHOUSE # 3 ";A(253,1)
4016 INPUT "253    LBS SUGAR IN WAREHOUSE # 3",A(253,1)
4017 PRINT "254    LBS SUGAR IN WAREHOUSE # 4 ";A(254,1)
4018 INPUT "254    LBS SUGAR IN WAREHOUSE # 4",A(254,1)
4020 PRINT HEX(0A)
4030 LINPUT "REMARKS - LINE 1A",-B1$(1)
4040 LINPUT "REMARKS - LINE 1B",-B1$(2)
4050 LINPUT "REMARKS - LINE 2A",-B1$(3)
4060 LINPUT "REMARKS - LINE 2B",-B1$(4)
4070 LINPUT "REMARKS - LINE 3A",-B1$(5)
4080 LINPUT "REMARKS - LINE 3B",-B1$(6)
4090 LOAD T "MRDACOWU" 10
```