```
0010  REM THIS PROGRAM PRINTS UP THE DAILY REPORT DATA FORM (MRDATAFM)
0020  DIM C$(110)36,X(110)
0030 SELECT PRINT 005(80)
0040 PRINT HEX(030A0A0A0A0A0A0A0A0A0A0A0A0A0A0A)
0050 PRINT "PRINTING UP DATA FORMS"
0060  FOR J=1 TO 10
0070  C$(J+2)=J$(J)
0080  NEXT J
0090  FOR J=1 TO 12
0100  C$(J+13)=H$(J)
0110  NEXT J
0120  C$(1)="Report Date"
0130  C$(1)="Crop Day Number"
0140  C$(2)="Lbs TRS Purchased"
0150  C$(13)="Total Hours Available"
0160  C$(26)="Crusher Juice Brix"
0170  C$(27)="Crusher Juice Pol"
0180  C$(28)="Crusher Juice Glucose"
0190  C$(29)="Crusher Juice pH"
0200  C$(30)="Mixed Juice Brix"
0210  C$(31)="Mixed Juice Pol"
0220  C$(32)="Mixed Juice Glucose"
0230  C$(33)="Mixed Juice pH"
0240  C$(34)="Last Roll Juice Brix"
0250  C$(35)="Last Roll Juice Pol"
0260  C$(36)="Clarified Juice Brix"
0270  C$(37)="Clarified Juice Pol"
0280  C$(38)="Clarified Juice Glucose"
0290  C$(39)="Clarified Juice pH"
0300  C$(40)="Filter Press Juice Brix"
0310  C$(41)="Filter Press Juice Pol"
0320  C$(42)="Syrup Brix"
0330  C$(43)="Syrup Pol"
0340  C$(44)="Syrup Glucose"
0350  C$(45)="Syrup pH"
0360  C$(46)="A Massecuite Brix"
0370  C$(47)="A Massecuite Pol"
0380  C$(48)="Top-Off A Massecuite Brix"
0390  C$(49)="Top-Off A Massecuite Pol"
0400  C$(50)="B Massecuite Brix"
0410  C$(51)="B Massecuite Pol"
0420  C$(52)="C Massecuite Brix"
0430  C$(53)="C Massecuite Pol"
0440  C$(54)="A Molasses Brix"
0450  C$(55)="A Molasses Pol"
0460  C$(56)="Top-Off A Molasses Brix"
0470  C$(57)="Top-Off A Molasses Pol"
0480  C$(58)="B Molasses Brix"
0490  C$(59)="B Molasses Pol"
0500  C$(60)="Grain Brix"
0510  C$(61)="Grain Pol"
0520  C$(62)="C Magma Brix"
0530  C$(63)="C Magma Pol"
0540  C$(64)="B Magma Brix"
0550  C$(65)="B Magma Pol"
0560  C$(66)="Cu. Ft. of A Massecuite Made"
0570  C$(67)="Cu. Ft. of Top-Off A Massecuite Made"
0580  C$(68)="Cu. Ft. of B Massecuite Made"
0590  C$(69)="Cu. Ft. of C Massecuite Made"
0600  C$(70)="Sugar Made, % Moisture"
0610  C$(71)="Sugar Made, % Pol"
```

```
0620  C$(72)="Sugar Made, % Starch"
0630  C$(73)="Sugar Made, Dextran"
0640  C$(74)="Final Molasses Made Brix"
0650  C$(75)="Final Molasses Made Pol"
0660  C$(76)="Final Molasses Made Glucose"
0670  C$(77)="Final Molasses Made Ash"
0680  C$(78)="Final Molasses Made Clerget"
0690  C$(79)="Final Molasses Shipped Brix"
0700  C$(80)="Final Molasses Shipped Pol"
0710  C$(81)="Final Molasses Shipped Glucose"
0720  C$(82)="Final Molasses Shipped Ash"
0730  C$(83)="Final Molasses Shipped Clerget"
0740  C$(84)="Filter Cake Pol"
0750  C$(85)="Filter Cake Moisture"
0760  C$(86)="Bagasse Pol"
0770  C$(87)="Bagasse Moisture"
0780  C$(88)="Tons Cane Purchased"
0790  C$(89)="Net Tons Cane Purchased"
0800  C$(90)="Standard Tons Cane Purchased"
0810  C$(91)="Tons Cane Ground"
0820  C$(92)="Tons Mixed Juice"
0830  C$(93)="Tons Imbibition Water"
0840  C$(94)="Tons Filter Cake Made"
0850  C$(95)="Lbs Sugar Made"
0860  C$(96)="Gallons Final Molasses Made"
0870  C$(97)="Lbs Sugar Shipped"
0880  C$(98)="Gallons Final Molasses Shipped"
0890  C$(99)="Core Lab Cane, % Pol"
0900  C$(100)="Core Lab Cane, % Brix"
0910  C$(101)="Core Lab Cane, % Fiber"
0920  C$(102)="Rainfall, Inches"
0930  C$(103)="Temperature, Maximum, deg. F"
0940  C$(104)="Temperature, Minimum, deg. F"
0950  C$(105)="Lbs Sugar Brix in Process"
0960  C$(106)="Lbs Sugar Pol in Process"
0970  C$(107)="Lbs Final Molasses Brix in Process"
0980  C$(108)="Lbs Final Molasses Pol in Process"
0990  C$(109)="Weighting Factor"
1000  C$(110)="Tons Metered Imbibition Water"
1010  IF H(22)=1 THEN 1040
1020  C$(64)="C Cyclone Brix"
1030  C$(65)="C Cyclone Pol"
1040  SELECT PRINT 215(132)
1042 IF H(36)=0 THEN 1050
1044 SELECT PRINT 204(132)
1050  IF H(23)=0 THEN 1080
1060  PRINT HEX(0E);TAB(20-LEN(B$)/2);B$
1070  GOTO 1090
1080  PRINT TAB(40-LEN(B$)/2);B$
1090  PRINT HEX(0A0A)
1100  PRINT TAB(26);"DAILY REPORT DATA INPUT FORM";TAB(70);"Page 1"
1110  PRINT HEX(0A0A0A)
1120  PRINTUSING 2900,"  ","Report Date"
1130 J=1
1140  PRINTUSING 2960,J,C$(J)
1150  GOSUB '1(2,2)
1160  PRINT HEX(0A)
1170  GOSUB '1(3,13)
1180  PRINT HEX(0A)
1190  GOSUB '1(14,25)
1200  PRINT HEX(0A)
```

```
1210  GOSUB '1(26,27)
1220  IF H(2)=0 THEN 1250
1230  GOSUB '1(28,28)
1240  GOTO 1260
1250  GOSUB '2(28,28)
1260  IF H(3)=0 THEN 1290
1270  GOSUB '1(29,29)
1280  GOTO 1300
1290  GOSUB '2(29,29)
1300  PRINT HEX(0A)
1310  GOSUB '1(30,31)
1320  IF H(4)=0 THEN 1350
1330  GOSUB '1(32,32)
1340  GOTO 1360
1350  GOSUB '2(32,32)
1360  IF H(5)=0 THEN 1390
1370  GOSUB '1(33,33)
1380  GOTO 1400
1390  GOSUB '2(33,33)
1400  PRINT HEX(0A)
1410  GOSUB '1(34,35)
1420  PRINT HEX(0A)
1430  GOSUB '1(36,37)
1440  IF H(6)=0 THEN 1470
1450  GOSUB '1(38,38)
1460  GOTO 1480
1470  GOSUB '2(38,38)
1480  IF H(7)=0 THEN 1510
1490  GOSUB '1(39,39)
1500  GOTO 1520
1510  GOSUB '2(39,39)
1520  PRINT HEX(0C)
1530  IF H(23)=0 THEN 1560
1540  PRINT HEX(0E);TAB(20-LEN(B$)/2);B$
1550  GOTO 1570
1560  PRINT TAB(40-LEN(B$)/2);B$
1570  PRINT HEX(0A0A)
1580  PRINT TAB(23);"DAILY REPORT DATA INPUT FORM (Cont'd)";TAB(70);"Page 2"
1590  PRINT HEX(0A0A0A)
1600  IF H(18)=0 THEN 1630
1610  GOSUB '1(40,41)
1620  GOTO 1640
1630  GOSUB '2(40,41)
1640  PRINT HEX(0A)
1650  GOSUB '1(42,43)
1660  IF H(8)=0 THEN 1690
1670  GOSUB '1(44,44)
1680  GOTO 1700
1690  GOSUB '2(44,44)
1700  IF H(9)=0 THEN 1730
1710  GOSUB '1(45,45)
1720  GOTO 1740
1730  GOSUB '2(45,45)
1740  PRINT HEX(0A)
1750  GOSUB '1(46,47)
1760  PRINT HEX(0A)
1770  IF H(19)=0 THEN 1800
1780  GOSUB '1(48,49)
1790  GOTO 1810
1800  GOSUB '2(48,49)
1810  PRINT HEX(0A)
```

```
1820  GOSUB '1(50,51)
1830  PRINT HEX(0A)
1840  GOSUB '1(52,53)
1850  PRINT HEX(0A)
1860  GOSUB '1(54,55)
1870  PRINT HEX(0A)
1880  IF H(19)=0 THEN 1910
1890  GOSUB '1(56,57)
1900  GOTO 1920
1910  GOSUB '2(56,57)
1920  PRINT HEX(0A)
1930  GOSUB '1(58,59)
1940  PRINT HEX(0A)
1950  GOSUB '1(60,61)
1960  PRINT HEX(0A)
1970  GOSUB '1(62,63)
1980  PRINT HEX(0A)
1990  IF H(20)=0 THEN 2020
2000  GOSUB '1(64,65)
2010  GOTO 2030
2020  GOSUB '2(64,65)
2030  PRINT HEX(0A)
2040  GOSUB '1(66,66)
2050  IF H(19)=0 THEN 2080
2060  GOSUB '1(67,67)
2070  GOTO 2090
2080  GOSUB '2(67,67)
2090   GOSUB '1(68,69)
2100  PRINT HEX(0A)
2110  GOSUB '1(70,71)
2120  IF H(10)=0 THEN 2150
2130  GOSUB '1(72,72)
2140  GOTO 2160
2150  GOSUB '2(72,72)
2160  IF H(11)=0 THEN 2190
2170  GOSUB '1(73,73)
2180  GOTO 2200
2190  GOSUB '2(73,73)
2200  PRINT HEX(0C)
2210  IF H(23)=0 THEN 2240
2220  PRINT HEX(0E);TAB(20-LEN(B$)/2);B$
2230  GOTO 2250
2240  PRINT TAB(40-LEN(B$)/2);B$
2250  PRINT HEX(0A)
2260  PRINT TAB(23);"DAILY REPORT DATA INPUT FORM (Cont'd)";TAB(70);"Page 3"
2270  PRINT HEX(0A)
2280  GOSUB '1(74,75)
2290  IF H(12)=0 THEN 2320
2300  GOSUB '1(76,76)
2310  GOTO 2330
2320  GOSUB '2(76,76)
2330  IF H(13)=0 THEN 2360
2340  GOSUB '1(77,77)
2350  GOTO 2370
2360  GOSUB '2(77,77)
2370  IF H(14)=0 THEN 2400
2380  GOSUB '1(78,78)
2390  GOTO 2410
2400  GOSUB '2(78,78)
2410  PRINT HEX(0A)
2420  GOSUB '1(79,80)
```

```
2430  IF H(15)=0 THEN 2460
2440  GOSUB '1(81,81)
2450  GOTO 2470
2460  GOSUB '2(81,81)
2470  IF H(16)=0 THEN 2500
2480  GOSUB '1(82,82)
2490  GOTO 2510
2500  GOSUB '2(82,82)
2510  IF H(17)=0 THEN 2540
2520  GOSUB '1(83,83)
2530  GOTO 2550
2540  GOSUB '2(83,83)
2550  PRINT HEX(0A)
2560  GOSUB '1(84,84)
2570  IF H(21)=0 THEN 2600
2580  GOSUB '1(85,85)
2590  GOTO 2610
2600  GOSUB '2(85,85)
2610  PRINT HEX(0A)
2620  GOSUB '1(86,87)
2630  PRINT HEX(0A)
2640  GOSUB '1(88,88)
2650  PRINT HEX(0A)
2660  GOSUB '1(91,96)
2670  PRINT HEX(0A)
2680  GOSUB '1(97,98)
2690  PRINT HEX(0A)
2700  GOSUB '1(99,101)
2710  PRINT HEX(0A)
2720  GOSUB '1(102,102)
2730  PRINT HEX(0A)
2740  GOSUB '1(103,104)
2750  PRINT HEX(0A)
2760  GOSUB '1(105,106)
2770  PRINT HEX(0A)
2780  GOSUB '1(107,108)
2790  PRINT HEX(0A)
2800  GOSUB '2(109,109)
2810  PRINT HEX(0A)
2820 IF H(27)=0 THEN 2850
2830 PRINTUSING 2900,246,C$(110)
2840 GOTO 2981
2850 PRINTUSING 2960,246,C$(110)
2860  GOTO 2981
2870  DEFFN'1(X,Y)
2880  FOR J=X TO Y
2890  PRINTUSING 2900,J,C$(J)
2900  %###    ########################################
2910  NEXT J
2920  RETURN
2930  DEFFN'2(X,Y)
2940  FOR J=X TO Y
2950  PRINTUSING 2960,J,C$(J)
2960  %###    ########################################         XXXXXXXXXX
2970  NEXT J
2980  RETURN
2981 PRINT HEX(0A)
2982  PRINTUSING 2900,"251","Lbs Sugar in W/H #1"
2983  PRINTUSING 2900,"252","Lbs Sugar in W/H #2"
2984  PRINTUSING 2900,"253","Lbs Sugar in W/H #3"
2985  PRINTUSING 2900,"254","Lbs Sugar in W/H #4"
```

```
2990 PRINT HEX(0C)
3000 PRINT "REMARKS - LINE 1A:       ----------------------------------------------------------------"
3010 PRINT "REMARKS - LINE 1B:       ----------------------------------------------------------------"
3020 PRINT "REMARKS - LINE 2A:       ----------------------------------------------------------------"
3030 PRINT "REMARKS - LINE 2B:       ----------------------------------------------------------------"
3040 PRINT "REMARKS - LINE 3A:       ----------------------------------------------------------------"
3050 PRINT "REMARKS - LINE 3B:       ----------------------------------------------------------------"
3060  PRINT HEX(0C)
3070  LOAD T "MRSTART" 10
```