Gold Standard Service Corp.

P.O. BOX 4831 Rancho Cucamonga, CA 91729

gold-standard@hotmail.com (877)313-3552 Of...

Bill To

P.O. #

Unit # S2

Hour Meter: 14958

Serial # SA-06-05151

Total Transportation & Distribution 210 East Lambert Road, Fullerton, CA 9283

KP11937-S2

Invoice

Gold Standard
Service

Date: 1/14/2022

Invoice # 36761

Work Order # 36761

Ship To

11937 Woodruff Downey, CA

Terms: Due on receipt

Due Date: 1/14/2022

Ship Date 1/13/2022 Tech: JR

Model: RaymondSACSR30T

Description	Qty	Rate	Amount
Labor Special Rate Total Trans: 1/11 Check oil leak. Found broken hose guard and leaking hose. Ordered Parts. 1/13 Pickup parts and return. Replace two ACX hoses and one mini lift hose on overhead guard. Replace guard and install new steer tiller. Test OK.	6.5	112.50	731.25
Hose Assembly Hose 1001288/104 Overhead chain Tiller-Arm RA838-007-102	1 1 1 1	263.47 272.26 273.97 675.86 68.68	263.47T 272.26T 273.97T 675.86T 68.68T

Thank you for choosing Gold Standard Service for all your material handling needs.	Subtotal	\$2,285.49
	Sales Tax (10.0%)	\$155.42
	Total	\$2,440.91
Remit To: Gold Standard Service Corp. P. O. Box 4831	Payments/Credits	\$0.00
Rancho Cucamonga, CA 91729		\$2,440.91