Return shipping instructions:

- 1: Remove lithium battery from each case.
- 2: Place all shipping foam back inside each case.
- 3: Peel off or cover the following items (MUST NOT BE VISIBLE): -QTY2 "UN3480" labels.
 - -QTY1 "FedEx Hazardous Materials Shipping Papers Enclosed" pouch
 - -QTY1 "Hazardous Materials Description and Quantity" label.
- 4: Place one prepaid USPS return shipping label onto each box.
- 5: Drop off at any USPS facility.