On T-Beam v1.x:	Interacts with	these options:									
Using this option:	Active buzzer	Passive buzzer	Strobe	Voice	Auxiliary serial port	ADS-B module	External GNSS	SD card	OLED	BMP	Notes
Active buzzer on pin 14				only via DAC			not via pins 14,15				
Passive buzzer on pins 14,15				only via DAC			not via pins 14,15				
Strobe on pin 25				if strobe on 15				not via pins 13,25			
Voice via DAC on pin 25	available	n.a. if strobe too	move to pin 15					not via pins 13,25			
Voice via I2S on pins 14,15,25	not available	not available	not available				not via pins 14,15	not via pins 13,25			
Auxiliary serial port on pins VN,4	1					not available	not via pins VN,4				affects red LED
ADS-B module on pins VN,4					not available		not via pins VN,4				affects red LED
											main serial alt pin n.a.,
External GNSS on pins VN,4,VP					not available	not available		no PPS if SD uses VP			affects blue LED
External GNSS on pins 15,14,VP	not available	not available	n.a. if voice too	only via DAC				no PPS if SD uses VP			main serial alt pin n.a.
											harder to flash via USB,
External GNSS on pins 13,2,VP								only via LORA pins	only on 21,22	only on 21,22	main serial alt pin n.a.
SD card on 13,25,2,0			not available	not available			not via pins 13,2		only on 21,22	only on 21,22	harder to flash via USB
			not if want PPS	not if want PPS							harder to flash via USB,
SD card on 13,VP,2,0			on pin 25	on pin 25			no PPS, or PPS on 25		only on 21,22	only on 21,22	main serial alt pin n.a.
SD card on LORA (5,19,27), 0											soldered to LORA chip
OLED on pins 21,22											
OLED on pins 13,2							not via pins 13,2	only via LORA pins			harder to flash via USB
BMP on pins 21,22											
BMP on pins 13,2							not via pins 13,2	only via LORA pins			harder to flash via USB

On T-Beam v0.7:	Interacts with these options:										
Using this option:	Active buzzer	Passive buzzer	Strobe	Voice	Auxiliary serial port	ADS-B module	External GNSS	SD card	OLED	BMP	Notes
Active buzzer on pin 14							not via pins 25,14				affects blue LED
Passive buzzer on pins 14,25			not available	not available			not via pins 25,14	not via pins 13,25			affects blue LED
Strobe on pin 25	available	not available		not available			not via pins 25,14	not via pins 13,25			
Voice via DAC on pin 25	available	not available	not available				not via pins 25,14	not via pins 13,25			
Auxiliary serial port on pins VP,4						not available	not via pins VP,4	not via pins 13,4			main serial alt pin n.a.
ADS-B module on pins VP,4					not available		not via pins VP,4	not via pins 13,4			main serial alt pin n.a.
External GNSS on pins VP,4,25			no PPS if used	no PPS if used	not available	not available		no PPS if via pins 13,25			main serial alt pin n.a.
											main serial alt pin n.a.,
External GNSS on pins 25,14,VP	not available	not available	not available	not available	no PPS if used	no PPS if used		not via pins 13,25			affects blue LED
											harder to flash via USB,
External GNSS on pins 13,2,VP					PPS to pin 25	PPS to pin 25		only via LORA pins	only on 21,22	only on 21,22	main serial alt pin n.a.
SD card on 13,25,2,0			not available	not available			only on VP,4 & no PPS		only on 21,22	only on 21,22	harder to flash via USB
SD card on 13,4,2,0					not available	not available	only on 25,14,VP		only on 21,22	only on 21,22	harder to flash via USB
SD card on LORA (5,19,27), 0											soldered to LORA chip
OLED on pins 21,22											
OLED on pins 13,2							not via pins 13,2	only via LORA pins			harder to flash via USB
BMP on pins 21,22											
BMP on pins 13,2							not via pins 13,2	only via LORA pins			harder to flash via USB