Parts list Voron Trident 5-axis

Base

| Dasc | | |
|--------------------------------------|--------------------------------|----|
| Aluminium Extrusion 2020 | Lenght 410mm | 2 |
| Aluminium Extrusion 2020 | Lenght 180mm | 2 |
| 90 Degree corners | For Aluminium profile 2020 | 12 |
| Screw | M5 x 10mm | 24 |
| Screw | M5 x 20mm | 12 |
| T nuts | M5 | 36 |
| Heat insert | M3 x 5mm | 2 |
| Screw SHCS | M3 x 8mm | 6 |
| High precision Bearing | 608ZZ | 4 |
| Spacer M8 x 1mm | | 2 |
| Spacer M3 x 0.7 mm | | 4 |
| Shaft 8mm Left | lenght 57 mm | 1 |
| Shaft 8mm Right | lenght 79 mm | 1 |
| Nema 17 stepper motor | 48mm 0.9deg, optimal 2.0Amp | 1 |
| optical switch sensor for 3D printer | | 1 |
| Closed loop GT2 belt 6mm | lenght 302 or 303 mm | 1 |
| Pulley GT2 | 80 tooth 8mm bore | 1 |
| Pulley GT2 | 16 tooth 5mm bore | 1 |

https://www.amazon.com/M akerHawk-Optical-Endstop-Photoelectric-Control/dp/B07PMW2QMT/r ef=sr_1_1?keywords=Optical +Endstop&qid=1700156544& sr=8-1

Table

| Heat insert | M3 x 5mm | 40 |
|-------------|----------|----|
| Heat insert | M3 x 7mm | 6 |

| Screw SHCS | M3 x 8mm | 52 |
|---|---|----|
| Screw SHCS | M3 x 10mm | 20 |
| Screw SHCS | M3 x 12mm | 1 |
| Screw SHCS | M3 x 20mm | 6 |
| Screw FHCS | M3 x 22mm | 6 |
| Spacer M3 x 0.7 mm | | 7 |
| NEMA_17_20mm 1.8deg | | 1 |
| Pulley GT2 | 20 tooth 5mm bore | 1 |
| Slip Ring | Dia 22mm 4CH 10A | 1 |
| IGUS ring | PRT_04_30 Diameter 90mm | 1 |
| High precision Bearing | 608ZZ | 2 |
| Closed loop GT2 belt 6mm | lenght 330mm | 1 |
| Pololu Hub 8mm | The six M3 holes needs to be drilled with 3.2mm drill | 2 |
| Round Heated bed round for kossel 220mm 24V | | 1 |
| Round Magnetic sheet 220mm | | 1 |
| Round PEI sheet 220mm | for kossel | 1 |
| Bed spring | ID 3mm OD 6mm Lenght 15mm | 6 |

https://www.amazon.com/s? k=slip+ring+4+wire&crid=2CO T7GQJ0ZHZ7&sprefix=slip+rin g+4+wire%2Caps%2C217&ref =nb_sb_noss_1

https://www.igus.ch/product /iglidur_PRT_04?artnr=PRT-04-30

Z - axis Hotend with Extruder

| Heat insert | M3 x 5mm | 20 |
|-------------|----------|----|
| Heat insert | M2 x 4mm | 13 |
| Screw SHCS | M2 x 6mm | 17 |

| Screw SHCS | M3 x 8mm | 12 |
|--|---|----|
| Screw SHCS | M3 x 10mm | 4 |
| Screw SHCS | M3 x 14mm | 8 |
| Screw SHCS | M3 x 16mm | 3 |
| Screw FHCS | M3 x 22mm | 2 |
| Screw FHCS stainless steel !!! | M3 x 6mm | 10 |
| Spacer M5 x 1mm | | 1 |
| Spacer M2 x 0.5 mm wide | | 4 |
| neodymium magnets | 6 x 3 mm | 4 |
| Self taping Screw | M2 size for micro switch | 2 |
| MGN7 - H Linear Rail | Lenght 200mm | 1 |
| NEMA_17_20mm 1.8deg | | 1 |
| Small Shaft 5mm | Lenght 44mm | 1 |
| Shaft Collar 5mm | | 1 |
| High precision Bearing | 625 ZZ | 2 |
| Pulley GT2 | 20 tooth 5mm bore | 2 |
| GT2 belt 6mm | Lenght 500mm | 1 |
| Micro switch for 3d printer | | 1 |
| Nonplanar nozzle | 0.4mm | 1 |
| 24V Ceramic Heating Core | снс | 1 |
| Heat Break For 1.75mm Filament M6 | for V6 Hotend | 1 |
| HeatSink Extruder Radiator 3D Printer | for V6 Hotend M6 bottom, top 1/8 or M10mm thread | 1 |
| DM1 OMG V2S Extruder | with M6 to M10 adapter and stepper motor | 1 |
| PTFE Tube OD 4mm ID 2.5mm | 1.0 M then cut it tio required lenght | 1 |
| | | |

https://imprimante-3dservice.com/gb/553trianglelab-chc-v6-24v-115wceramic-heater.html

https://www.omgextrd.com/ https://store.dremc.com.au/product product-page/omgextrd-omg- s/omg-v2s-all-metal-direct-extruderdm1-extruder-upgrade dual-drive-dm1-a-dm1-b

| 24V Fan 30x30x10mm | 1 |
|--------------------|-----|
| Zip ties | 100 |

Controls

| Duet 6HC board | | 1 |
|-------------------------|----------------|---|
| Power supply output 24V | 350W min. | 1 |
| Rj-45 cable, 0.5m | male to female | 1 |
| Optional | Raspberry Pi4 | 1 |