Best Practices

- 1. Draw picture of the intended design
 - a. Clearly label inputs, output, and bus widths
- 2. Use clear variable names
- 3. Comment components as you would in a drawing
- 4. Design and test incrementally
- 5. Create concrete test benches
- 6. Agree on style convention
- 7. Compile with vcom -work work *.vhd