MX150 Only!

Introduction

According to AptioFixPkg's README, "[c]ertain firmwares fail to properly initialize 0xE2 MSR register (MSR_BROADWELL_PKG_CST_CONFIG_CONTROL) across all the cores....

CFG Lock option is available on most APTIO V firmware, although it may be hidden from the GUI. If VerifyMsrE2 reports that your 0xE2 register is consistently locked, you may try to unlock this option directly."

How to Unlock

Cyb and Fallen Chromium created script to unlock. Please download DVMT_and_0xE2_fix and read README to unlock.

After that, you should delete OC MSR 0xE2 patch.

Open /EFI/OC/config.plist, change the following code:

```
<key>AppleXcpmCfgLock</key>
```

- <true/>
- + <false/>

Credits

- Acidanthera
 - AptioFixPkg
 - OpenCorePkg
- Cyb and FallenChromium