

$$\mathbf{u}(\mathbf{x}) \bullet \hat{\mathbf{n}}(\mathbf{x}) = 0$$

$$k^{(1)} = 12 k_o$$

$$k^{(2)} = 2 k_o$$

$$k^{(3)} = 1 k_o$$

$$k^{(4)} = 6 k_o$$

$$k^{(5)} = 2 k_o$$

$$\mathbf{u}(\mathbf{x}) \bullet \hat{\mathbf{n}}(\mathbf{x}) = 0$$

$$p(\mathbf{x}) = p^{\text{left}}$$

$$p(\mathbf{x}) = p^{\text{right}}$$

 H
 L
