

WELL COMPLETION REPORT — MUD LOSS SUMMARY

(WELL-002)

Well ID:	WELL-002 (Offset Well NHK-104)
Operator:	Oil India Limited
Formation Target:	Tipam Sandstone
Incident Depth:	1,980.0 m TVD
Report Type:	Well Completion Report (WCR)
Date of Event:	03-Mar-2023

1. Incident Overview

Partial to heavy circulation loss of 55 bbl/hr encountered while drilling porous Tipam sandstone interval at 1980m depth with 1.18 sg mud weight.

2. Root Cause

Surge pressure during tripping in fractured permeable Tipam matrix, initiating induced losses into sub-hydrostatic sand bodies.

3. Mitigation Action Applied

Pumped 40 bbl blended Lost Circulation Material (LCM) sweep consisting of coarse Nutplug (15 lb/bbl), Mica flakes (10 lb/bbl), and Calcium Carbonate (20 lb/bbl). Pump rate reduced from 500 gpm to 360 gpm.

4. Outcome

Full fluid circulation restored after 7.5 hours of curing losses. No further fluid loss recorded down to target depth.