DMP Electronics Inc. 瞻營全電子股份有限公司
8F, No.12, Wu-Quan 7 Rd., Wu-Gu Industrial Park, Wu Gu Xiang, Taipei #248, Taiwan, R.O.C
Tel:+886-2 22980770 Fax:+886-2 22991883 email:info@dmp.com.tw.

Errata No: 9121D-110801

Affected Product: Vortex86DX. Item number:Vx86-9121D

The Vortex86DX , item number:Vx86-9121D, has the following errors in the Fact Sheet version 2.00

1. Chapter 2, page 8
"DDRII size support up to **1Gbytes**" changes to "DDR2 size support up to **512Mbytes**"

2. Chapter 10.4, page 85
Delete following 1GB in Two Banks.

1GB	256MB x 8 x 4	

3 Chapter 11.3 PCI Configuration Space Register, page 253
Delete 1GB in Memory Bank Register

Issue Date:2011/08/10

----------END----------