DMP Electronics Inc. 瞻營全電子股份有限公司
No.15, Wugong 5th Rd., Xinzhuang Dist., New Taipei City, #24890, Taiwan, R.O.C
Tel:+886-2 22980770 Fax:+886-2 22991883 email:info@dmp.com.tw.

Product Change Notice

Doc No. :PCN-EX-20166A


Date: 2016/06/20

Subject: Increase the UART FIFO from 16 to 32 bytes

Content: In Vortex86EX ver:CTF, the FIFO of UART 1 to UART 8 is 16 bytes. The new version, ver:ETF, increase the FIFO to 32 bytes.

Top marking:
From CTF to ETF.

CTF ETF



Ordering Part No.:
From VX86EX-9123 to VX86EX9123E

Effect :
Not any side effect from customer's hardware/software. Increase the FIFO is to avoid the data overflow when UART baud rate set to over 1M bit/s.