## **3D Printer A8 assembly parts list**

Item	Picture	Name		Check		Picture	Name	ОТУ	Check
1-1		Hot bed fixed aluminum plate	1	Oncor	2-1		Mainboard	1	Oncok
1-2		220mm*220mm*3mm Hot bed	1		2-2		Left Z axis nut support	1	
1-3		Plastic nippers	1		2-3		Right Z axis nut support	1	
1-4		1.5M Power line	1		2-4		Wind mouth	1	
1-5		5mm*160mm Screwdriver	1		2-5	0	1.6M Belt	1	
1-6		Four parts below in this bag	1		2-6	2 o CML	1.5M USB wire	1	

Item	Picture	Name	QTY	Check	Item	Picture	Name	QTY	Check
1-6-1		40*10 Fan	1		2-7		5015 Air blower	1	
1-6-2		40*11 Cooling fin	1		2-8		Y axis belt bearing support	1	
1-6-3		Fan cover	1		2-9		Seven parts below in this bag	1	
1-6-4		M3*45 Screw 2pcs M3 Spacer 8pcs	1		2-9-1	• • •	Z axis Limit switch fixed plate	2	
1-7		Screw bag include below screws	1		2-9-2		Y axis motor support	1	
1-7-1		M3*18 screw 52pcs	1		2-9-3	£.	Y axis Limit switch fixed plate	1	
1-7-2		M3 Nut 64pcs	1		2-9-4		Y axis belt fixation clamp	2	

Item	Picture	Name	QTY	Check	Item	Picture	Name	QTY	Check
1-7-3	00000	M8 Nut 16pcs M8 Spacer 12pcs	1		2-9-5		Guide rod back up plate	6	
1-7-4	E & June 1 may live	M4*8 screw 28pcs M4*14 screw 4pcs	1		2-10	***	Side support plate	2	
1-7-5	1 00 May 1	M3*30 screw 14pcs	1		2-11	Δ	Filament support plate	2	
1-7-6	# 00 m.	M3*12 screw 15pcs	1		2-12	- "Teo g	Filament support plate connecting plate	2	
1-7-7	All Man	M2*12 screw 4pcs wing nut 4pcs Spring 4pcs	1		2-13		Screen baffle plate	1	
1-7-8	Carlos domesos Carlos domesos Antes per traca	M3*20 screw 4pcs M2.3*10screw 2pcs	1		2-14	#	Z axis motor support Plate	4	
1-8		Three parts below in this bag	1		2-15		8GB TF card and card reader	1	

Item	Picture	Name	QTY	Check	Item	Picture	Name	QTY	Check
1-8-1		Wire 70CM	1		3-1		Bottom support plate	1	
1-8-2	Ö	Z Limit switch A 20CM X Limit switch B 50CM Y Limit switch C 50CM	3		3-2		Top support plate	1	
1-8-3	000	Pillar washer M3*7 4pcs Pillar washer M3*15 4pcs	8		3-3	[+ <u>-</u>	Back plate	1	
1-9		Three parts below in this bag	1		3-4		Front plate	1	
1-9-1		3mm*130mm Screwdriver	1		3-5		Support plate lock plate	2	
1-9-2		Hex wrench M1.5 Hex wrench M2 Hex wrench M2.5 Hex wrench M3	4		3-6		Z axis motor fixed plate	2	
1-9-3	ĭ	Open spanner	1		3-7	8	Y axis motor fixed plate	1	

Item	Picture	Name	QTY	Check	Item	Picture	Name	QTY	Check
1-10		Four parts below in this bag	1		3-8		Extruder	1	
1-10-1		4.5M Winding pipe	1		3-9		X axis motor	1	
1-10-2		Belting	10		3-10		Y axis motor	1	
1-10-3		R clip	3		3-11		Z axis motor	2	
1-10-4	X	Locating piece	2		3-12		Linear bearing	7	

lt	em	Picture	Name	QT	Y Check	Item	Picture	Name	QTY	Check
1-	-11		LCD 2004 screen	1		3-13		Guide rod 436mm 2pcs Guide rod 380mm 4pcs	6	
1-	-12		Y Motor line 40 Left Z Motor line 40 Right Z Motor line 90	OCM OCM OCM OCM		3-14		T type lead screw M8*345mm 2pcs Threaded rod M8*400mm 2pcs Threaded rod M8*150mm 1pcs	5	
1-	-13		Heat bed line 90	OCM 1		3-15		Power Supply	1	