

1. GENERAL

1.1. ATIS

D-ATIS Arrival 126.275

D-ATIS Departure 131.7

1.2. NOISE ABATEMENT PROCEDURES

Except for passenger operations, ACFT not in possession of noise certification in accordance with Annex 16 to the ICAO and/or ACFT whose noise certification does not conform to the minimum standards set out in Annex 16, Chapter 3, Part 2, Volume 1 are not permitted to operate to/from Dubai APT.

1.3. LOW VISIBILITY PROCEDURES (LVP)

LVP become effective when:

- Touchdown RVR is 600m or less;
- VIS 600m or less, if instrumented RVR is not available; and/or
- Ceiling 300' or less.

Regulations require serviceable surface movement radar for operations to continue when VIS or RVR is 300m or less. Any unserviceability may result in delays in the affected areas of coverage.

During LVP, pilots are required to use the CAT II/III holding points and take-off from:

- TWY N10/TWY M14A for RWY 30R;
- TWY M4/TWY K1 for RWY 12R;
- TWY N1A/TWY M1A for RWY 12L;
- TWY K17/TWY M20 for RWY 30L.

For arriving ACFT available RWY exits will be illuminated.

Arriving ACFT shall delay reporting "RWY vacated" until the ACFT has completely passed the end of the green/amber coded TWY centerline lights.

Pilots shall follow ATC clearances in combination with selected high intensity TWY centerline lights. Pilots shall not continue taxiing if high intensity TWY centerline lights are not illuminated.

1.4. FLIGHT PROCEDURES

1.4.1. ENHANCED WAKE TURBULENCE SEPARATION (eWTS)

The ICAO unified eWTS minima RECAT system is applied within DUBAI CTA and airspace controlled by DUBAI Approach. It distinguishes seven (A to G) Wake Turbulence Groups (WTG) of ACFT based on wake generation and resistance characteristics of the ACFT depending primarily on maximum certificated take-off mass, wing characteristics and speeds.

The eWTS system includes distance-based Wake Turbulence Separation minima for ACFT being provided with an ATS surveillance service in the approach and departure phases of flight and time-based separations on departure for the take-off phase of flight.

In order to benefit from this reduction of separation minima, pilots are to fully comply with assigned speeds, particularly on final approach, and to minimize RWY occupancy time. When crews are unable to maintain any assigned speeds, they must inform ATC as soon as possible.

The implementation of the ICAO eWTS scheme does not affect pilot procedures, flight management or changes to the format for completion or filling out a flight plan. The WTC designator on the ICAO flight plan does not change. Pilots are to continue to fill in the flight plan WTC in item 9 with the ICAO ACFT CAT, H,M or L, and J for SUPER HEAVY CAT.

All ACFT operating within the DUBAI CTA must enter the appropriate ACFT type designator. The use of incorrect ACFT type designator may result in possible delays due to RDR system flight plan rejection or system allocation of an unknown ACFT type resulting in larger separation application by ATC.

1. GENERAL

For ACFT in the ICAO SUPER or HEAVY WTC, the suffix of 'SUPER' or 'HEAVY' does not change. On first transmission, the word "SUPER" or "HEAVY" shall still be included, as appropriate, immediately after the ACFT call sign in the initial radiotelephony contact between such ACFT and the ATS units.

Peak traffic periods at OMDB involving a high proportion of (Super) Heavy type ACFT often occur at times when local atmospheric conditions (e.g. quartering tailwinds) favour longer lasting wake at low levels. Pilots are therefore to use caution when quartering tailwinds of 5 KT or less exist as possible transient sporadic low level wake turbulence may persist in the RWY corridor. Pilots are to be alert to larger ACFT upwind from their approach and take-off flight paths. Should unfavourable quartering tailwinds associated with wake encounter reports be prolonged, ATC will consider a RWY direction change.

TWY V is used for helicopter operations and is parallel to RWY 12R/30L ACFT operations. Pilots are to exercise caution and be prepared to receive traffic information from ATC about departing/arriving helicopters in order to avoid reaction to possible TCAS RA and TA.

1.5. MODES OF RWY OPERATION

The parallel RWYs at Dubai International APT are spaced 1263'/385m apart and staggered. The RWY spacing restrict operations to Segregated Operations on Parallel RWYs (Mode 4).

Normal operations at Dubai International APT will be conducted as segregated RWY operations with simultaneous arrivals and departures from closely spaced parallel RWYs. Simultaneous operations will be restricted to the following weather conditions:

- Cloud base is 1500' or above;
- Visibility is 5km or greater.

Available approaches during dual RWY operations when visibility is 3000m or greater is as follows:

- RWY 12 in use:
 - RWY 12L ILS (RNP);
 - RWY 12R RNP (VISUAL) (ILS switched OFF).
- RWY 30 in use:
 - RWY 30L ILS (RNP);
 - RWY 30R RNP (ILS) (VISUAL).

Approaches to non-standard arrival RWYs (RWY 12R or RWY 30R) will be either an RNP or a Visual Approach on request with ATC. ILS RWY 30R will be issued at ATC discretion during times when arrival traffic is offloaded to RWY 30R. During single RWY operations or when the visibility reduces below 3000m, an ILS approach will be available onto the arrival RWY in use.

In order to facilitate simultaneous operations departing ACFT may be issued with departure instructions in accordance with chart (10-3J) Omnidirectional Deps. Departing ACFT shall not change frequency until advised.

Pilots shall be aware of the proximity of arriving and departing traffic particularly in the event of a missed approach or baulked landing situation.

Both arriving and departing ACFT may be issued with instructions to turn on to a heading away from the adjacent RWY at any time in order to ensure separation from conflicting ACFT. Turns have been evaluated for obstacle clearance from 800' for all RWYs. For departing traffic, this turn may initially take an ACFT away from its planned departure track. ACFT should expedite climb and comply with ATC instructions without delay.

Pilots requiring full length for departure for RWY 12R or RWY 30R shall advise ATC of the required departure point on first contact and can expect delays at peak times due to RWY dependencies.

Practice autolands may be conducted in CAT I conditions when LVP are not in effect. In these cases, no safeguarding measures will be in force. Subject to operator requirements, it is not necessary to inform ATC when carrying out a practice autoland. The operator and flight crew are considered solely responsible for these practice autolands and must recognize that changes in the ILS signal may occur without warning.

1. GENERAL

1.6. TAXI PROCEDURES

1.6.1. GENERAL

All ACFT operating on the movement area of an aerodrome shall display lights intended to attract attention to the ACFT.

Taxilanes J, J1, J2, J3, U, W, Y, Z MAX 15 KT.

ACFT are not permitted to carry out 180° turn on a TWY. In some circumstances, depending on ACFT type, TWY width and location, Airside Operations may approve such a maneuver with the assistance of a marshaller.

ACFT on TWY M and TWY N are not permitted to taxi behind ACFT holding at any RWY Holding Position (RHP). This is applicable to all ACFT types.

All TWYs are code F compliant except for taxilane Q which is code C and TWYs U1 thru U6, Y1, W1, taxilanes J4, J5, U, W, Y, and Z1 which are code E.

180° turns on RWYs not permitted for ACFT larger than A320.

Crew should not take any crossovers unless specifically instructed to by ATC (this applies for arrival and departure traffic).

For arriving traffic, taxiing onto parking stands from outer parallel TWY is permitted, only when instructed by ATC.

Flight crew shall follow the TWY centerline at all times.

No live Acft movements permitted on Apron S (engine starts and taxiing under own power are prohibited within the Apron S boundaries, towed movements only).

1.6.2. WINGTIP CLEARANCE

To ensure wingtip clearance behind, flight crew are to hold as close as possible to RHP/IHP to remain visual with RHP/IHP paint markings and stopbar lights.

Pilots to use minimum power when using any 90° link northbound from taxilane Z flight/towing crew are responsible for maintaining wingtip clearance. If in doubt crew should stop, advice ATC and await further instructions.

Minimum wingtip clearance of 24.6'/7.5m for code F operations on TWY N abeam TWY P5 (due to presence of substation South side of TWY N).

In order to ensure safe wingtip clearance, crossover TWYs are used only when authorized by ATC.

1.6.3. ACFT CODE RESTRICTIONS

Code E ACFT and code F ACFT not permitted on adjacent taxilane curves at the same time in any direction.

Code F ACFT pushed onto taxilane J South of concourse B and C must align/report on centerline before an ACFT can pass on taxilane U.

Code F ACFT cannot be on taxilane J and J1 curve at the same time as code E ACFT on taxilane U and taxilane Y curve.

Code F ACFT cannot be on taxilane J and J2 curve at the same time as code E ACFT on taxilane U and W curve.

Code F ACFT cannot be on sections of taxilane W and J2 between TWY K and taxilane Z at the same time.

Code F ACFT cannot be on sections of taxilane J1 and TWY Y between TWY K and taxilane Z at the same time.

Code F ACFT are only permitted to taxi behind when code D or smaller ACFT is at the RHP at TWY K1, K2, K3, K4 and K5.

1.6.4. MULTIPLE APRON RAMP SYSTEM (MARS) STANDS

Stand C51L/C51/C51R is a Multiple Apron Ramp System (MARS) stand. The following must be noted as there is a potential for stand signage confusion.

- Stand lead-in line for C51L and C51 starts from TWY K and taxilane Z. Taxiing westbound, C51 lead-in line is beyond the C51L lead-in line.
- Stand lead-in line for C51R originates from taxilane Z1.

1.6.5. JET BLAST

Due to jet blast concerns, flight crew must use minimum power when taxiing in vicinity of apron areas.

1. GENERAL

1.6.6. TURN RESTRICTIONS

Heading South - Right turn onto taxilane Z not available from TWYs K10 and Y.
 Heading East - Left turn onto TWY R not available from TWY N.
 Heading South - Right turn onto TWY N not available from TWY R.
 Heading North - Right turn onto TWY R not available from TWY R1.
 Heading West - Right turn onto taxilane S not available from TWY M.
 Heading West - Left turn onto TWY M not available from taxilane S.
 Heading South - Left turn onto TWY N not available from TWY P8.
 Heading South - Left/Right turns onto taxilane Z not available from TWY W.
 Heading West - Left turns onto TWY K4 not available from TWY Z11.
 Heading South - Left turn onto TWY K not available from TWY K18.
 Heading North - Left turn onto TWY K10 not available from taxilane Z.

1.6.7. TAXI GUIDANCE SYSTEM

ATC will use the phraseology "Follow the greens..." when issuing a clearance to pilots to taxi along the directional guidance provided by the green TWY centerline lights. The controller may use the expression "Follow the greens" in a taxi clearance instead of detailing the route to be followed. The instruction however will always include a clearance limit, e.g. "EMIRATES 12 TAXI TO HOLDING POINT M13A RWY 30R FOLLOW GREENS".

1.6.8. REDUCED ENGINE/SINGLE ENGINE TAXI

Reduced Engine/Single-engine for up to Code C ACFT taxi-in/out allowed.
 If RWY crossing is required, crew are expected to be able to expedite the crossing.
 Pilots must consider the additional thrust required for manoeuvring and the potential for asymmetrical thrust, special attention must be given to ensuring adequate braking capability and maintaining control during turns and while taxiing in adverse weather conditions.

1.7. PARKING INFORMATION

1.7.1. GENERAL

In the event that ACFT comes to a complete halt whilst entering a parking stand or taking a turn towards an adjoining TWY, aircrew must hold position and contact ATC for assistance to ensure the area behind is free from effects of jet blast.

ACFT stands A1, A10, B15 thru B27 (including B18L, B18R, B21L, B21R, B26L and B26R), C25 thru C47, C49 thru C51 (including C51L and C51R), C53 thru C64 (excluding C53L, C53R, C54L, C54R, C55L and C55R), D1 thru D10, F5, F17 and G1 thru G21 have less than 12'/3.75m clearance from the ACFT tail to the apron safety line at the rear of stand.

1.8. WIND SHEAR WARNINGS

1.8.1. WIND SHEAR REPORTS PASSED BY ATC

On receipt of any report of wind shear, ATC will:

- Immediately relay the report to other ACFT potentially affected;
- Pass the full report to the MET Office; and
- Pass the information to other ATC units that may be affected.

Wind shear reports that are relayed by ATC to other ACFT will contain as many of the following details as possible:

- ACFT type that reported the wind shear;
- Description of event (e.g. light/moderate/severe, or positive/negative);
- Height/altitude wind shear encountered;
- Phase of flight;
- RWY;
- Time of encounter;
- MET/operational information as received from the reporting pilot.

1. GENERAL

Examples of the phraseology used by ATC to pass on wind shear reports:

- "CAUTION WIND SHEAR. AT (TIME) (ACFT TYPE) REPORTED STRONG WIND AT (HEIGHT/ALTITUDE) FEET ON APPROACH RWY (DESIGNATOR). MAX THRUST REQUIRED."
- "CAUTION WIND SHEAR. AT (TIME) (ACFT TYPE) REPORTED AFTER DEPARTING RWY (DESIGNATOR) AT (HEIGHT/ALTITUDE) FEET AIRSPEED LOSS OF (NUMBER) KNOTS, STRONG (LEFT/RIGHT) DRIFT."

1.8.2. WIND SHEAR WARNINGS ON ATIS

Wind shear warning issued by the National Centre of Meteorology (NCM) or received from an ACFT will be broadcast on both the departure and arrival ATIS. Regardless of any relevant information being broadcast on the ATIS, during final approach and prior to take-off, ATC will transmit to ACFT without delay:

- The latest information on wind shear in the approach, final approach, take-off and climb out area;
- Any significant variations in the current surface wind, expressed in terms of minimum and maximum values.

1.8.3. PILOT REPORTS OF WIND SHEAR

For the benefit of subsequent ACFT and for validation and further enhancement of the low-level wind shear warning, pilots are requested to inform ATC if they experience any wind shear on arrival or departure, irrespective of whether a warning has been given. ATC will pass reports to following ACFT and the MET Office.

ATC will continue to transmit information on wind shear until it is confirmed, either by three (3) consecutive subsequent ACFT reports or by advice from the MET Office that conditions are no longer a hazard to the operations.

1.8.4. LOW LEVEL WIND SHEAR

Caution, transient and sporadic low level wind shear is possible between 1800-0300UTC on the approach and climb out due to land and sea breeze interaction resulting in possible airspeed loss/gain of 10 KT or more.

1.8.5. 1000' AND BELOW WINDS

If a wind shear warning has been issued, ACFT may be requested by ATC to state the 1000' and below winds when able.

ATC will then subsequently pass this information onto following ACFT whilst the wind shear warning is in force.

1.9. OTHER INFORMATION

Birds.

RWYs 12L and 12R right-hand circuit.

2. ARRIVAL

2.1. SPEED RESTRICTIONS

ATC has zero tolerance with regards to the compliance with speed control instructions. Pilots shall adhere to the speed approved or assigned by ATC and shall request ATC approval before making any changes thereto. When an immediate speed adjustment is required for the safe operation of the flight, ATC shall be notified as soon as possible.

Pilots unable to maintain the last assigned speed during any particular phase of flight, e.g. for ACFT safety or performance reasons, shall inform ATC as soon as possible.

Pilots can expect the following speed control restrictions to be enforced by ATC:

- a) 210 - 250 KT: From CTA entry to downwind;
- b) 180 - 230 KT: From downwind to base leg;
- c) 160 - 210 KT: On base leg and closing heading to final approach;
- d) 160 - 190 KT: 10NM from touchdown;
- e) 160 KT: 4NM from touchdown.

Pilots must advise ATC if a speed adjustment is considered excessive or contrary to ACFT operating specifications.

2. ARRIVAL

2.2. CAT II/III OPERATIONS

All RWYs approved for CAT II/III operations, special aircrew and ACFT certification required.

2.3. RWY OPERATIONS

When on approach to RWY 30R, pilots shall reconfirm DME/GP information and ensure that they have correctly identified the landing RWY. Do not confuse with staggered parallel RWY 30L with THR approximately 1.5NM East of RWY 30R.

2.3.1. RWY OCCUPANCY TIME

Unless otherwise advised by ATC, expect to vacate the RWY via a Rapid Exit TWY.

ATC will advise ACFT on final approach of the expected RWY exit point. This will normally be a Rapid Exit TWY and pilots must advise ATC as soon as practicable if unable to comply.

ACFT are expected to vacate the RWY expeditiously and pilots are reminded to keep moving until the ACFT is completely clear of the RWY stop bars on exiting.

Distance (m) from DTHR to assigned Rapid Exit TWY							
RWY 12L		RWY 12R		RWY 30L		RWY 30R	
Vacate LEFT	Vacate RIGHT	Vacate LEFT	Vacate RIGHT	Vacate LEFT	Vacate RIGHT	Vacate LEFT	Vacate RIGHT
N5A 1825	M7A 1825	M16 2144	K13 2154	K9 2029	M12B 2029	M6 1775	N5 1775
N6 2143	M9 2143	M18 2745	K15 2845	K8 2390	M11 2387	M3A 2351	N3A 2356
N8 2759	M12A 2759	-	-	K6 2881	M8 2746	M3 2745	N3 2745

Notes:

1. ATC will assign a RWY exit point upon first contact with DUBAI Tower.
2. Pilots are expected to vacate the RWY at the assigned exit point.
3. Pilots must advise ATC if unable to comply for performance reasons.
4. During dual RWY 30 operations, all arrivals landing RWY 30L shall vacate LEFT unless otherwise instructed.
5. Pilots shall remain on DUBAI Tower frequency until instructed to change.

2.3.2. REDUCED RWY SEPARATION MINIMA (RRSM)

2.3.2.1. GENERAL

Dubai Intl APT applies special landing procedures over H24 period for RWYs 12L/30R and 12R/30L.

In order that ATC can plan final approach spacing accordingly, inbound arrivals shall advise DUBAI Arrivals on first contact if their airline Standard Operating Procedures prevent them from participating in these procedures.

It is essential that aircrew adhere to paragraph 2.3.1. "RWY Occupancy Time" to ensure the efficiency of operations during RRSM.

OMDB/DXB
DUBAI INTL

JEPPESEN

24 NOV 23

10-1P6

Eff 30 Nov

DUBAI, UAE

AIRPORT BRIEFING

2. ARRIVAL

2.3.2.2. CONDITIONS FOR THE APPLICATION OF RRSM

RRSM may be applied H24 between:

- a departing ACFT and a succeeding landing ACFT using a single RWY; or
- two successive landing ACFT; or
- two successive departing ACFT;

provided:

- Tail wind does not exceed 5 KT, and there are no reports of wind shear.
- Met visibility shall be equal to or greater than 5km, the cloud ceiling shall not be lower than 1000' and the ATC is satisfied that the pilot of the following ACFT will be able to observe the relevant traffic clearly and continuously.
- The pilot of the following ACFT is warned.
- The RWY is dry and there is no evidence that the braking action may be adversely affected.
- The controller is able to assess separation visually or by radar-derived information.
- Wake turbulence separation minima shall be applied.
- Minimum separation continues to exist between two departing ACFT immediately after take-off of the second ACFT.

2.3.2.3. SINGLE RWY MODE PROCEDURE

When the RWY-in-use is temporarily occupied by other traffic, landing clearance may be issued to an arriving ACFT, provided that the controller has reasonable assurance that the following separation distances/criteria will be met when the landing ACFT crosses the RWY THR:

Landing following Landing

- RWY 12L/30R:

The preceding landing ACFT has landed and has vacated the RWY or has passed a point at least 8202'/2500m from the THR of the RWY (abeam TWYs N7 and M10A for RWY12L, abeam the RWY exit points for TWYs N3A and M3A for RWY 30R) and is in motion and will vacate the RWY without stopping and/or backtracking.

Landing RRSM will only be applied between two successive arrivals provided both ACFT have been instructed to vacate at published Rapid Exit TWYs.

- RWY 12R/30L:

The preceding landing ACFT has landed and has passed a point at least 8202'/2500m from THR of the RWY (abeam TWYs M17 and K14 for RWY 12R, abeam the RWY exit points for TWYs M11 and K8 for RWY 30L) and is in motion and will vacate the RWY without stopping and/or backtracking.

Landing RRSM will only be applied between two successive arrivals provided both ACFT have been instructed to vacate at published Rapid Exit TWYs.

Landing following Departure

- RWY 12L/30R:

The preceding departing ACFT will be airborne and has passed a point at least 8202'/2500m from the THR of the RWY (abeam TWYs N7 and M10A for RWY12L, abeam the RWY exit points for TWYs N3A and M3A for RWY 30R), or if not airborne, will be at least 8202'/2500m from THR of the RWY.

- RWY 12R/30L:

The preceding departing ACFT will be airborne and has passed a point at least 8202'/2500m from THR of the RWY (abeam TWYs M17 and K14 for RWY 12R, abeam the RWY exit points for TWYs M11 and K8 for RWY 30L), or if not airborne, will be at least 8202'/2500m from THR of the RWY.

OMDB/DXB
DUBAI INTL

JEPPESEN

24 NOV 23

10-1P7

Eff 30 Nov

DUBAI, UAE

AIRPORT BRIEFING

2. ARRIVAL

2.3.2.4. DUAL DEPENDENT RWY MODE PROCEDURE (BOTH DIRECTIONS)

The procedures described in the previous section for single RWY operations for "Landing following landing" shall be applied in the same manner on respective RWYs during dual RWY operations. The exception for dual RWY operations is when the RWY mode becomes dependent in VMC (when ACFT are departing from full RWY length 12R from TWY K1, K2, M4, M5B; or from full length RWY 30R from TWY M15, M15A, N11 or N12). Therefore the difference from single RWY operations, is in the scenario Landing following Departure. In RWY 12 direction, a preceding ACFT off RWY 12R must have passed abeam TWYs M10B and K7, prior to the landing ACFT crossing the THR of RWY 12L. In RWY 30 direction, a preceding departing ACFT off RWY 30R must have passed abeam TWYs M10A and N7, prior to the landing ACFT crossing the THR of RWY 30L.

2.3.3. VISUAL APPROACH WITH OWN SEPARATION

When visual meteorological conditions exist, visual approach may be requested by arrivals on final approach. When requesting a visual approach, the pilot must be able to report the preceding ACFT in sight and accept to maintain own separation from that ACFT.

ATC may initiate a visual approach, provided that the pilot concurs, has the preceding ACFT in sight and accepts to maintain own separation from that ACFT. Whenever deemed necessary, ATC will issue a caution of possible wake turbulence.

Pilot request or acceptance of a visual approach means the pilot can maintain visual reference to the terrain and accepts responsibility for establishing a safe landing interval behind preceding ACFT as well as responsibility for wake turbulence avoidance.

It is pilot's responsibility to inform ATC if they are operating their ACFT other than in a normal manner.

2.4. TRANSPONDER OPERATION

Transponder shall remain switched on and transmit last assigned code until parked on stand.

2.5. OTHER

Pilots commencing a descent in accordance with ATC instruction shall immediately advise ATC if their rate of descent during level change will be less than 500' per minute.

Coordinated Arrival Slot Time

Due to capacity constraints from 0000-0259UTC and 1800-2200UTC, airlines and flight crews shall arrange their flights to arrive at their coordinated slot time (STA). This time should be planned using a nominal holding time of 8 minutes.

Caution: Possible signal fluctuation during ILS GP CAT I conditions for arrival ACFT due to taxiing, towing and departing ACFT. Pilots should anticipate possible GP interference and monitor ILS profile, FLT display indications and autopilot behavior during manual or coupled ILS APCH.

3. DEPARTURE

3.1. SPEED RESTRICTIONS

ATC has zero tolerance with regards to the compliance with speed control instructions. Pilots shall adhere to the speed approved or assigned by ATC and shall request ATC approval before making any changes thereto. When an immediate speed adjustment is required for the safe operation of the flight, ATC shall be notified as soon as possible.

Pilots unable to maintain the last assigned speed during any particular phase of flight, e.g. for ACFT safety or performance reasons, shall inform ATC as soon as possible.

3.2. START-UP, PUSH-BACK AND TAXI PROCEDURES

3.2.1. START-UP PROCEDURES

Departing ACFT shall pass the following information to DUBAI Delivery on request for start-up:

ACFT callsign, ACFT type, parking stand, destination, advise if unable to comply with SID minimum climb gradient and/or speed restriction.

Engine runs on stands are permitted at IDLE only and typically MAX 5 minutes only. If engine runs on stands (in IDLE power) are required for more than 5 minutes (including for cabin cooling purposes where all engines may be operated), this must be explicitly requested by the Airline Engineering.

High power engine runs are permitted at predesignated areas. Prior approval is required for both IDLE and high power engine runs. Request shall be made to Dubai Airports Aerodrome Operations. Engine runs on stand above IDLE is prohibited.

Requests shall be made at least 30 minutes prior to start-up.

ACFT will normally be expected to start-up during push-back. ACFT wishing to start engines either before or after push-back should notify ATC.

ACFT requiring a start on stand may only start 50% of their total engines on stand. The remaining engine(s) are only to be started once the push-back has been completed, ACFT is on the TWY centerline and parking brakes applied.

3.2.2. PUSH-BACK PROCEDURES

PUSH-BACK ATC INSTRUCTION AND ASSOCIATED STOP POSITIONS

STANDARD PUSH: Push abeam adjacent stand or up to one stand distance.

Example of ATC phraseology: "Push-back approved, face (direction)." No reference to "STANDARD" or a stop position will be included in ATC clearance. Ground crew will know where to stop.

SHORT PUSH: Push and pull abeam the departure stand.

Example of ATC phraseology: "Short push-back approved, face (direction)." No reference to stop position will be included in ATC clearance. Ground crew will know where to stop.

Short push is in fact a push and pull on the TWY and does not involve the traditional "S" like or dog-leg maneuver which is initiated inside the stand before entering the TWY. The "S" like maneuver inside the stand is prohibited.

LONG PUSH: Push up to two stand distance.

Example of ATC phraseology: "Long push approved, face (direction)." No reference to stop position will be included in ATC clearance. Ground crew will know where to stop.

PUSH AND PULL: Push and pull abeam the stand in front.

Example of ATC phraseology: "Push-back and pull forward approved, face (direction)." No reference to stop position will be included in ATC clearance. Ground crew will know where to stop.

Deviations to the above have been published in Dubai APTs' Airside Operating Regulation (AOR).

Where a pull forward maneuver is involved, consider starting ACFT engines only after completing the pull forward maneuver to minimize forward stress on the push-back tractor during the pull.

3. DEPARTURE

SIMULTANEOUS PUSH OF MULTIPLE ACFT IN CLOSE VICINITY

For simultaneous push from adjacent stands or alternate stands with one stand in between:

- ATC will alert the crew of all involved ACFT about the simultaneous push;
- ATC will provide a combination of different push-back instructions (Standard, Long etc.) such that there is a separation of about two (2) stands between the ACFT in the final stop positions on the TWY.

ACFT are required to switch on transponders when commencing push-back. ACFT not requiring push-back shall switch on transponders prior to commencing taxiing.

If no push-back is required due to ACFT facing nose out, this must be notified to DUBAI Delivery on first contact.

Dubai National Air Travel Agency, Jet Aviation and certain operating companies with own trained drivers are the only approved agencies for executing push-backs.

Their procedures are mandatory. However, it is the pilot's responsibility, to obtain push-back approval from ATC and relay the same to their ground engineer prior to commencing push-back.

Push-back approval includes instructions to face North, East, South or West as appropriate.

PUSH-BACK RESTRICTIONS

Push-back onto taxilane J and taxilane U:

- Code F will push back onto taxilane J and code E will push back onto taxilane U. Note that taxilane U is code E compatible and taxilane J is code F compatible.
- Due to proximity of taxilane J and taxilane U (south of B stands), pilots on taxilane J and taxilane U must adhere to centerline at all times and must confirm ACFT aligned on centerline prior to reporting push-back complete.
- Due to code F push-back onto taxilane J, a code E on taxilane U in the vicinity of the pushing code F shall keep clear and hold position until the code F pilot reports to ATC that the push-back is complete on taxilane J. Follow ATC instructions at all times.
- Code E ACFT on taxilane U shall not pass code F ACFT during push-back onto taxilane J.

ACFT are permitted to push back and start up on the push or to start one engine on stand at idle power before push-back.

In the event of simultaneous push-back from adjacent stands, ground crew may ask to delay the engine start until the ground crew on the ACFT behind is clear of the forward ACFT's jet blast zone.

Under normal circumstances push-backs onto the outer TWYs are not permitted. Exceptions to this are B stands servicing A380 or WIP restrictions.

3.2.3. TAXI PROCEDURES

ACFT taxiing via TWYs K16 and K17 for departure RWY 30L shall use minimum power due to proximity of apron H.

A380 Acft from B stands, except B27, shall push onto the outer taxilane J.

After disconnecting, push-back tug will hold on taxilane J centerline in view of the pushed ACFT until completion of engine start. Once cleared by ATC, the tug will cross taxilane U to return to the stand on the North. Pushed ACFT to initiate taxi only after the tug has vacated taxilane J. ACFT taxiing on taxilane U to exercise caution due to crossing tugs.

"HOLD SHORT" instruction expectation is when ATC issues instruction to "hold short of stand" to accommodate incoming traffic, the ACFT must stop its nose landing gear on the centerline of the adjacent stand, thus ensuring adequate clearance between the ACFT and the designated stand.

OMDB/DXB
DUBAI INTL

JEPPESEN

24 NOV 23

10-1P10

Eff 30 Nov

DUBAI, UAE

AIRPORT BRIEFING

3. DEPARTURE

3.3. RWY OPERATIONS

3.3.1. REDUCED RWY SEPARATION MINIMA (RRSM)

3.3.1.1. GENERAL

Special departing procedures may be utilized at Dubai Intl APT for RWY 12L/30R and 12R/30L.

3.3.1.2. SINGLE RWY MODE PROCEDURE

Take-off clearance may be issued to a departing ACFT, commencing its take-off roll from full length, before the preceding departure has passed the upwind end of the RWY, provided:

- **RWY 12L/30R:**

The preceding ACFT is airborne and has passed a point at least 8202'/2500m from the THR of the RWY (abeam TWYs N7 and M10A for RWY 12L, abeam the RWY exit points for TWYs N3A and M3A for RWY 30R), and minimum separation continues to exist, constant or increasing, between the two departing ACFT immediately after take-off of the second ACFT.

- **RWY 12R/30L:**

The preceding ACFT is airborne and has passed a point at least 8202'/2500m from THR of the RWY (abeam TWYs M17 and K14 for RWY 12R, abeam the RWY exit points for TWYs M11 and K8 for RWY 30L), and minimum separation continues to exist, constant or increasing, between the two departing ACFT immediately after take-off of the second ACFT.

Due to displaced THRs, the succeeding departure may commence its take-off roll subject to the same provisions above when departing off

- RWY 12R from M4 to M7B or K1 to K4;
- RWY 30L from K17, K18 to M20, M21;
- RWY 12L from M1 to M1B or N1 to N1B;
- RWY 30R from M15 to M15A or N11 to N12.

3.3.1.3. DUAL DEPENDENT RWY MODE PROCEDURE (BOTH DIRECTIONS)

The procedures described in the previous section for single RWY operations shall be applied in the same manner on respective RWYs during dual RWY operations.

3.3.2. RWY OCCUPANCY TIME

eWTS time based wake turbulence separation will be applied.

On receipt of the line-up clearance, ACFT shall taxi into position expeditiously.

If pilots require more separation than the eWTS time-based standard, or extra time for any other reason, advise ATC early prior to entering the RWY, not when on the RWY. When informed, ATC may be able to make changes in the departure sequence, if necessary, to minimize delays to other succeeding departures.

Cockpit checks shall be complete prior to line-up.

Once ATC issues a take-off clearance, if there is any unreasonable delay in the ACFT commencing the take-off roll, ATC may cancel the take-off clearance and reposition the ACFT in the departure sequence. When cleared for take-off, ATC will expect and will have planned on seeing movement within 8 to 10 seconds of the take-off clearance being issued.

ACFT that cannot comply with these requirements are to notify ATC as soon as possible.

OMDB/DXB
DUBAI INTL

 **JEPPESEN**
5 JUN 20 **10-2**

DUBAI, UAE
RNAV STAR

RNAV STAR INSTRUCTIONS

Pilots are required to strictly follow ATC advised STAR clearance and ensure correct readback of STAR clearance at all times.

Unless explicitly cancelled or amended by ATC, the pilot must follow the vertical and lateral profile of the STAR and comply with any published speed restrictions.

The use of a STAR designator without a cleared level does not authorise the pilot to descend on the STAR vertical profile.

A level restriction depicted on a STAR chart does not authorise a pilot to descend to meet that restriction. ATC will issue descent clearance to permit compliance with vertical navigation restrictions. Pilots must inform ATC if a level restriction cannot be met. Do not descend below ATC cleared level.

Flight crews are expected to strictly adhere to STAR speed restrictions unless otherwise approved or instructed by ATC.

JEPPESEN
18 JUL 25 (10-2A)
DUBAI, UAE
RNAV STAR

OMDB/DXB
DUBAI INTL

Alt Set: hPa Trans level: FL150

RNAV 1 (GNSS) required

D-ATIS

126.275

1. On initial contact with DUBAI ARRIVALS state passing level and ACFT type, including series.

2. Advise DUBAI ARRIVALS when full RWY length is required.

3. Do not descend below ATC cleared level.

4. When changing from DUBAI ARRIVALS to DUBAI DIRECTOR, state only: DUBAI DIRECTOR, [aircraft call sign] unless otherwise instructed.

5. Execute all turns at a bank angle of 25° or at a rate of 3° per second, unless otherwise instructed by ATC.

6. ATC instructions must be followed IMMEDIATELY.

Apt Elev

62

DATOB 1E [DATO1E]
BY ATC

IMPED 3B [IMPE3B], IMPED 3E [IMPE3E]
LORID 1E [LORI1E], PUVAL 5B [PUVA5B]
PUVAL 2E [PUVA2E], VUTEB 3B [VUTE3B]
VUTEB 3E [VUTE3E]
RNAV ARRIVALS
(RWYS 12L/R)

IMPED

MAX 230 KT
(MHA 10000)
MAX 240 KT
(MHA FL150)
MAX FL250

ITLAP

MAX 230 KT
(MHA 10000)
MAX 240 KT
(MHA FL150)
MAX FL180

VUTEB

MAX 230 KT
(MHA 10000)
MAX 240 KT
(MHA FL150)
MAX FL250

En-route holding at VUTEB, IMPED and ITLAP - aircraft might be directed to a different hold and re-assigned to a different STAR subject to the tactical operational situation.

© JEPPESEN, 2017, 2025. ALL RIGHTS RESERVED.

CHANGES: Chart resized, procedures transferred, en-route holdings and note established.

OMDB/DXB
DUBAI INTL

 **JEPPESEN**
15 MAY 20 **10-3** **Eff 21 May**

DUBAI, UAE
DEPARTURE

SID INSTRUCTIONS

Unless explicitly cancelled or amended by ATC, the pilot must follow the vertical and lateral profile of the SID and comply with any published speed restrictions.

A level restriction depicted on a SID chart does not authorise a pilot to climb to meet that restriction. ATC will issue climb clearance to permit compliance with vertical navigation restrictions. Pilots must inform ATC if a level restriction cannot be met. Do not climb above ATC cleared level.

When conducting a SID, the priority is to meet the vertical navigation restrictions of the SID. When speed restrictions do not enable the aircraft to meet a SID level restriction, the pilot must advise ATC of any speed deviation requirement prior to departure or as soon as the situation is identified. Pilots must advise ATC when able to resume the SID speed restrictions.

Operators or pilots should establish procedures to ensure compliance with the SID. The application of a performance margin on the published climb requirements is at the operator's/pilot's discretion taking into account the achievable climb performance of the aircraft and the means of monitoring the gradient achieved.


Flight crews are expected to strictly adhere to SID speed restrictions unless otherwise approved or instructed by ATC.

Pilots must advise ATC if a speed adjustment is considered excessive or contrary to ACFT operating specifications.

OMDB/DXB
DUBAI INTL

JEPPESSEN
19 SEP 25 10-3B Eff 2 Oct


DUBAI, UAE
RNAV SID



OMDB/DXB
DUBAI INTL

JEPPESSEN
19 SEP 25 10-3C Eff 2 Oct

DUBAI, UAE
RNAV SID




CHANGES: Close- in obstacle note established.

© JEPPESSEN, 2017, 2025. ALL RIGHTS RESERVED.

OMDB/DXB
DUBAI INTL

JEPPESSEN
19 SEP 25 10-3D Eff 2 Oct


DUBAI, UAE
RNAV SID



OMDB/DXB
DUBAI INTL

JEPPESSEN
19 SEP 25 10-3E Eff 2 Oct

DUBAI, UAE
RNAV SID




CHANGES: Close-in obstacle note & climb gradient established.

© JEPPESSEN, 2017, 2025. ALL RIGHTS RESERVED.

OMDB/DXB
DUBAI INTL

JEPPESSEN
19 SEP 25 10-3F Eff 2 Oct

DUBAI, UAE
RNAV SID



CHANGES: Climb gradients established.


© JEPPESSEN, 2017, 2025. ALL RIGHTS RESERVED.



OMDB/DXB
DUBAI INTL

JEPPESSEN
19 SEP 25 10-3J Eff 2 Oct

DUBAI, UAE
DEPARTURE



TEMPORARY CLOSURE OF TAXIWAYS (AIP SUP 40/25)

REFER ALSO TO LATEST NOTAMS

Work is planned in various phases as indicated below.

Note: The work/closure phases listed below are not in any particular order.

AREA C02

- a. Section of taxilane Z between taxiway Z5 and taxiway Y closed.
- b. Sections of taxilane J1 and taxiway Y North of taxilane Z closed.
- c. Taxiway Z5 closed.
- d. Taxiway Y East link onto taxilane Z/taxiway L4 temporarily relocated to the East. Taxiway centreline installed with green reflectors instead of centreline lights.
- e. Section of taxilane U behind stands B1 thru B3 diverted with temporary centreline installed with green reflectors instead of centreline lights.
- f. Temporary crossover taxiway U2A implemented between taxilane J and taxilane U West of stand B3. Taxiway centreline installed with green reflectors instead of centreline lights.
- g. Aforementioned temporary taxiway centrelines will be available for unrestricted movements up to Code F. In CAT II/III conditions, movements will be allowed under "Follow-me" guidance as advised by ATC.
- h. Code F movement permitted on taxilane Y and the section of taxilane U West of temporary crossover taxiway U2A.
- i. Code F aircraft are not permitted on taxilane J1 and taxilane Y at the same time.
- j. Intermediate Holding Position (IHP) UA not available in CAT II/III conditions.
- k. IHP YA is available but has no sign, marking is available.
- l. Aircraft turning/moving on taxiway Y1:
 1. Must use minimum power to prevent jet blast onto the stands behind.
 2. Must continue movement under constant power setting without coming to a full stop.
 3. If the aircraft has to stop for any reason on taxiway Y1, report to ATC for Airside assistance to assess jet blast impact before re-commencing movement.


AREA J1

- a. Section of taxilane J between stands C63 and stand B3 closed.
- b. Section of taxilane U behind stands B1 thru B3 diverted with temporary centreline installed with green reflectors instead of centreline lights.
- c. Temporary crossover taxiway U2A implemented between taxilane J and taxilane U West of stand B3. Taxiway centreline installed with green reflectors instead of centreline lights.
- d. Aforementioned temporary taxiway centrelines will be available for unrestricted movements up to Code F. In CAT II/III conditions, movements will be allowed under "Follow-me" guidance as advised by ATC.
- e. Code F movement permitted on taxilane Y and the section of taxilane U West of temporary crossover taxiway U2A.
- f. Code F aircraft are not permitted on taxilane J1 and taxilane Y at the same time.
- g. Aircraft turning/moving on taxiway Y1:
 1. Must use minimum power to prevent jet blast onto the stands behind.
 2. Must continue movement under constant power setting without coming to a full stop.
 3. If the aircraft has to stop for any reason on taxiway Y1, report to ATC for Airside assistance to assess jet blast impact before re-commencing movement.
- h. Taxiway crossing road may be maintained through the worksite.

AREA B17

- a. Section of taxilane U behind stand B17 closed.
- b. Taxiway U3 closed.

Data Comm ACATS: D-ATIS	DUBAI Comm DCL	DUBAI Delivery 120.350	DUBAI Ground GMC-2 121.650	Tower North 118.350	Tower South 119.550	DUBAI Departures	
						North 124.675	South 121.025
131.7							



INCURSION HOT SPOTS

(For information only, not to be construed as ATC instructions.)

HS1

Misroute Hotspot: Potential to proceed onto RWY holding position M2 from TWY L3.

HS2

Pilots to ensure ATC clearance to cross RWY at RWY holding position K11.

HS3

Pilots to ensure ATC clearance to enter/cross RWY at RWY holding position N2.

HS4

Misroute Hotspot: Pilots to ensure ATC clearance to use TWY crossover Z2.

HS5

Misroute Hotspot: Pilots to ensure ATC clearance to use TWY crossover Z4.

HS6

Premature turn from TWY K (Westbound) onto TXL Y (taxilane) instead of TXL J1.

HS7

Misroute Hotspot: Potential to miss TWY crossover Z6 and proceed Westbound on TWY K.

HS8

Misroute Hotspot: Potential to miss TWY crossover Z8 and proceed Westbound on TWY K.

HS9

Misroute Hotspot intersection. Potential to wrongly turn onto TWY K, TXL J2, TXL W or TXL Z.

HS10

Potential to not hold at intermediate holding position KP when instructed.

ADDITIONAL RUNWAY INFORMATION

USABLE LENGTHS

LANDING BEYOND

THRESHOLD

GLIDE SLOPE

TAKE-OFF

WIDTH

RWY	HIRL (60m) CL (15m)	1	HIALS-II SFL TDZ	OFZ	RVR	11,811' 3600m	11,766' 3586m	197'
12L	REIL HSTIL PAPI (angle 3.0°)					13,123' 4000m	12,197' 3718m	60m
30R								

length 900m

TAKE-OFF RUN AVAILABLE

RWY 30R:

From twy head

14,108' (4300m)

twy M15/N11 int

13,698' (4175m)

twy M14A int

13,291' (4051m)

twy N10 int

13,284' (4049m)

twy M13A/N9 int

12,972' (3954m)

twy M13/N8A int

12,648' (3855m)

twy M10A int

9974' (3040m)

twy N7 int

9967' (3038m)

Intersection departures via Rapid Exit Taxiways (RETs) are not permitted.

Twy M15A/Twy N12 entry points. Departure from twy M15A /N12 int or from the twy M15/N11 intersection may be subject to add delay and must be requested from Clearance Delivery prior to taxi.

Primary entry point.

12R

HIRL (60m) CL (15m)

1

HIALS-II SFL TDZ

OFZ

RVR

11,811' 3600m

10,839' 3304m

197'

30L

REIL HSTIL PAPI (angle 3.0°)

14,157' 4315m

13,063' 3982m

60m

TAKE-OFF RUN AVAILABLE

RWY 30L:

From twy head

14,590' (4447m)

twy K16/M19 int

14,272' (4350m)

twy K15A int

13,950' (4250m)

twy M18A int

13,947' (4251m)

twy K14 int

10,915' (3327m)

twy M17 int

10,912' (3326m)

twy K12/M15B int

8996' (2742m)

twy M14B int

8153' (2485m)

twy K11 int

8120' (2475m)

twy M13B int

7835' (2388m)

twy K10 int

7799' (2377m)

Twy K17/M20 int. ACFT entering RWY 30L from twy K18/M21 int must taxi forward to the twy K17/M20 int position before commencing take-off run.

Std/State

TAKE-OFF

Low Visibility Take-off

RL & CL relevant RVR

RL & CL

RL or CLM

RL or CL

RL or CLM

RL or CL

Adequate Vis Ref


2	HIRL & CL (spacing 15m or less) & relevant RVR	RL & CL relevant RVR	RL & CL	RL or CLM	RL or CL	RL or CLM	RL or CL	Adequate Vis Ref
TDZ	R125m	TDZ	R150m	TDZ	R200m	TDZ	R300m	R/V400m
Mid	R125m	Mid	R150m	Mid	R150m	Mid	R150m	R/V500m
Rollout	R125m	Rollout	R150m	Rollout	R150m	Rollout	R150m	NA

1

For low visibility departures all RVR transmissometers of departure RWY shall be serviceable. If reported meteorological VIS more than 150m TDZ RVR not required.

2

R75m with approved lateral guidance system or HUD/HUDLS.



OMDB/DXB

 JEPPesen

DUBAI, UAE

17 JAN 25

10-9D

Eff 23 Jan

DUBAI INTL

INS COORDINATES					
STAND No.	COORDINATES	ELEV	STAND No.	COORDINATES	ELEV
APRON A					
A1, A2	N25 14.7 E055 22.2	13	C50	N25 15.6 E055 20.5	7
A3	N25 14.7 E055 22.2	15	C51 thru C51R	N25 15.6 E055 20.5	5
A4	N25 14.7 E055 22.3	15	C52	N25 15.6 E055 20.5	6
A5	N25 14.6 E055 22.3	15	C53	N25 15.6 E055 20.6	6
A6, A7	N25 14.6 E055 22.4	15	C53L	N25 15.6 E055 20.6	5
A8	N25 14.6 E055 22.5	15	C53R	N25 15.6 E055 20.5	6
A9, A10	N25 14.5 E055 22.5	15	C54	N25 15.6 E055 20.6	6
APRON B			C54L	N25 15.6 E055 20.6	5
B1	N25 15.2 E055 21.0	8	C54R	N25 15.6 E055 20.6	6
B2 thru B4	N25 15.2 E055 21.1	8	C55	N25 15.5 E055 20.6	6
B5	N25 15.2 E055 21.2	8	C55L	N25 15.5 E055 20.7	5
B6	N25 15.1 E055 21.2	8	C55R	N25 15.5 E055 20.6	6
B8	N25 15.1 E055 21.3	8	C56	N25 15.5 E055 20.7	6
B9, B10	N25 15.1 E055 21.3	7	C57	N25 15.5 E055 20.7	5
B11, B12	N25 15.0 E055 21.4	7	C58	N25 15.5 E055 20.8	5
B14	N25 15.0 E055 21.5	7	C59	N25 15.4 E055 20.8	5
B15	N25 15.0 E055 21.5	9	C60	N25 15.4 E055 20.8	5
B16	N25 14.9 E055 21.5	12	C61	N25 15.4 E055 20.9	5
B17 thru B18R	N25 14.9 E055 21.6	13	C62	N25 15.4 E055 20.9	6
B20	N25 14.9 E055 21.7	13	C63	N25 15.4 E055 20.8	7
B21L/R	N25 14.8 E055 21.7	13	C64	N25 15.3 E055 20.8	6
B22, B23	N25 14.8 E055 21.8	13	APRON D		
B24	N25 14.8 E055 21.9	13	D1	N25 14.7 E055 22.1	14
B25 thru B26R	N25 14.7 E055 21.9	13	D2, D3	N25 14.6 E055 22.2	15
B27	N25 14.8 E055 22.0	13	D4, D5	N25 14.6 E055 22.3	15
APRON C			D6, D7	N25 14.5 E055 22.4	15
C18	N25 16.0 E055 20.5	8	D8 thru D10	N25 14.5 E055 22.5	15
C19	N25 16.0 E055 20.5	9	APRON E		
C20	N25 16.0 E055 20.6	9	E1, E2	N25 16.1 E055 21.1	9
C21	N25 16.0 E055 20.6	8	E3	N25 16.1 E055 21.2	10
C22, C23	N25 16.0 E055 20.6	7	E4, E5	N25 16.0 E055 21.2	10
C24	N25 15.9 E055 20.5	10	E6	N25 16.0 E055 21.3	10
C25	N25 15.9 E055 20.5	8	E7L/R, E8	N25 16.0 E055 21.3	11
C26, C27	N25 15.9 E055 20.6	7	E9L thru E10R	N25 15.9 E055 21.4	11
C28, C29	N25 15.8 E055 20.7	7	E11L thru E12R	N25 15.9 E055 21.5	11
C30	N25 15.7 E055 20.7	7	E13	N25 15.8 E055 21.5	11
C31	N25 15.9 E055 20.4	8	E14	N25 15.8 E055 21.6	11
C32	N25 15.9 E055 20.4	10	E15	N25 15.8 E055 21.6	12
C33	N25 15.9 E055 20.5	9	E16, E17	N25 15.8 E055 21.7	12
C34	N25 15.9 E055 20.5	7	E18	N25 15.7 E055 21.7	12
C35	N25 15.9 E055 20.6	7	E19, E20	N25 15.7 E055 21.8	12
C36, C37	N25 15.8 E055 20.6	7	E21	N25 15.7 E055 21.9	12
C38	N25 15.8 E055 20.7	7	E22	N25 15.6 E055 21.9	12
C39, C40	N25 15.7 E055 20.7	7	E23	N25 15.6 E055 21.9	13
C41	N25 15.8 E055 20.3	9	E24	N25 15.6 E055 22.0	12
C42	N25 15.8 E055 20.4	9	E25	N25 15.6 E055 22.0	11
C43, C44	N25 15.8 E055 20.4	7	E26	N25 15.6 E055 22.1	12
C45, C46	N25 15.7 E055 20.4	8	E27 thru E28R	N25 15.5 E055 22.1	13
C47	N25 15.7 E055 20.3	9	E29	N25 15.5 E055 22.2	13
C48	N25 15.5 E055 20.4	8	E43	N25 15.3 E055 22.6	22
C49	N25 15.6 E055 20.4	7	E44 thru E44R	N25 15.4 E055 22.4	17
			E45	N25 15.3 E055 22.5	20
			E45L	N25 15.3 E055 22.5	19

CHANGES: Stands E30 thru E37 coords withdrawn.

© JEPPesen, 2014, 2025. ALL RIGHTS RESERVED.

OMDB/DXB

 JEPPesen

17 JAN 25

10-9E

Eff 23 Jan

DUBAI, UAE


DUBAI INTL


INS COORDINATES					
STAND No.	COORDINATES	ELEV	STAND No.	COORDINATES	ELEV
APRON E (CONTD)					
E45R	N25 15.3 E055 22.5	20	Q6	N25 15.5 E055 22.6	15
			Q7	N25 15.4 E055 22.6	16
APRON F			Q8	N25 15.4 E055 22.5	17
F2, F3	N25 15.3 E055 21.0	8	Q9, Q10	N25 15.4 E055 22.5	18
F4, F5	N25 15.3 E055 21.1	8	Q11	N25 15.4 E055 22.5	19
F6 thru F8	N25 15.2 E055 21.2	8	APRON S		
F9, F10	N25 15.2 E055 21.3	8	S1	N25 14.4 E055 23.9	33
F12, F13	N25 15.1 E055 21.4	8	S2	N25 14.3 E055 24.0	34
F16	N25 15.0 E055 21.5	8	S3	N25 14.3 E055 24.0	35
F17	N25 15.0 E055 21.6	11	S4	N25 14.4 E055 24.0	32
F18	N25 15.0 E055 21.6	13	S5	N25 14.3 E055 24.1	34
F19	N25 15.0 E055 21.7	13	S6	N25 14.2 E055 24.1	36
F20	N25 14.9 E055 21.7	13	S7	N25 14.2 E055 24.1	39
F21, F22	N25 14.9 E055 21.8	13	S8	N25 14.2 E055 23.9	38
F23	N25 14.9 E055 21.9	13	S9	N25 14.2 E055 23.9	36
F24, F25	N25 14.8 E055 21.9	13	S10	N25 14.3 E055 23.8	34
F26L	N25 14.8 E055 22.0	12	S11	N25 14.3 E055 23.8	33
F26R, F27	N25 14.8 E055 22.0	13	S12	N25 14.3 E055 23.7	33
APRON G			S13	N25 14.3 E055 23.7	32
G1	N25 14.5 E055 22.7	27	S14	N25 14.3 E055 23.7	33
G2	N25 14.4 E055 22.7	28	S15	N25 14.4 E055 23.6	34
G3	N25 14.4 E055 22.7	29			
G4	N25 14.4 E055 22.7	31			
G5	N25 14.4 E055 22.7	33			
G6	N25 14.3 E055 22.8	36			
G7	N25 14.3 E055 22.8	34			
G8	N25 14.3 E055 22.8	32			
G9	N25 14.4 E055 22.8	31			
G10	N25 14.3 E055 22.9	31			
G11	N25 14.3 E055 22.9	32			
G12	N25 14.3 E055 22.9	33			
G13	N25 14.3 E055 23.0	34			
G14	N25 14.3 E055 23.0	35			
G15	N25 14.2 E055 23.0	36			
G16	N25 14.2 E055 22.9	39			
G17	N25 14.1 E055 23.0	41			
G18	N25 14.1 E055 23.1	39			
G19	N25 14.2 E055 23.1	37			
G20	N25 14.2 E055 23.1	35			
G21	N25 14.2 E055 23.1	33			
G22	N25 14.1 E055 23.3	50			
APRON H					
H1	N25 14.1 E055 23.3	51			
H2	N25 14.1 E055 23.4	51			
H3	N25 14.0 E055 23.6	51			
H4	N25 13.9 E055 23.8	52			
APRON Q					
Q1	N25 15.4 E055 22.4	17			
Q2	N25 15.4 E055 22.4	16			
Q3	N25 15.5 E055 22.5	15			
Q4	N25 15.5 E055 22.5	14			
Q5	N25 15.5 E055 22.5	13			

CHANGES: Stand E38 coords withdrawn.


© JEPPesen, 2014, 2025. ALL RIGHTS RESERVED.

D-ATIS Departure	D-ATIS Departure ACARS: DCL	Data Comm	DUBAI Delivery	DUBAI Ground	Tower	DUBAI Departures
131.7			120.350	GMC-2 121.650 GMC-1 118.350	North 118.750 South 119.550	North 124.675 South 121.025






D-ATIS Departure	Data Comm ACARS: D-ATIS DCL	DUBAI Delivery	DUBAI Ground		Tower		DUBAI Departures	
			GMC-2	GMC-1	North	South	North	South
131.7		120.350	121.650	118.350	118.750	119.550	124.675	121.025



D-ATIS Departure	Data Comm ACARS: D-ATIS DCL	DUBAI Delivery	DUBAI Ground		Tower		DUBAI Departures	
			GMC-2	GMC-1	North	South	North	South
131.7		120.350	121.650	118.350	118.750	119.550	124.675	121.025



CHANGES: Twvs M9 & N3 shape.

VISUAL DOCKING GUIDANCE SYSTEMS (VDGS)

1. INTRODUCTION

Parking stands are equipped with visual docking guidance system (VDGS) and hence no wing walkers/marshaller is available on the stand. If VDGS is faulty/not available, marshaling assistance would be arranged on the stand.

A pilot must inform ATC immediately, and not enter the stand if:

- Unsure of VDGS information;
- VDGS is not activated (missing vertical floating arrows);
- VDGS fails; and
- VDGS displays different ACFT type.

Upon entering the stand, the pilot must hold position and inform ATC if:

- There is a VDGS failure; or
- The ACFT has not stopped at the designated stop position.

The VDGS system is installed for the lead-in line of all stands. It displays to pilots on a large LED Board, azimuth and 'distance-to-go' information.

Pilots should follow the lead-in ground marking to initiate the turn from taxilane into the stand. The VDGS unit will be set to capture mode prior to the ACFT arrival. The capture mode will display on LED Board the ACFT type with vertical floating arrows.

In case, the vertical floating arrows are not displayed, pilot should not enter the stand and report to ATC that VDGS is not activated.

Before turning onto the stand, check if ACFT type displayed in the VDGS is correct.

Once the VDGS captures the ACFT, the display will change to tracking mode showing the relative position of the ACFT from the lead-in line (T). A flashing red arrow on the board indicates the direction of turn to align the ACFT nose-wheel with the lead-in line of the stand.

The VDGS will display the final closing rate information in meters, which is shown 66'/20m from the STOP position and rows of light gets extinguished from 39'/12m. The closing rate is also shown graphically by gradual shortening of the (T) symbol. Slow down the ACFT speed to halt at the STOP position.

Note: Pilot must not proceed unless the vertical floating arrows have been superseded by the closing rate bar.

When the ACFT nose-wheel reaches the correct STOP position, 'distance-to-go' reading reaches zero and the 'STOP' signal and red lights are displayed on the board to halt the ACFT from any further movement.

The 'STOP' will change to an 'OK' signal on the Board to indicate the ACFT is correctly parked. If the ACFT has overshoot the STOP position, 'TOO FAR' signal will be displayed on the Board.

The VDGS should be approached at a speed less than 2 KT.

Notes:


- Pilots must not enter an ACFT stand unless the VDGS is illuminated or a marshaller has signalled clearance to proceed.
- Pilots must not attempt to self-park if the VDGS is not illuminated or calibrated for their ACFT type.
- VDGS units used at OMDB will not operate effectively below CAT III conditions (visibility down to 175m), if VDGS unit is not illuminated or failing to capture ACFT, Pilots must stop and request marshaling assistance from ATC.

VISUAL DOCKING GUIDANCE SYSTEMS (VDGS) (contd)

2. LED Board Display - When VDGS is functioning optimally

2.1. NOT SCHEDULED AND NOT ACTIVATED

- If only stand number is shown, it means VDGS is not activated.
- ACFT should not enter stand.



2.2. SCHEDULED BUT NOT ACTIVATED

- The ACFT is allocated to the stand and hence call sign and EIBT with countdown timer appears on the VDGS.
- However VDGS is not yet activated, as vertical floating arrows are missing.
- Report to ATC, if VDGS not activated.
- Wait for the vertical floating arrows to enter the stand.




2.3. CAPTURE

- The vertical floating arrows indicate that the system is activated and is in Capture mode and searching for an approaching ACFT.
- Pilots shall check that the correct ACFT type is displayed.
- Pilot must not proceed beyond the boarding bridge unless the vertical floating arrows are superseded by yellow Closing Rate Bar.




2.4. TRACKING

- When the ACFT has been caught by the laser, the vertical floating arrow is replaced by the yellow Closing Rate Bar.
- If a flashing red indicator is displayed, then this is indicating the direction of turn required to be taken to align onto the lead-in line.



2.5. CLOSING RATE (DIGITAL)

This is the digital count down from a specific distance to the final stop position.



3. LED Board Display - Examples of VDGS Failures


3.1. OVERSHOOT

If the ACFT has overshoot the stop-position, 'TOO FAR' will be displayed.



3.2. STOP SHORT

If the ACFT is found standing still but has not reached the intended stop position, the message 'STOP, OK' will be shown after a pre-configured time.




3.3. AIRCRAFT VERIFICATION FAILURE

During entry into the Stand, the ACFT geometry is being checked. If, for any reason, ACFT verification is not made 39'/12m before the stop-position, the display will first show 'WAIT' and make a second verification check. If this fails, 'STOP' and 'ID FAIL' will be displayed.



3.4. GATE BLOCKED


If an object is found blocking the approach to gate/apron view from the Safedock to the planned stop position for the ACFT, the docking procedure will be halted with a 'WAIT' and 'GATE BLOCK' message.





OMDB/DXB
DUBAI INTL

JEPPESSEN
11 APR 25
Eff 17 Apr 11-1A

DUBAI, UAE
CAT II/III ILS Rwy 12L

D-ATIS Arrival	MINHAD Approach	DUBAI Arrivals	DUBAI Director	DUBAI Tower		Ground
126.275	122.5	124.9	127.9X	North 118.750	South 119.550	118.350
LOC IDBL 110.1	Final Aptch Crs 119°	DB612 MANDATORY 2000' (1988')	CAT IIIB, IIIA & II ILS Refer to Minimums	Apt Elev 62' Rwy 12'		
MISSED APCH: Climb direct to DB611, then on track 104° to TALTU, hold at 3000'. Missed apch requires a minimum climb gradient of 3.0%.						
Alt Set: hPa		Rwy Elev: 0 hPa	Trans level: FL150		Trans alt: 13000'	
1. RNAV 1 required for initial, intermediate and missed apch transitions. 2. Special Aircrew & Aircraft Certification Required. 3. CAUTION: Independent Parallel Departures on RWY 12R. 4. ILS DME reads zero at TDZ.						



Gnd speed-Kts	70	90	100	120	140	160				
GS	3.00°	372	478	531	637	743	849			
							HIALS-II REIL PAPI PAPI	➔	DB611	TALTU on 104°


Std/State		STRAIGHT-IN LANDING			
CAT IIIB ILS		CAT IIIA ILS	CAT II ILS		
		DH 50'	A: RA 100' DA(H) 112' (100')	C: RA 121' DA(H) 133' (121')	
			B: RA 109' DA(H) 121' (109')	D: RA 135' DA(H) 147' (135')	
A	R75m	R200m	R300m		
B					
C					
D			R400m		

OMDB/DXB
DUBAI INTL


JEPPESSEN
11 APR 25 **(11-2)** Eff 17 Apr

DUBAI, UAE
ILS Rwy 12R

D-ATIS Arrival	MINHAD Approach	DUBAI Arrivals	DUBAI Director	DUBAI Tower North	DUBAI Tower South	Ground
126.275	122.5	124.9	127.9X	118.750	119.550	118.350
LOC IDBE	Final Apch Crs	DB657 MANDATORY	ILS DA(H)	Apt Elev 62'		
109.5	119°	3000' (2989')	211' (200')	Rwy 11'		
MISSED APCH: Climb direct to DB614, then on track 134° to DB655 at 4000', then turn LEFT on track 044° to TALTU, hold at 4000'. Refer to minimums for missed apch climb gradients.						MSA ARP
Alt Set: hPa Rwy Elev: 0 hPa Trans level: FL150 Trans alt: 13000'						
1. RNAV 1 required for initial, intermediate and missed apch transitions. 2. ILS DME reads zero at TDZ. 3. CIRCLE-TO-LAND: N/A.						



LOC (GS out)	IDBE DME	6.1	5.1	4.1	3.1	2.1	1.1
	ALTITUDE	1940'	1620'	1300'	990'	680'	370'



Gnd speed-Kts	70	90	100	120	140	160	HTALS-II	REIL PAPI	PAPI	DB614	DB655 on 134°
GS 3.00°	372	478	531	637	743	849					
MAP at RW12R											

Std/State		STRAIGHT-IN LANDING		LOC (GS out)	
ILS		Missed apch climb gradient MIN 5.0%		Missed apch climb gradient MIN 4.3%	
DA(H) 211' (200')		CDFA		DA/MDA(H) 620' (609')	
FULL		TDZ or CL out		ALS out	
A	R550m	R550m	R1200m	R1500m	
B					
C					
D				R2100m	R2400m

1 R750m when a Flight Director or Autopilot or HUD to DA is not used.



2 VNAV DA(H) in lieu of MDA(H) depends on operator policy.

CHANGES: OM(D)-10 withdrawn, TALTU and holding at TALTU restrictions.


© JEPPESSEN, 2007, 2025. ALL RIGHTS RESERVED.

DUBAI, UAE
① CAT II/III ILS Rwy 12R

D-ATIS Arrival	MINHAD Approach	DUBAI Arrivals	DUBAI Director	DUBAI Tower North	DUBAI Tower South	Ground
126.275	122.5	124.9	127.9X	118.750	119.550	118.350
LOC IDBE 109.5	Final Apch Crs 119°	DB657 MANDATORY 3000' (2989')	CAT IIIB, IIIA & II ILS Refer to Minimums	Apt Elev 62' Rwy 11'	MSA ARP	
MISSED APCH: Climb direct to DB614, then on track 134° to DB655 at 4000', then turn LEFT on track 044° to TALTU, hold at 4000'. Missed apch requires a minimum climb gradient of 5.0%.						
Alt Set: hPa		Rwy Elev: 0 hPa		Trans level: FL150		Trans alt: 13000'
1. RNAV 1 required for initial, intermediate and missed apch transitions. 2. Special Aircrew & Aircraft Certification Required. 3. ILS DME reads zero at TDZ.						



Gnd speed-Kts	70	90	100	120	140	160
GS 3.00°	372	478	531	637	743	849



DB6 14

DB655 on 134°

Std/State

STRAIGHT-IN LANDING

CAT IIIB ILS		CAT IIIA ILS	CAT II ILS
		DH 50'	ABC: RA 100' DA(H) 111' (100') D: RA 110' DA(H) 121' (110')
A	R75m	R200m	I R300m
B			
C			
D			


1 CAT D without autoland: R350m.

OMDB/DXB
DUBAI INTL


JEPPESSEN
31 JAN 25 11-3

DUBAI, UAE
ILS Rwy 30L

D-ATIS Arrival	MINHAD Approach	DUBAI Arrivals	DUBAI Director	DUBAI Tower		Ground
126.275	122.5	124.9	127.9X	North 118.750	South 119.550	118.350
LOC IDBW 111.3	Final Apch Crs 299°	MODUS MANDATORY 2000' (1940')	ILS DA(H) 260' (200')	Apt Elev 62' Rwy 60'		 MSA ARP
MISSED APCH: Climb direct to DB707, then on track 284° to EGNOT, hold at 3000'. Refer to minimums for missed apch climb gradients.						
Alt Set: hPa		Rwy Elev: 2 hPa		Trans level: FL150		
Trans alt: 13000'						
1. RNAV 1 required for initial, intermediate and missed apch transitions. 2. CAUTION: Independent Parallel Departures on RWY 30R. 3. ILS DME reads zero at TDZ. 4. CIRCLE-TO-LAND: N/A.						



LOC (GS out)	IDBW DME	1.1	2.1	3.1	4.1	5.1	6.1
	ALTITUDE	410'	720'	1040'	1350'	1670'	1980'




Gnd speed-Kts	70	90	100	120	140	160	HIALS-II REIL PAPI PAPI		DB707	EGNOT _{on}	284°
GS 3.00°	372	478	531	637	743	849					
MAP at RW30L											



Std/State		STRAIGHT-IN LANDING			LOC (GS out)	
		ILS			CDFA	
		Missed apch climb gradient MIN 2.8%			DA/MDA(H) 560' (500')	
		DA(H) 260' (200')				
		TDZ or CL out			ALS out	
A						
B						
C	R550m	R550m	R1200m		R1500m	R1500m
D						
D1						R2300m
1 R750m when a Flight Director or Autopilot or HUD to DA is not used.						
2 VNAV DA(H) in lieu of MDA(H) depends on operator policy.						

OMDB/DXB
DUBAI INTL

JEPPESSEN
31 JAN 25 11-3A

DUBAI, UAE
CAT II/III ILS Rwy 30L

D-ATIS Arrival	MINHAD Approach	DUBAI Arrivals	DUBAI Director	DUBAI Tower		Ground
126.275	122.5	124.9	127.9X	North 118.750	South 119.550	118.350
LOC IDBW 111.3	Final Aptch Crs 299°	MODUS MANDATORY 2000' (1940')	CAT IIIB, IIIA & II ILS Refer to Minimums	Apt Elev 62' Rwy 60'		
MISSED APCH: Climb direct to DB707, then on track 284° to EGNOT, hold at 3000'. Missed apch requires a minimum climb gradient of 2.83%.						
Alt Set: hPa		Rwy Elev: 2 hPa	Trans level: FL150	Trans alt: 13000'		
1. RNAV 1 required for initial, intermediate and missed apch transitions. 2. Special Aircrew & Aircraft Certification Required. 3. CAUTION: Independent Parallel Departures on RWY 30R. 4. ILS DME reads zero at TDZ.						



Gnd speed-Kts	70	90	100	120	140	160	HIALS-II			
GS	3.00°	372	478	531	637	743	849	REIL	PAPI	PAPI

Std/State		STRAIGHT-IN LANDING		
CAT IIIB ILS		CAT IIIA ILS	CAT II ILS	
		DH 50'	RA 100'	
			DA(H) 160' (100')	
A	R75m	R200m	R300m	
B				
C				
D				
DL				
CAT D/DL without autoland: R350m.				

DUBAI, UAE
① ILS Rwy 30R



D-ATIS Arrival	MINHAD Approach	DUBAI Arrivals	DUBAI Director	DUBAI Tower		Ground
126.275	122.5	124.9	127.9X	North 118.750	South 119.550	118.350
LOC IDBR 110.9	Final Apch Crs 299°	DB759 MANDATORY 3000' (2967')	ILS DA(H) Refer to Minimums	Apt Elev 62'		
				Rwy 33'		

MISSED APCH: Climb direct to DB755, then on track 314° to DB756 at 4000', then turn LEFT on track 224° to EGNOT, hold at 4000'. Refer to minimums for missed apch climb gradients.


Alt Set: hPa Rwy Elev: 1 hPa Trans level: FL150 Trans alt: 13000'

1. RNAV 1 required for initial, intermediate and missed apch transitions.

2. ILS DME reads zero at TDZ. 3. CIRCLE-TO-LAND: N/A.



LOC (GS out)	IDBR DME	1.2	2.2	3.2	4.2	5.2	6.2
	ALTITUDE	420'	730'	1040'	1360'	1670'	1990'



Gnd speed-Kts	70	90	100	120	140	160
Gs 3.00°	372	478	531	637	743	849
MAP at RW30R						

HIALS-II 		DB755	DB756 on 314
---	--	--------------	----------------------------

Std/State		STRAIGHT-IN LANDING		LOC (GS out)	
		ILS Missed apch climb gradient MIN 4.83% DA(H) ABC: 233' (200') D: 240' (207')		Missed apch climb gradient MIN 4.24% CDFA 2 DA/MDA(H) 510' (477')	
		FULL	TDZ or CL out	ALS out	ALS out
A	R550m	1 R550m	R1200m	R1500m	
B					
C				R1500m	R2200m
D					

1 R750m when a Flight Director or Autopilot or HUD to DA is not used.

2 VNAV DA(H) in lieu of MDA(H) depends on operator policy.


CHANGES: Altitude at ULDOT added.



© JEPPESEN, 2000, 2025. ALL RIGHTS RESERVED.

OMDB/DXB
DUBAI INTL

JEPPESSEN
31 JAN 25 11-4A

DUBAI, UAE
CAT II/III ILS Rwy 30R

D-ATIS Arrival	MINHAD Approach	DUBAI Arrivals	DUBAI Director	DUBAI Tower North	DUBAI Tower South	Ground
126.275	122.5	124.9	127.9X	118.750	119.550	118.350
LOC IDBR 110.9	Final Apch Crs 299°	DB759 MANDATORY 3000' (2967')	CAT IIIB, IIIA & II ILS Refer to Minimums	Apt Elev 62' Rwy 33'		
MISSED APCH: Climb direct to DB755, then on track 314° to DB756 at 4000', then turn LEFT on track 224° to EGNOT, hold at 4000'. Missed apch requires a minimum climb gradient of 4.84%.						
Alt Set: hPa	Rwy Elev: 1 hPa	Trans level: FL150	Trans alt: 13000'			
1. RNAV 1 required for initial, intermediate and missed apch transitions. 2. Special Aircrew & Aircraft Certification Required. 3. ILS DME reads zero at TDZ.						



Gnd speed-Kts	70	90	100	120	140	160	HIALS-II			
GS	3.00°	372	478	531	637	743	849	REIL PAPI	DB755	DB756 on 314°

Std/State		STRAIGHT-IN LANDING			
CAT IIIB ILS		CAT IIIA ILS		CAT II ILS	
		DH 50'		A: RA 100' DA(H) 133' (100')	C: RA 117' DA(H) 150' (117')
				B: RA 105' DA(H) 138' (105')	D: RA 132' DA(H) 165' (132')
A					
B					
C	R75m	R200m		R300m	
D				R400m	


OMDB/DXB
DUBAI INTL

JEPPESSEN
11 APR 25 (12-1) Eff 17 Apr


DUBAI, UAE
RNP Rwy 12L

BRIEFING STRIP™

D-ATIS Arrival	MINHAD Approach	DUBAI Arrivals	DUBAI Director	DUBAI Tower		Ground
126.275	122.5	124.9	127.9X	North 118.750	South 119.550	118.350
RNAV	Final Apch Crs 119°	DB601 MANDATORY 2000' (1988')	LNAV/VNAV DA(H) Refer to Minimums	Apt Elev 62' Rwy 12'		MSA ARP
MISSED APCH: Climb direct to DB611, then on track 104° to TALTU, hold at 3000.' Refer to minimums for missed apch climb gradients.						
Alt Set: hPa		Rwy Elev: 0 hPa	Trans level: FL150	Trans alt: 13000'		
RNP Apch	1. CAUTION: Independent Parallel Departures on RWY 12R. 2. CIRCLE-TO-LAND: N/A. 3. Baro-VNAV not authorized below +5°C.					



DIST to RW12L	5.5	4.5	3.5	2.5	1.5	0.5
ALTITUDE	1690'	1390'	1100'	800'	500'	200'



Gnd speed-Kts	70	90	100	120	140	160
Glide Path Angle	2.80°	347	446	495	594	693
MAP at RW12L						

Std/State		STRAIGHT-IN LANDING	
LNAV/VNAV Missed apch climb gradient MIN 2.75% A: 330' (318') DA(H) BC: 350' (338') DDL: 370' (358')		LNAV Missed apch climb gradient MIN 2.6% CDFA 2 DA/MDA(H) 550' (538')	
ALS out		ALS out	
A	1 R750m	R1400m	R1500m
B	R800m	R1500m	R1500m
C	R800m	R1500m	R1500m
D	R900m	R1600m	R1700m
DL	R900m	R1600m	R2400m

1 With TDZ & CL & HUD: R700m. **2** VNAV DA(H) in lieu of MDA(H) depends on operator policy.

CHANGES: OM(D)-10 withdrawn, TALTU and holding at TALTU restrictions.


© JEPPESSEN, 2012, 2025. ALL RIGHTS RESERVED.

OMDB/DXB
DUBAI INTL


JEPPESSEN
11 APR 25 **(12-2)** Eff 17 Apr

DUBAI, UAE
RNP Rwy 12R


BRIEFING STRIP

D-ATIS Arrival	MINHAD Approach	DUBAI Arrivals	DUBAI Director	DUBAI Tower		Ground
126.275	122.5	124.9	127.9X	North 118.750	South 119.550	118.350
RNAV	Final Apch Crs 119°	DB658 MANDATORY 3000' (2989')	LNAV/VNAV DA(H) Refer to Minimums	Apt Elev 62'	Rwy 11'	
MISSED APCH: Climb direct to DB614, then on track 134° to DB655 at 4000', then turn LEFT on track 044° to TALTU, hold at 4000'. Refer to minimums for missed apch climb gradients.						
Alt Set: hPa		Rwy Elev: 0 hPa	Trans level: FL150	Trans alt: 13000'		
RNP Apch	1. CIRCLE-TO-LAND: N/A. 2. Baro-VNAV not authorized below +5°C.					

MSA ARP



DIST to RW12R	6.5	5.5	4.5	3.5	2.5	1.5	0.5
ALTITUDE	1990'	1690'	1400'	1100'	800'	500'	210'



Gnd speed-Kts	70	90	100	120	140	160	HIALS-II	DB614	DB655 on 134°
Glide Path Angle	2.80°	347	446	495	594	693	792	REIL PAPI	PAPI
MAP at RW12R									

Std/State		STRAIGHT-IN LANDING	
LNAV/VNAV		LNAV	
Missed apch climb gradient MIN 4.55%		Missed apch climb gradient MIN 4.65%	
A: 420' (409')		CDFA	
DA(H) BC: 440' (429') DDL: 450' (439')		DA/MDA(H) 620' (609')	
ALS out		ALS out	
A	R1200m	R1500m	
B		R1500m	
C	R1300m	R2000m	
D		R2100m	
DL		R2400m	

VNAV DA(H) in lieu of MDA(H) depends on operator policy.

CHANGES: OM(D)-10 withdrawn, TALTU and holding at TALTU restrictions.

© JEPPESSEN, 2012, 2025. ALL RIGHTS RESERVED.



OMDB/DXB
DUBAI INTL

JEPPESSEN
17 JAN 25 **(12-3)** Eff 23 Jan

DUBAI, UAE
● **RNP Rwy 30L**

BRIEFING STRIP™

D-ATIS Arrival	MINHAD Approach	DUBAI Arrivals	DUBAI Director	DUBAI Tower North	DUBAI Tower South	Ground
126.275	122.5	124.9	127.9X	118.750	119.550	118.350
RNAV	Final Apch Crs 299°	DB713 MANDATORY 2000' (1940')	LNAV/VNAV DA(H) Refer to Minimums	Apt Elev 62' Rwy 60'	 MSA ARP	
MISSED APCH: Climb direct to DB707, then on track 284° to EGNOT, hold at 3000'. Refer to minimums for missed apch climb gradients.						
Alt Set: hPa		Rwy Elev: 2 hPa	Trans level: FL150	Trans alt: 13000'		
RNP Apch	1. CAUTION: Independent Parallel Departures on RWY 30R. 2. CIRCLE-TO-LAND: N/A. 3. Baro-VNAV not authorized below +5°C.					



Gnd speed-Kts	70	90	100	120	140	160	HIALS-II	REIL	PAPI	PAPI	DB707	EGNOT on 284°
Glide Path Angle	2.80°	347	446	495	594	693	792					
MAP at RW30L												


Std/State	LNAV/VNAV	STRAIGHT-IN LANDING	LNAV
	Missed apch climb gradient MIN 2.6%		Missed apch climb gradient MIN 2.55%
	A: 370' (310') C: 390' (330')		CDFA
	DA(H) B: 380' (320') DDL: 400' (340')		2 DA/MDA(H) 560' (500')
	ALS out		ALS out
A	R750m	R1400m	R1500m
B			
C			
D	R800m	R1500m	R2300m
D _L			

1 With TDZ & CL & HUD: R700m.
 2 VNAV DA(H) in lieu of MDA(H) depends on operator policy.

OMDB/DXB
DUBAI INTL

JEPPesen
8 AUG 25 19-10


DUBAI, UAE VFR



OMDB/DXB
DUBAI INTL

8 AUG 25 19-11

DUBAI, UAE VFR



VRP: DEFINITION:

CCI	N25 10.8 E055 19.2
EIN	N25 07.2 E055 21.9
FLP	N25 14.5 E055 16.1
GBR	N25 14.0 E055 20.3
HCG	N25 12.6 E055 14.3
MBR	N25 15.1 E055 19.3
NBC	N25 14.9 E055 15.3
QEL	N25 15.7 E055 16.8
RCG	N25 11.1 E055 22.2
SFP	N25 11.3 E055 14.5
SHP	N25 13.4 E055 13.9
STR	N25 14.1 E055 16.7
WTK	N25 13.2 E055 22.8

VFR ROUTE: MAX Altitude:

VR1	1000' (1500' between NBC and SHP)
VR2	1000'
VR5	1000' (1500' between FLP and HCG)
VR6	1000'
VR7	1000'
VR8	1000'

REMARKS:

Opposite direction traffic may be expected along VR1 between SHP-NBC-QEL-MBR-GBR due to seaplane operations arriving and departing to/from Creek and Port Rashid water runways

Caution: Drone activity on segments STR-GBR, MBR-QEL and QEL-NBC from GND to 400' AGL. Exercise vigilance when operating within these segments.

Traffic transiting OM(R)-75 shall at VRP EIN contact MINHAD App (122.5) for approval.

Do not climb to 1500' until established Southbound.

For segments between RCG, DFB, MKI see 19-10.

Traffic transiting OM(R)-75 shall at VRP EIN contact MINHAD App (122.5) for approval. DUBAI Tower may request to hold at WTK.

DUBAI Tower may request to hold at WTK.