Firmware Security Assessment Summary

May 21, 2020



Linksys E900 1.0.09

Filename FW_E900_1.0.09.002_US_20180808.bin MD5 Sum b064e43f98a0780b50504125b48047c1 Operating System Linux kernel version 2.6.22 Scanned May 20, 2020

Firmware Image

7.4M FILE SIZE

31M EXTRACTED SIZI 1624

1 ROOT FILESYSTEMS

CVE Detection

77
OPEN SOURCE
VULNERABILITIES

4
FILES AFFECTED

Critical/High 22

Medium 51

Low 4

Unassigned 0

1 openssl 10 2 busybox 7

3 pppd 3 4 radvd 2

Top Critical/High Components

CVE Severity Distribution

Software Maturity

84 HIGH RISK EXECUTABLES 747 TOTAL FLAWS 51 EMULATED FLAWS

1 rc 113 2 httpd 90 3 wlconf 65

4 wps_monitor

5 libshared.so 54

54

Top High Risk Executables

Firmware Security Assessment Summary

Powered by CENTRIFUGE
May 21, 2020



Linksys E900 1.0.09

Crypto Keys			
O TOTAL KEYS	O SSH PRIVATE KEYS	O SSH PUBLIC KEYS	O OTHER KEYS
Crypto Certificates			
1 TOTAL CERTIFICATES	O CERTIFICATE AUTHORITIES	1 STANDARD CERTIFICATES	O EXPIRED CERTIFICATES
Password Hashes		Software Bill of Materials	
O PASSWORD HASHES		19 OPEN SOURCE COMPONENTS	
Security Checklist			
4.0		N/A	
12 PASSING TESTS	O FAILING TESTS	Failing Tests	

Firmware Security Assessment Summary

refirm labs

Linksys E900 1.0.09

Binary Hardening

210 BINARIES 301/1050 FEATURES ENABLED

28% OVERALL COVERAGE

