Homework

Previously, we have discussed how to design a quadratic programming based MPC to allow a single-axis triple integrator to travel from an arbitrary state to the centre of the state space, a.k.a with zero position, velocity and acceleration.

Now please design a quadratic programming based MPC to track conical spiral for a 3-axis triple integrator (basically a quadrotor model).



