OSDP Interop Cable

Table of Contents

Notes	1
Cable Assembly	
Parts List.	
Tools List	
Cable Harness Assembly	
about pins:	
about wiring the connector:	1
Device Cable Assembly	
Device Power Cable	
Figure 1 OSDP Interop Cable.	

Notes

- 1. Picture attached at end of this document as Figure 1.
- 2. twisted pair ignored due to short length
- 3. termination resistors ignored due to short length
- 4. happy to modify cable if someone can show up with a standard to follow.

Cable Assembly

Parts List

4x 3pin male molex 4x 3pin female molex pins for each (assume you will mess up a few, get extras) 20 gauge solid core wire. red, white, black.

Tools List

pin crimp tool wire stripper

Cable Harness Assembly

build 4-drop cable. note 2 inner drops hav double the wires in the crimp.

cut cable 3x 0.3 meter lengths r,w,b strip 3/16 inch each

about pins:

male pins go in female shell female pins go in male shell

about wiring the connector:

red - pointy end white - middle black - square end

for inner connectors insert 2 stripped cables in pin; crimp; insert in shell for outer connectors insert stripped cable in pin; crimp; insert in shell

Device Cable Assembly

for pigtails: red is tx+ white is txblack is ground

Device Power Cable

power cables:
2-pin
DUT gets female shell
red is +12
black is -12 / ground

Figure 1 OSDP Interop Cable

