Sea-Bird Scientific 13431 NE 20<sup>th</sup> Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 4443 CALIBRATION DATE: 21-Feb-23 SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **COEFFICIENTS:**

g = 4.41121516e-003 h = 6.41795534e-004 i = 2.18210915e-005 j = 1.86256511e-006 f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
-1.5000	3254.446	-1.4999	0.00006
1.0000	3442.605	1.0000	-0.00004
4.5000	3719.078	4.4999	-0.00008
8.0000	4011.170	8.0000	-0.00003
11.5000	4319.304	11.5001	0.00006
15.0000	4643.890	15.0001	0.00013
18.5000	4985.311	18.5000	-0.00001
22.0000	5343.984	21.9999	-0.00009
25.5000	5720.297	25.5000	-0.00003
29.0000	6114.594	29.0000	-0.00001
32.4999	6527.224	32.4999	0.00004

f = Instrument Output (Hz)

Temperature ITS-90 (°C) =  $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$ 

Residual ( $^{\circ}$ C) = instrument temperature - bath temperature

