Sea-Bird Scientific 13431 NE 20th Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 5827 CALIBRATION DATE: 22-Nov-22 SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

g = 4.36805829e-003 h = 6.67750954e-004 i = 2.67979371e-005j = 2.06288985e-006

f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
-1.5000	2917.796	-1.5000	0.00003
1.0000	3081.113	1.0000	-0.00002
4.5000	3320.790	4.5000	-0.00005
8.0000	3573.674	8.0000	-0.00001
11.5000	3840.123	11.5000	0.00002
15.0000	4120.492	15.0001	0.00006
18.5000	4415.120	18.5000	0.00003
22.0000	4724.349	22.0000	-0.00001
25.5000	5048.506	25.4999	-0.00006
29.0000	5387.918	29.0000	-0.00002
32.5000	5742.885	32.5000	0.00004

f = Instrument Output (Hz)

Temperature ITS-90 (°C) = $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$

Residual ($^{\circ}$ C) = instrument temperature - bath temperature

