

Report Date : 26-Aug-2020 16:41

Page No.: 1 of 4

Near Miss Investigation Basic Detail						
Report No :	NFIP1/NM/2020/0025	Event Date & Time :	24-Aug-2020 14:10			
Department :	Stores	Contractors:	Saiurja			
Plants/Areas :	Warehouse	Exact Location :	Hazardous waste area			
Category:	Near Miss	Report Date & Time :	24-Aug-2020 14:34			
Severity:	Medium					
Description of what happened :	While shifting the material in hazardous waste storage area, Fork lift got stuck up and to remove the Fork lift, Hydra was brought there. During this Activity Fork lift hit the Fire cabinet over there resulting Minor damage.					
Immediate Action Taken (Also mention who visited site first and what action was proposed by him? if applicable):	Immediately Vehicle is withdrawn from the location where it had touch with Fire cabinet and Cabinet was found dent and glass broken.					
Investigation Detail						
Sequential occurrence :	Fork lift was shifting hazardous waste shifting (Internally) in hazardous waste storage area.  Fork lift was stuck up hence made idle and switched off and to remove the Fork lift, Hydra was brought there.  During this Activity Fork lift hit with Fire cabinet over there resulting Minor damage and also glass broken of the same'					
Activity of the person(s) /injured at the time of the incident :	Nil					
Near Miss Cause						
Direct Causes						
A) UNSAFE ACTS :						
Tools or Equipment :	N/A	Noncompliance to proper procedure	es: N/A			
Protective Methods :	N/A	Distraction / Inattention :	Improper decision making			
B) UNSAFE CONDITIONS :						

Note: This is system generated report hence signature not required.



Report Date : 26-Aug-2020 16:41

Page No.: 2 of 4

Sr. #	Action to be Taken Responsibility		Priority		Target Date	Status		
Recon	nmendation(s)							
3	Mishant Lakdawala	SURAT		Chemistry			Sr. Officer	
2	Aditya Jain		SURAT		Boiler Maintenance		Associate Manager	
1	Rajiv Shukla	SURAT		Chemistry			Sr. Officer	
Sr. #	Name		Plant			Department	Position	
Invest	igation Team							
			lift was stuck up due to lack of judgement/ Inexperience of its operator. ift operator was allowed to operate the vehicle with learning licence only.					
			oper Communication between the Hydra operator and Supervising person.					
People – Skill Level : Inadequate job		· ·	ills, Employed for out of skill	kill People – Behaviors :		N/A	N/A	
People – Physical Wellbeing : N/A			People – Mental V					
,	RSONAL FACTORS:							
	unication():	Inadequate co	ommunication between differer	nt work groups				
	Management : N/A			Training / Knowledge transfer :		: N/A	N/A	
		different work				N/A		
Work Planning : N/A			vana vaisatian hatusan	Tools & Equipment :			N/A	
	B FACTORS :	NI/A		T. d. 0 F. '		NI/A		
	Causes							
•	xposures to : N/A		Work Place Environment :		Conge	Congested workplace		
	ctive Systems : N/A			Tools, Equipment & Vehicles :			N/A	

Note: This is system generated report hence signature not required.



Report Date : 26-Aug-2020 16:41

Page No.: 3 of 4

Recom	Recommendation(s)				
1	Forklift operation must be with valid permanent driving licence only.	Mishant Lakdawala	Medium	31-Aug-2020	Active - (Pending)
2	Awareness training to be impart among the persons associate with the forklift/Hydra movement.	Rajiv Shukla	Immediate	25-Aug-2020	Active - (Pending)
Sr. #	File Name(s)				
1	CompletionTasks.jpg				
Comment(s) & Status History					
Investi	Investigation completed & send for EHS Head review				
Investi	Investigation completed and sending for your review.				
By Raji	By Rajiv Shukla on 24-Aug-2020 15:20 (Hrs.)				
Near Miss send for investigation					
By Ravi Patel on 24-Aug-2020 14:39 (Hrs.)					
Near M	Near Miss reported and send for review				
By Adit	By Aditya Jain on 24-Aug-2020 14:34 (Hrs.)				

Attach	Attachment(s)		
Sr. #	File Name(s)		
1	pics1.jpg		
2	pics2.jpg		

Note: This is system generated report hence signature not required.



Report Date : 26-Aug-2020 16:41

Page No.: 4 of 4

### Attachment(s) Preview:

