

Three Definitions of Optimal k
Balanced: k=900
Smoothest: k=30
Most Efficient: k=870
Position x [mm]
Time [s]
k=30
k=900
k=870 (optimal)
0
2
4
50