

Three Definitions of Optimal k
Balanced: k=300
Smoothest: k=10
Most Efficient: k=290
Position x [mm]
Time [s]
k=10
k=300
k=300
k=10
k=10
k=300
k=10
k=290 (optimal)
k=300
0
50
0
2
4