

Measured Force: Tanh (saturates) vs. Linear (unbounded)
Tanh (Fmax=4.0)
Linear
Measured shear force [N]
0.0
0.2
0.4
0.6
0.8
10
20
30
40
50
Commanded displacement —goal— [cm]