

no_gauss_r1 – Gaussian strength 0 N/m
whole run
first 61 s
target reached
target reached
Tip [cm]
0
−50
solid: tip, dashed: goal
X
Y
Z
|F| [N]
5
0
lin_tip
gauss_seg1
gauss_seg2
Spring param
$10^1$
$10^0$
0
lin_tip
gauss_seg1
gauss_seg2
Torque [N m]
0.2
0.0
max |tau| asked
Shear [N]
0.5
0.0
reading > 1 s old
0
10
20
30
40
50
60
70
Time [s]
0
20
40
60
Time [s]