

no_gauss_r4 – Gaussian strength 0 N/m
whole run
first 61 s
target reached
target reached
Tip [cm]
solid: tip, dashed: goal
X
Y
Z
|F| [N]
lin_tip
gauss_seg1
gauss_seg2
Spring param
lin_tip
gauss_seg1
gauss_seg2
Torque [N m]
max |tau| asked
Shear [N]
reading > 1 s old
Time [s]
Time [s]