

Three Definitions of Optimal k
Balanced: k=690
Smoothest: k=30
Most Efficient: k=690
Position x [mm]
Time [s]
k=690 (optimal)
k=300
k=30 (optimal)
k=300
k=690 (optimal)
k=300
0
2
4
50
25
0