


a


S_0
S_I
S_{II}
S_{III}
Motors

b


120°


Bowden cables
Tendons
Section I
Section II
Section III