DefectCorrection_GigE_v1.0 프로그램 간단 매뉴얼

DefectCorrection							- 🗆 X
For Black Image Offset Low: Offset High:	10		For White Image Gain Lower: 0. Gain Upper: 1.			Skip Size Left: 0 Top: 0	Right: 0
	Open_Black		0	pen_White		□ COLOR ● BLACK ○ W	
						Process	ST0P
USER_ID	MODEL_NAME MG-A160M_	SERIAL_NUMBER SN_23921869004	DEVICE_VERSION 3.2.1.4	MAC_ADDRESS 00:14:F7:00:92:04	IP_AI 169.25⁴	Defect_Count Black: 0 White: 0	Merge Defect : 0
Discovery			CONN	ECT Write To C	amera	●○● 경과시간	: (ms)

기능 1. 이미지 디펙 검출

기능 2. 디펙 좌표 카메라 전송 및 카메라 디펙 보정

기능 1. 이미지 디펙 검출

- 1. Open_Black 또는 Open_White 버튼 클릭하여 이미지를 불러옵니다.
- 2. OffSet 과 Gain 또는 SkipSize 설정하기
- 3. Color 체크박스 또는 Black, White, Both 체크하기
- 4. Process 버튼 클릭

기능 2. 디펙 좌표 카메라 전송 및 카메라 디펙 보정(Process 가 모두 완료 된 후 사용 가능.)

- 1. 연결하고자 하는 카메라를 선택하고 CONNECT 버튼을 눌러 연결합니다.
- 2. Write To Camera 버튼을 클릭합니다.

UI 설명

-Offset 범위 설정

For Black Image		
Offset Low:	30	
Offset High :	30	

Offset 값이 Offset Low 값보다 작거나 Offset High 값보다 클경우 디펙으로 인식합니다.

(Offset = OriginalVal - AverageVal)

-Gain 범위 설정

For White Image						
Gain Lower:	0					
Gain Upper :	1.7					

Gain 값이 GainLower 값보다 작거나 GainUpper 값보다 클경우 디펙으로 인식합니다.


(Gain = OriginalVal/AverageVal)

-Skip Size 설정




이미지에서 제외할 부분을 설정합니다.

-Color 이미지 설정



Bayer pattern 이미지일 경우 체크박스에 체크합니다.

-이미지 종류 선택



Black 체크일경우 Black 이미지만 검출, White 체크일경우 White 이미지만 검출, Both 체크일경우 양쪽 이미지모두 검출합니다.

-디펙 검출 시작 버튼




이미지의 크기(해상도)에 따라 시간이 오래 걸릴 수 있습니다.

-디펙 좌표 전송 및 카메라 디펙 보정




카메라에 디펙 좌표를 전송합니다.

-디펙 갯수 Count



디펙 갯수를 표시합니다. Merge Defect 은 중복된 좌표를 제외한 갯수입니다.

-GigE 리스트



현재 PC 와 연결된 GigE 카메라 리스트를 보여줍니다.