# DefectCorrection\_3CC\_v1.0.0 프로그램 간단 메뉴얼

DefectCorrection		- 🗆 X
For Black Image Offset Low: -10 Offset High: 10	For White Image Gain Lower: 0.8  Gain Upper: 1.2	Skip Size           Left:         0         Right:         0           Top:         0         Bottom:         0
Open_Black	Open_White	● BLACK ○ WHITE ○ BOTH
C:\Users\unders\undersktop\unders\understop\un	C:\Users\users\userblack\users\userblack\users\userblack\users\userblack\use	Process STOP
		Defect_Count  Black: 0 0 0  White: 0 0 0
· >	>	Merge : 0 0 0 Defect
Port COM_Port#COM1 > CONNECTION C	WriteTo Camera	●○● 정확시간: (ms)

## 기능 1. 이미지 디펙 검출

#### 기능 2. 디펙 좌표 카메라 전송 및 카메라 디펙 보정

## ※이미지 디펙 검출 방법

- 1. Open\_Black 와 Open\_White 버튼 클릭하여 이미지 불러오기
- 2. OffSet 과 Gain 또는 SkipSize 설정하기
- 3. Color 체크박스와 Black, White, Both 체크하기
- 4. Process 버튼 클릭

# ※디펙 좌표 카메라 전송 및 카메라 디펙 보정 방법(Process 가 모두 완료 된 후 사용 가능.)

- 1. Connect 버튼을 눌러 카메라와 연결
- 2. Write To Camera 버튼을 클릭


# UI 설명

#### -Offset 범위 설정



Offset 값이 Offset Low 값보다 작거나 Offset High 값보다 클경우 디펙으로 인식합니다. (여기서 Offset 이란 실제 값과 필터링된 DN 값의 차이 입니다.)

## -Gain 범위 설정




Gain 값이 GainLower 값보다 작거나 GainUpper 값보다 클경우 디펙으로 인식합니다. (여기서 Gain 이란 실제 값과 필터링된 값의 차이(퍼센티지)값입니다.)

# -Skip Size 설정



이미지에서 제외할 부분을 설정합니다.

#### -이미지 종류 선택



Black 체크일경우 Black 이미지만 검출, White 체크일경우 White 이미지만 검출, Both 체크일경우 양쪽 이미지 모두 검출합니다.

## -디펙 검출 시작 버튼




이미지의 크기(해상도)에 따라 시간이 오래 걸릴 수 있습니다.

## -카메라 연결




카메라와 연결합니다.

#### -디펙 좌표 전송 및 카메라 디펙 보정



카메라에 디펙 좌표를 전송합니다.

#### -디펙 갯수 Count



디펙 갯수를 표시합니다. Merge Defect 은 중복된 좌표를 제외한 갯수입니다.