TOYOTA MOTORS NORTH AMERICA 6565 HEADQUARTERS DR. PLANO. TX 75024







MILES IN DATE/TIME IN VEHICLE ID MILES OUT DATE OUT 204 STRATEGIC INNOVATION INVOICE NO. 5TFAY5F19MX961364 9506 9506 08/23/21 16:48 10/13/21 24250 6565 HEADQUARTERS DR VEHICLE DESCRIPTION TAG NO. **STATUS** PLANO, TX 75024 Brittney.Ferrell@toyota.com 2021 TOYOTA TUNDRA CRE **COMPLETE** CONTROL NO. LICENSE PLATE NO. CUST. LABOR RATE PROD. DATE IN-SERV DATE DELIV. DATE DELIV. MILES **TERMS** 014116 Cash HOME PHONE WORK PHONE **CELL PHONE** STOCK NO. SERV. ADV. **RO COMMENT**

) 204 204-0	050012 680350-TF	SIC
Line	Op-Code	Fail Code	Tech	Hours	Туре		Amount
A Concern Cause Correction	DFMOKD Check driver' No problem f Document or		A54	0.00	Customer		\$0.00
			Total Hours:	0.00		Line Total	\$0.00
В			A54	0.00	Customer		\$0.00
	from the Tundra that I have up there? This vehicle will be part of that test pilot where we will install a different kind of hardware (since Continental still has not provided us with the software package needed for the current hardware). The new hardware is the one that the installer is flying in for and I will reserve a high bay. Ill let you know when that will be taking place so you can determine if Ryan will be able to join.						
Cause Correction	Training -Removed all OTA key hardware. Training on this vehicle in Highbay to installed new ride share hareware Intervert.10.00 hours labor N/C						
			Total Hours:	0.00		Line Total	\$0.00
C +	21		A54	0.50	Customer		\$58.55
Concern Correction	CHASSIS EL Battery failed	ECTRICAL load test replaced ba	attery.				
Part N	Number	Descri	iption			Qty. Unit Price	Ext. Price

Part Number	Description		Qty. Unit Price	Ext. Price
0054427F60710 TRUESTART BATT			1 \$106.68	\$106.68
			Parts Total	\$106.68
	Total Hours:	0.50	Line Total	=====================================

10/13/21 12:42 INVOICE CUSTOMER COPY Page 1 of 2

TOYOTA MOTORS NORTH AMERICA 6565 HEADQUARTERS DR. PLANO. TX 75024







5TFAY5F19MX961364	

204 STRATEGIC INNOVATION	VEHICLE ID		MIL	LES IN	MILES OUT	DATE/TIME IN		DATE OUT	INVOICE NO.
6565 HEADQUARTERS DR	5TFAY5F19MX961364		9	506	9506	08/23/21 16:48		10/13/21	24250
PLANO, TX 75024		VEHICLE DESCRIPTION TAG NO.					STATUS		
Brittney.Ferrell@toyota.com	2021 TOYOTA	2021 TOYOTA TUNDRA CRE					COMPLETE		
CONTROL NO. LICENSE PLATE NO	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE		ERV DATE DELIV. DATE		DELIV. MILES		TERMS
014116									Cash
HOME PHONE WORK PHONE	CELL PHONE	STOCK	STOCK NO. SEF		SERV	SERV. ADV.		RO COMMENT	
) 204 204-050		204-050012 680350-TFSI		(

Customer Totals

Charge Description	Amount
Labor	\$58.55
Parts	\$106.68
Total Amount Due	\$165.23

Default \$165.23

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the $\hfill \hfill$

sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of

merchantability or fitness for a particular purpose. Seller neither

assumes nor authorizes any other person to assume for it any liability in

connection with the sale of this item/items.

CUSTOMER SIGNATURE

On behalf of servicing dealer, I hereby certify that the information contained hereon is accurate unless otherwise shown. Warranty services

hereon is accurate unless otherwise shown. Warranty services described were

performed at no charge to owner. There was no indication from the appearance of the vehicle or otherwise, that any part repaired or replaced under

this claim had been connected in any way with any accident, negligence, or

misuse. Records supporting this claim are available for (1) year from the date of payment notifi-

cation at the servicing dealer for inspection by manufacturer's representative.

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)