

Longo Collision Repair Center 3534 N. Peck Road

El Monte, CA 91731

Phone: (626)539-2855 Fax: (626)580-6187 BAR #ARD268047. EPA #CAD982337131.



0.00

Kinto Share 5	Date of Loss:	Longo Toyota
3534 N Peck Rd	Year: 15	
El Monte, CA 91731	Make: Toyota	
	Model: Prius	
	Type: 1	Phone:
Home: 626-580-6166	Style: Light	Fax:
Work:	Engine:	Adjuster:
Est.: Jose Chavez	Color: Grey	Claim #: 00150465
I —		

 Received: 11/17/20
 License: CA 7W1R751
 Policy:

 Del. Date: 12/23/20
 Paid: 1/11/21
 Mileage: 80,105
 Betterment: VIN: JTDKN3DU4F1913520

n.	Description	P	arts	Labor Units	Refin Units	Other
	BOLT, W/W	OE	2.24			
	glass labor			-2.60		
	glass labor			2.60		
1	vehicle needs teardown					
2	ELECTRICAL					
3	High voltage system deactivate			0.70		
4	PILLARS, ROCKER & FLOOR					
5	RT Rocker molding			0.90		
6	LT Rocker molding			0.90		
7	RT Rocker molding grommet type	OE	1.35			
8	LT Rocker molding grommet type	OE	1.35			
9	RT Rocker molding grommet type	OE	3.16			
10	LT Rocker molding grommet type	OE	3.16			
11	RT Rocker molding grommet type	OE	4.72			
12	LT Rocker molding grommet type	OE	4.72			
13	RT Rocker molding retainer typ	OE	13.00			
14	LT Rocker molding retainer typ	OE	13.00			
15	RT Rocker molding retainer typ	OE	27.00			
16	LT Rocker molding retainer typ	OE	27.00			
17	RT Rocker molding dip	OE	53.01			
18	LT Rocker molding dip	OE	53.01			
19	QUARTER PANEL					
20	LT Quarter panel w/o Plug-in			2.00	2.90	
21	Add for Clear Coat				1.20	
22	LT Trough			2.00	0.40	
23	Add for Clear Coat				0.10	
24	REAR BODY & FLOOR					
25	Rear body panel			14.00	1.40	
26	RT Front panel			0.30		
27	LT Front panel			0.30		
28	Center panel			0.20		
29	Rear panel					
30	RT Side panel	OE	248.05	0.10		
31	Storage box w/o dividers w/15"			0.30		
32	Storage box					

		2/11/21	J.UI AIVI		24331001
33 Cushion w/15" wheel			0.10		
34 Rear trim			0.20		
35 RT Side trim panel	ii ii		0.40		
36 LT Side trim panel			0.40		
37 Rear floor pan w/o Plug-in			4.00	1.80	
38 Overlap Major Non-Adj. Panel				-0.20	
39 LIFT GATE					
40 Lift gate w/rr camera (ALU)	OE	600.19	5.30	3.80	
41 Overlap Major Adj. Panel				-0.40	
42 Add for Clear Coat				0.70	
43 Add for wiper			0.60		
44 Add for trnsfr glass upper		1	1.20		
45 Add for trnsfr glass lower			0.80		
46 RT Lift gate cushion upper	OE	12.18			
47 LT Lift gate cushion upper	OE	12.18			
48 RT Lift gate cushion lower	OE	5.32			
49 LT Lift gate cushion lower	OE	5.32			
50 RT Lift gate stopper	OE	15.34			
51 LT Lift gate stopper	OE	15.34			
52 RT Lift gate bolt cushion	OE	1.18			
53 LT Lift gate bolt cushion	OE	1.18			
54 RT Lift gate bolt stopper	OE	2.16			
55 LT Lift gate bolt stopper	OE	2.16			
56 Lift gate w'strp					
57 Lift gate trim gray					
58 RT Support cylinder			0.20		
59 LT Support cylinder			0.20		
60 Spoiler assy gloss black			0.40		
61 Upper trim panel					
62 Center panel					
63 RT Side trim panel					
64 LT Side trim panel					
65 Lower trim panel					
66 RT Hinge			0.50		
67 LT Hinge			0.50		
68 Lock assy	i i				
69 REAR LAMPS					
70 RT Tail lamp assy retainer	OE	19.83			
71 REAR BUMPER					
72 Bumper cover			2.00	2.80	
73 Add for Clear Coat				1.10	
74 O/H bumper assy			1.90		
75 RT Side spoiler			1,00		
76 LT Side spoiler					
77 Spoiler center					
78 MISCELLANEOUS OPERATIONS	1				
79 Cover car/bag				0.20	
80 Color Tint				1.00	
81 Color Tint 2nd Tone/Inner stru				0.50	
82 Mask vehicle for Overspray				0.20	li li
83 Mask vehicle for Primer Stage				0.50	
•				0.50	
84 Ready to Spray Waterbase Seale 85 Color Sand & Polish				1.60	
86 Clean Compound Residue after p			0.80	1.00	
oo orean compound neardine after p	I,	1	0.60		E E

87 Fill, s	and, Feather, Edge & Bl				1.00		
88 Remo	veglue/residue on repaire		0.80				5.00
89 Hazar	rdous Waste Removal						14.00
	sion Promoter				0.50		10.00
91 ProGr	rip Polyurethane 300ml Bac		0.40				28.74
	ilver Weld Thru II Coating		0.40				16.13
93 3M U	Itrapro MSP White Seam Sea		0.80				15.70
94 Mask	interior to prevent overs				0.30		
95 3M D	uramix Factory - Match Bla				0.30		24.22
96 3M U	Itrapro MSP White Seam Sea		0.30				10.36
97 Mask	/Tape Door Edge to Duplica				0.30		3.00
98 5/16 \	Windo-Weld Ribbon Sealer		0.30				10.68
99 Mask	Liftgate openings for pai				0.20		2.00
100 Set U	p & Measure		3.00				
101 Clam	p damages after pulls		1.00		1.00		
102 Set Ba	ack Wiring Harness for Re		0.50				
913 Paint	Materials						657.00
919 Clear	Coat Paint Materials						90.00
Total	s	1,147.15	48.70		23.70		938.86
	Total Category						Total
	BODY LABOR						2,828.70
	PAINT LABOR						1,442.70
	FRAME LABOR						285.00
	RUB-OUT LABOR						100.80
	PAINT MATERIAL						924.86
	HAZARDOUS MATERIALS						14.00
	OEM PART						1,147.15
	Subtotals						6,743.21
	SALES TAX CA						208.60
	Grand Total:						6,951.81
D-1	D			Daneit d D		Ob	A 1
Date	Payment			Received By		Charge Type	Amount
1/11/21	James river ck#0000638621			Arasi477	Check		3,230.47
1/11/21	Jamse River ck#000638967			Arasi477	Check		2,718.75
	Total Payments:						5,949.22
	Balance Due:						1,002.59