CUSTOMER #: 73810

KINTO SHARE

695061

INVOICE

5611 Hollister Ave. - Goleta, California 93117

Phone (805) 967-5611 · Service (805) 683-2593 · Fax (805) 967-3732

www.toyotaofsantabarbara.com

CA 93117

PAGE 1

Service and Parts Department Hours Monday through Friday: 7:00 A.M. to 6:00 P.M. Saturday: 7:30 A.M. to 5:00 P.M

HOME: 805-9	67-5	611	CONT:805-	967-561	1	Saturday: 7:30 A.M. to 5:00 P.M.					
BUS: CELL:					SEI	SERVICE ADVISOR: 7503 RACHEL MASEDA VIN LICENSE MILEAGE IN / OUT TAG					
COLOR	YEAR	MAKE/MODEL			VIN		MILEAC	SE IN / OUT	TAG		
<u>White</u>	15		OTA PRIUS			<u> N3DU7F0439214</u>			<u>/107661</u>		
DEL. DATE	PROD.	DATE	WARR. EXP.	PROM	IISED	PO NO.	RATE	PAYMENT	INV. [DATE	
01 TAN15 DD			Ο <i>Ι</i> ΤΙΤΝΤ Ο 1	JUN21 AR 07JUN21			0.1				
01JAN15 DD R.O. OPENED			17:00 04 READY OPTIONS					AR		07JUN21	
R.O. OPENED READT OF HONS. DER: 4150											
10:12 04JUN21 09:38 07JUN21											
LINE OPCODE TECH TYPE HOURS LIST NET TOTAL										ΓAL	
A c/s vehicle needs to be jumped, check and advise											
MA001 c/s vehicle needs to be jumped, check and											
advise											
976 CANI 80.00 80.0											
PARTS:				80.00			TOTAL I		80	.00	
96573 Jump started vehicle, Charged and tested 12v battery. Passed.											
Found dome light to have been left on draining battery.											

B c/s a driver noted vehicle rattles when driven, check and advise											
EE312 c/s a driver noted vehicle rattles when driven, check and advise											
			cneck and CANI					1.00 (1.0	0.0	
1			JANI 190 JACK			Λ	297.97	160.0 297.9			
PARTS:	207	1-3(07	TADOD.	160 00	I, PANI	÷ 0.00			457		
						when turning			437	• 9 1	
									1		
	to be rolling back and forth in trunk making noise removed orange and test drove heard a rattle from rear and inspected, found spare tire										
						e to be loose					
						ck. (parts bi					
repair or	der)	7-7				The North					
		***	*****	*****	*****	*****	*****	***			
C Service	- 10	0,00	00 Miles o	r 120 M	onths						
В004С	21000	00 5	Service -	100,000	Miles	or 120 Months					
976 CANI 498.						75 498	.75				
00TS1M Rotate Tires											
976 CANI 0.00 0.00									.00		
00TS1R Replace Engine Oil and Oil Filter											
976 CANI 0.00									.00		
5 SYNTH 0/20 OIL							5.40			.00	
1 04152-YZZA6 REPLACEABLE EI					ELEMENT	l	8.00			.00	
										.50	
00TS8M Reset Oil Replacement Reminder										0.0	
976 CANI 0.00 0.00										.00	
OTS14R Replace Engine and Inverter Coolant Scan here to schedule or change your By signing below, you acknowledge that you were notified of and authorized DESCRIPTION TOTALS									11.0		
next appointment the Dealership to perform the services/repairs itemized in this Invoice and						nd LABOR AND	DESCRIPTION LABOR AMOUNT		ilo		
			that you received requested by you.	(or had the op	ortunity to ins	unity to inspect) any replaced parts as		PARTS AMOUNT			
			I acknowledge receipt of this invoice and k			evs to the vehicle described on this invoice		UBE			
。 			- 3 30.P		.,		-: .5, J, L				

Scan me

Date

Your next appointment is scheduled

SUBLET AMOUNT HAZARDOUS WASTE FEE ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. **TOTAL CHARGES** LESS INSURANCE I acknowledge notice and oral approval of an increase in the original estimated price. SALES TAX PLEASE PAY Please see back for glossary of abbreviations. THIS AMOUNT

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON THE BACK

Time Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2C - IMAGING

CUSTOMER COPY

BAR REG# ARD078672

EPA # CAD981569866

695061

TOYOTA

INVOICE

of Santa Barbara

5611 Hollister Ave. Goleta, California 93117

Phone (805) 967-5611 · Service (805) 683-2593 · Fax (805) 967-3732

www.toyotaofsantabarbara.com

KINTO SHARE

CA 93117

PAGE 2

Service and Parts Department Hours

Monday through Friday: 7:00 A.M. to 6:00 P.M.

Saturday: 7:30 A.M. to 5:00 P.M. HOME: 805-967-5611 CONT: 805-967-5611 SERVICE ADVISOR: 7503 <u>RACHEL MASEDA</u> BUS: CELL: COLOR YEAR MAKE/MODEL LICENSE MILEAGE IN / OUT TAG VIN 8DVK362 White 15 TOYOTA PRIUS JTDKN3DU7F0439214 107659/107661 TK33G DEL. DATE PROD. DATE WARR. EXP. PROMISED PO NO. RATE **PAYMENT** INV. DATE 01JAN15 DD 17:00 04JUN21 AR 07JUN21 R.O. OPENED READY **OPTIONS:** DLR:4150 10:12 04JUN21 09:38 07JUN21 OPCODE TECH TYPE HOURS LIST TOTAI NET 976 CANI 0.00 0.00 29.95 2 00272-SLLC2 SUPER LONG LIFE COOL 29.95 59.90 TS10IN Inspect Brake Linings/Drums and Brake Pads/Discs 976 CANI 0.00 0.00 TS44IN Check Installation of Driver's Floor Mat 976 CANI 0.00 0.00 TS45IN Inspect and Adjust All Fluid Levels 976 CANI 0.00 0.00 TS61IN Inspect Wiper Blades 976 CANI 0.00 0.00 PARTS: 96.40 LABOR: 595.15 498.75 OTHER: 0.00 TOTAL LINE C: 96573 Performed 100,000 mile service and inspection ****************** D COMPLIMENTARY MULTI-POINT INSPECTION - SOME ITEMS MAY NOT BE INSPECTED DEPENDING ON WORK PERFORMED AND CONFIGURATION CLMPI COMPLIMENTARY MULTI-POINT INSPECTION -SOME ITEMS MAY NOT BE INSPECTED DEPENDING ON WORK PERFORMED AND CONFIGURATION 0.00 976 CANI 0.00 TOTAL LINE D: PARTS: 0.00 LABOR: OTHER: 0.00 0.00 0.00 96573 Performed multi-point inspection per request. E CHECK TIRE PRESSURES AND INFLATE CHECK TIRE PRESSURES AND INFLATE EACH TIRE TO THE VEHICLES MANUFACTURER'S RECOMMENDED TIRE PRESSURE RATING. - AFTER WHEEL REMOVAL/INSTALLATION WHEELS MUST BE RETORQUED AFTER 100 MILES TIREPSI CHECK TIRE PRESSURES AND INFLATE CHECK TIRE PRESSURES AND INFLATE EACH TIRE TO THE VEHICLES MANUFACTURER'S RECOMMENDED TIRE PRESSURE RATING. - AFTER WHEEL REMOVAL/INSTALLATION WHEELS MUST BE RETORQUED AFTER 100 MILES

Scan here to schedule or change your next appointment



Your next appointment is scheduled

Date

00 976 CANI Λ 0.00 By signing below, you acknowledge that you were notified of and authorized DESCRIPTION TOTALS the Dealership to perform the services/repairs itemized in this Invoice and LABOR AMOUNT that you received (or had the opportunity to inspect) any replaced parts as requested by you. PARTS AMOUNT I acknowledge receipt of this invoice and keys to the vehicle described on this invoice. GAS, OIL, LUBE SUBLET AMOUNT Χ HAZARDOUS WASTE FEE ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. **TOTAL CHARGES** LESS INSURANCE I acknowledge notice and oral approval of an increase in the original estimated price. SALES TAX PLEASE PAY THIS AMOUNT Please see back for glossary of abbreviations.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON THE BACK

695061

of Santa Barbara

INVOICE

5611 Hollister Ave. - Goleta, California 93117

Phone (805) 967-5611 · Service (805) 683-2593 · Fax (805) 967-3732

www.toyotaofsantabarbara.com

KINTO SHARE

CA 93117

PAGE 3

Service and Parts Department Hours

Monday through Friday: 7:00 A.M. to 6:00 P.M. Saturday: 7:30 A.M. to 5:00 P.M. HOME: 805-967-5611 CONT: 805-967-5611 SERVICE ADVISOR: 7503 <u>RACHEL MASEDA</u> BUS: CELL: COLOR YEAR MAKE/MODEL LICENSE MILEAGE IN / OUT TAG VIN 8DVK362 White 15 TOYOTA PRIUS JTDKN3DU7F0439214 107659/107661 TK33G DEL. DATE PROD. DATE WARR. EXP. **PROMISED** PO NO. RATE **PAYMENT** INV. DATE 01JAN15 DD 17:00 04JUN21 AR 07JUN21 R.O. OPENED READY **OPTIONS:** DLR:4150 10:12 04JUN21 09:38 07JUN21 TYPE LINE OPCODE TECH HOURS NET TOTAI PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE 0.00 96573 Set tire PSI to Front:35 Rear:33 Spare:60 F FLOOR MAT POLICY: ALL DRIVERS SIDE FLOOR MATS THAT ARE NOT SECURE, DOUBLE STACKED OR INTERFERE WITH VEHICLES PEDAL OPERATION SHOULD BE PROPERLY SECURED OR REMOVED AND PLACED IN THE VEHICLE TRUNK. PLEASE DOCUMENT APPROPIATE ACTION IN 'CORRECTION' CO1MAT FLOOR MAT POLICY: ALL DRIVERS SIDE FLOOR MATS THAT ARE NOT SECURE, DOUBLE STACKED OR INTERFERE WITH VEHICLES PEDAL OPERATION SHOULD BE PROPERLY SECURED OR REMOVED AND PLACED IN THE VEHICLE TRUNK. PLEASE DOCUMENT APPROPIATE ACTION IN 'CORRECTION' 0.00 976 CANI 0.00 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 0.00 TOTAL LINE F: 96573 Inspected floormat. Found to have correct floormat, properly installed. G** Bulb - Taglight (One) - Replace EL25 Bulb - Taglight (One) - Replace 976 CANI 25.00 25.00 1 00234-00192 BULB 4.49 4.49 4.49 PARTS: 4.49 LABOR: 25.00 OTHER: 0.00 TOTAL LINE G: 29.49 96573 Replaced tag light bulb H** Bulb (Frt running Light) - Replace EL23 Bulb (Frt running Light) - Replace 976 CANI 25.00 25.00 1 00234-00192 BULB 4.49 4.49 4.49 29.49 PARTS: 4.49 LABOR: 25.00 0.00 TOTAL LINE OTHER: H:By signing below, you acknowledge that you were notified of and authorized Scan here to schedule or change your DESCRIPTION **TOTALS** the Dealership to perform the services/repairs itemized in this Invoice and LABOR AMOUNT that you received (or had the opportunity to inspect) any replaced parts as PARTS AMOUNT I acknowledge receipt of this invoice and keys to the vehicle described on this invoice. GAS, OIL, LUBE SUBLET AMOUNT Χ HAZARDOUS WASTE FEE ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. **TOTAL CHARGES** LESS INSURANCE I acknowledge notice and oral approval of an increase in the original estimated price.

Scan me

Your next appointment is scheduled

Date

Please see back for glossary of abbreviations.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON THE BACK

Time Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2C - IMAGING

CUSTOMER COPY

BAR REG# ARD078672

THIS AMOUNT

SALES TAX PLEASE PAY

EPA # CAD981569866

695061

INVOICE

of Santa Barbara 5611 Hollister Ave. - Goleta, California 93117

Phone (805) 967-5611 · Service (805) 683-2593 · Fax (805) 967-3732

www.toyotaofsantabarbara.com

KINTO SHARE

CA 93117

PAGE 4

Service and Parts Department Hours

Monday through Friday: 7:00 A.M. to 6:00 P.M. Saturday: 7:30 A.M. to 5:00 P.M. HOME: 805-967-5611 CONT: 805-967-5611 CELL: SERVICE ADVISOR: 7503 RACHEL MASEDA BUS: COLOR YEAR MAKE/MODEL LICENSE MILEAGE IN / OUT TAG JTDKN3DU7F0439214 8DVK362 White 15 TOYOTA PRIUS 107659/107661 TK33G DEL. DATE PROD. DATE WARR. EXP. **PROMISED** PO NO. RATE PAYMENT INV. DATE 07JUN21 01JAN15 DD 17:00 04JUN21 AR R.O. OPENED READY OPTIONS: 10:12 04JUN21 09:38 07JUN21 OPCODE TECH LIST NET TOTAL HOURS 96573 replaced running bulb I** Bulb (Frt running Light) - Replace EL23 Bulb (Frt running Light) - Replace 976 CANI 25.00 25.00 1 00234-00192 BULB 4.49 4.49 4.49 OTHER: 4.49 LABOR: 25.00 0.00 29.49 PARTS: TOTAL LINE I: 96573 replaced running bulb ****** J** Bulb - Taglight (One) - Replace EL25 Bulb - Taglight (One) - Replace 976 CANI 25.00 25.00 1 00234-00192 BULB 4.49 4.49 4.49 PARTS: 4.49 LABOR: 25.00 0.00 TOTAL LINE 29.49 OTHER: 96573 Replaced tag light bulb K** Cabin Air Filter (Standard Pollen/Electrostatic) - Replace MA83 Cabin Air Filter (Standard Pollen/Electrostatic) - Replace 976 CANI 40.00 40.00 29.95 29.95 1 87139-YZZ20 ELEMENT, AIR REFINER 29.95 PARTS: 29.95 LABOR: 40.00 OTHER: 0.00 TOTAL LINE K: 69.95 96573 Replaced cabin air filter L** Remove and clean hybrid battery inlet cooling screen EL99 Remove and clean hybrid battery inlet cooling screen 976 CANI 70.00 70.00 0.00 PARTS: 0.00 LABOR: 70.00 OTHER: TOTAL LINE L: 70.00 96573 Removed and cleaning hybrid inlet screen. ******** M** Mount and balance 4 tires TIRE4 Mount and balance 4 tires 100.00 976 CANI 100.00 Scan here to schedule or change your TOTALS By signing below, you acknowledge that you were notified of and authorized DESCRIPTION the Dealership to perform the services/repairs itemized in this Invoice and LABOR AMOUNT that you received (or had the opportunity to inspect) any replaced parts as requested by you. PARTS AMOUNT GAS, OIL, LUBE I acknowledge receipt of this invoice and keys to the vehicle described on this invoice. SUBLET AMOUNT Χ HAZARDOUS WASTE FEE ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. **TOTAL CHARGES** LESS INSURANCE I acknowledge notice and oral approval of an increase in the original estimated price. SALES TAX Scan me

Your next appointment is scheduled Date

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON THE BACK

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2C - IMAGING

Please see back for glossary of abbreviations.

CUSTOMER COPY

BAR REG# ARD078672

PLEASE PAY

THIS AMOUNT

EPA # CAD981569866

CUSTOMER #: 73810

KINTO SHARE

CA 93117

695061

INVOICE

of Santa Barbara

5611 Hollister Ave. - Goleta, California 93117 Phone (805) 967-5611 · Service (805) 683-2593 · Fax (805) 967-3732

www.toyotaofsantabarbara.com

PAGE 5

Service and Parts Department Hours Monday through Friday: 7:00 A.M. to 6:00 P.M.

Saturday: 7:30 A.M. to 5:00 P.M. HOME: 805-967-5611 CONT: 805-967-5611 7503 RACHEL MASEDA BUS: CELL: SERVICE ADVISOR: **COLOR** YEAR MAKE/MODEL LICENSE MILEAGE IN / OUT TAG JTDKN3DU7F0439214 8DVK362 White 15 TOYOTA PRIUS 107659/107661 TK33G DEL. DATE PROD. DATE WARR. EXP. **PROMISED** PO NO. RATE **PAYMENT** INV. DATE 01JAN15 DD 17:00 04JUN21 AR 07JUN21 R.O. OPENED READY OPTIONS: DLR:4150 10:12 04JUN21 09:38 07JUN21 LINE OPCODE TECH TYPE HOURS LIST NET TOTAL 4 DT001-33459-BS P195/65R15 139.00 117.00 468.00 HT TIRE DISPOSAL 2.75 2.75 11.00 1.75 7.00 4 TT TIRE TAX 1.75

6.00 4 WW WHEEL WEIGHT 1.50 1.50 PARTS: 492.00 LABOR: 100.00 OTHER: 0.00 TOTAL LINE M: 592.00

96573 Mounted and balanced 4 tire

N** Alignment (Four - Wheel)

FS02 Alignment (Four - Wheel)

976 CANI 119.95 119.95 0.00 PARTS: 0.00 LABOR: 119.95 OTHER: TOTAL LINE N: 119.95

96573 Performed alignment and test drove

EST: 1,252.89 04JUN21 12:22 SA: 7503 **CONTACT:**

Some Contract You for Choosing Toyota of Santa BARBARA. All parts installed are new unless otherwise specified.

JOIN OUR VIP CLUB TEXT "TOYOTAVIP18" TO 37483 FOR EXCLUSIVE OFFERS AND SPECIALS!

Scan here to schedule or change your next appointment



Χ

Your next appointment is scheduled

Date

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

I acknowledge receipt of this invoice and keys to the vehicle described on this invoice.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

I acknowledge notice and oral approval of an increase in the original estimated price.

Please see back for glossary of abbreviations.

DESCRIPTION	TOTALS
LABOR AMOUNT	1168.70
PARTS AMOUNT	934.28
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
HAZARDOUS WASTE FEE	0.00
TOTAL CHARGES	2102.98
LESS INSURANCE	0.00
SALES TAX	71.01
PLEASE PAY THIS AMOUNT	2173.99
	1 4113.22

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON THE BACK

CUSTOMER COPY

BAR REG# ARD078672