CTMO

Ninnion: The Observer's Operation Manual

Contents

1	Start up Observatory	Ę
2	Shutdown Observatory	,

4 Contents

CHAPTER 1

Start up Observatory

- 1. Turn on all breakers
- 2. Open shutter window
 - (a) Remove charger from power source
 - (b) Remove charger from battery. First Red (+) then Black (-)
 - (c) Connect Black motor cable to Black (-) on battery
 - (d) Connect Red motor cable to Red (+) on battery
 - (e) Press and hold OPEN on the shutter controller
- 3. Open shutter door. Undo rope and let down the shutter door
- 4. Turn on UPS
- 5. Turn on Computer
 - (a) Make sure to wait at the monitor to change boot order on grub.
- 6. Remove mirror shields
 - (a) Slide the light shroud up toward the front of the scope
 - (b) Remove cloth cover on secondary mirror
 - (c) Remove plastic shower cap
 - (d) Remove round plastic lid from primary
 - (e) Cover telescope with light shroud
- 7. Turn on Mount
 - (a) make brakes are off

- 8. Open PWI3
 - (a) verify the focuser established connection
- 9. Open PWI4
- 10. On PWI4:
 - (a) click: Enable DEC
 - (b) click: Enable RA
 - (c) click: Commands ¿ Home mount
- 11. You are ready to observe!

Chapter 2

Shutdown Observatory

1. TBD