

Remaining Problems

meltdown_rate not physically grounded

lifetime proxy saturation

missing DPA/material model

Next Engineering Steps

1. Replace meltdown with cumulative damage model
2. Integrate OpenMC tallies into damage pipeline
3. Validate MHD constraints for lithium flow
4. Establish closed-loop verification