

| | J17 |
|-------|-------------------------|
| PC6 | Conn 101 801_Pir |
| PDO | Conn 1019 01_Pir |
| PD1 | Conn <u>102</u> 001_Pir |
| PD2 | Conn <u>1</u> 01x01_Pir |
| PUZ / | _ |

| | J13 |
|-----|----------------------------------|
| PB4 | Conn <u>1</u> 01 <u></u> #01_Pin |
| PB3 | Conn 101 501_Pin |
| PB2 | Conn 101 601_Pin |
| PB1 | Conn <u>1</u> 01x01_Pin |
| PDI | |

